TECHNICAL TOPICS POWERTRAIN



15MY – Onward RR Evoque equipped



Noise or Judder while turning with Active Driveline Customer Voice: ▶ 1: General Information ▼ 2: Chassis There is a noise from the rear of the vehicle while turning. There is a judder feeling when turning. ▼ 205: Driveline ▶ 205-00: Driveline System - General Technical Description: ▶ 205-01: Driveshaft 205-02A: Rear Drive Axle/Differential The noise/judder is identified as coming from the rear drive unit. Vehicles Without: Active Driveline ▼ 205-02B: Rear Drive Axle/Differential Vehicles With: Active Driveline Status: It is important that all pinpoint testing outlined in the TOPIx Workshop Manual Rear Drive Axle and Differential Diagnosis and Testing (WSM) section 205-02B: Rear Drive Axle/Differential - Vehicles with Active Rear Drive Axle and Differ Driveline > Diagnosis and Testing is completed. Pay close attention to the work instructions as the amount of fluid drained requires measurement. Be sure to complete a thorough road test after any flushing procedures. Should a complaint persist, a FRED is required for replacement. Be sure to











with the tire size clearly visible.

PRINTED COPIES ARE UNCONTROLLED

include detailed results of all the testing performed in your submission along with a video of the noise and picture of each of the wheels/tires fitted to the vehicle