



GROUP  
ELE

MODEL  
2021MY  
Seltos (SP2)

NUMBER  
224

DATE  
December 2020

## TECHNICAL SERVICE BULLETIN

SUBJECT:

### SERVICE ACTION: FRONT CAMERA OPERATION LOGIC IMPROVEMENT (SA453)

This bulletin provides the procedure to improve the logic of the front view camera software on some 2021MY Seltos (SP2) vehicles, produced from November 20, 2019 through October 22, 2020, to improve the logic of the Lane Departure Warning (LDW) / Lane Keep Assist (LKA) operation. To improve driving experience and customer satisfaction, apply the improved logic to the ECU using the KDS ECU Upgrade function as described in this bulletin. For confirmation that the latest reflash has been applied to a vehicle you are working on, verify the ROM ID using the table on page 2 of this bulletin. Before conducting the procedure, verify the vehicle is included in the list of affected VINs in dealer stock.

#### **IMPORTANT**

If the vehicle in the applicable VIN list also applies to TSB (SA452) VIN list, then perform SA452 first before completing this Service Action for vehicle in dealer stock only.



Kia Diagnostic System

#### **\* NOTICE**

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA453.

Printed TSB copy is for reference only; information may be updated at any time.  
Always refer to KGIS for the latest information.

Circulate To:  General Manager  Service Manager  Parts Manager  
 Service Advisors  Technicians  Body Shop Manager  Fleet Repair

SUBJECT:

## SERVICE ACTION: FRONT CAMERA OPERATION LOGIC IMPROVEMENT (SA453)

### ECU Upgrade Procedure:

To correct this condition, the ECU should be reprogrammed using the KDS download, as described in this bulletin.

#### Upgrade Event Name

510. SP2 FRONT CAMERA (LDW/LKA) OPERATION LOGIC IMPROVEMENT

### ★ NOTICE

- A fully charged battery is necessary before ECU upgrade can take place. It is recommended that a battery charger is used in ECU mode during reflashing or the use of a fully charged jump starter box connected to the battery.
- DO NOT connect any other battery charger to the vehicle during ECU upgrade.
- Ensure the KDS or GDS is sufficiently charged prior to reflash.
- All ECU upgrades must be done with the ignition key in the 'ON' position.
- Be careful not to disconnect the VCI-II connected to the vehicle during the ECU upgrade procedure.
- DO NOT start the engine during ECU upgrade.
- Do NOT turn the ignition key 'OFF' or interrupt the power supply during ECU upgrade.
- When the ECU upgrade is completed, turn the ignition 'OFF' and wait 10 seconds before starting the engine.
- ONLY use approved ECU upgrade software designated for the correct model and model year.

### ★ NOTICE


It is recommended to ALWAYS check the Electronic Parts Catalog (EPC) to locate the ECU Part Number respective to Auto/Manual Mode ROM IDs. DO NOT reference the parts label affixed to the ECU.

### ★ NOTICE

Before attempting an ECU upgrade on any Kia model, make sure to first determine whether the applicable model is equipped with an immobilizer security system. Failure to follow proper procedures may cause the PCM to become inoperative after the upgrade and any claims associated with this repair may be subject to chargeback.

### ROM ID INFORMATION TABLE:

#### Upgrade Event #510

Model	SYS	IMMO 	ECU P/No.	ROM ID	
				Previous	New
SP2	FR_CMV	Yes - O	99210-Q5000	99210-Q5000_1.03 99210-Q5000_1.04	99210-Q50001.05

*To verify the vehicle is affected, be sure to check the Calibration Identification of the vehicle's ECM ROM ID and reference the Information Table as necessary.*

SUBJECT:

SERVICE ACTION: FRONT CAMERA OPERATION  
LOGIC IMPROVEMENT (SA453)

**\* NOTICE**

Prior to performing the ECU upgrade, be sure to check that the KDS is fully charged.

1. Connect the VCI-II to the OBD-II connector, located under the driver's side of the instrument panel.

**\* NOTICE**


The ECU upgrade function on KDS operates wirelessly. It is not necessary to perform the upgrade via USB cable.




2. With the ignition ON, turn ON the KDS tablet. Select **KDS** from the home screen.



3. Confirm communication with VCI (A) and then configure the vehicle (B) using the **AUTO VIN** (C) feature.




4. Select **ECU Upgrade**.



**SUBJECT: SERVICE ACTION: FRONT CAMERA OPERATION LOGIC IMPROVEMENT (SA453)**


- The KDS will check the server for recently uploaded Events and then automatically download **Upgrade Event #510**.

**\* NOTICE**  
 The vehicle must be identified in Vehicle Selection to download an Event for that vehicle.



- Select **Auto Mode**.

**CAUTION**  
 Do NOT attempt to perform a Manual Mode upgrade UNLESS Auto Mode fails. Always follow the instructions given on the KDS in either Auto or Manual mode.




KDS screenshot shown below is for demonstration purposes only. Events shown in screenshot are not applicable to this bulletin.

- Select the **FR\_CM** system under the System selection menu.



Touch **ID Check** (D) and confirm that the latest update is available.

Select **Upgrade Event #510** and select **Upgrade** to continue.



- The ECU upgrade will begin and the progress of the upgrade will appear on the bar graph. Upgrade part (1/2) (E) will download the upgrade event to the VCI-II. Upgrade part (2/2) (F) will upgrade the ECU.

**CAUTION**  
 Do not touch the system buttons (like 'Back', 'Home', 'etc.') while performing ECU Upgrade.




SUBJECT:

## SERVICE ACTION: FRONT CAMERA OPERATION LOGIC IMPROVEMENT (SA453)


9. If a “Communication Fail” screen appears, verify that the VCI-II and KDS are communicating properly. Touch **OK** and restart the procedure from step 4.

### \* NOTICE


**If an error notice continues to appear or if the upgrade cannot be performed, DO NOT disconnect the KDS/VCI-II. Contact GIT America Help Desk at (888) 542-4371 or Techline.**




10. When instructed on the KDS, turn the ignition **OFF** for ten (10) seconds then back on. Touch **OK** to continue.



11. Once the upgrade is complete, touch **OK** to finalize the procedure.



12. When prompted, select **YES** to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.



13. Start the engine to confirm proper operation of the vehicle.

**Manual Upgrade Procedure:****\* NOTICE**

The manual upgrade should **ONLY** be performed if the automatic upgrade fails.

If the automatic upgrade fails, turn the ignition **OFF** for about 10 seconds then place it back in the **ON** position to reset the control unit **BEFORE** performing manual upgrade.

See table below for Manual Mode passwords.

**Manual Mode ECU Upgrade Passwords**

Menu	Password
SP2 FR_CMV : 99210-Q5000 //5000	5000

1. Within the ECU Upgrade screen displayed, select **Manual Mode**.
2. Select the **FR\_CMV** system under the System selection menu. Select **Upgrade Event #510** and select **Upgrade** to continue.
3. Select the appropriate control unit part number with reference to the ROM ID Information Table on page 2, and select **OK**.
4. Enter the appropriate password from the Manual Mode password table above and select **OK**.
5. The upgrade will begin and the progress of the upgrade will appear on the bar graph.
6. When instructed on the KDS, turn the ignition **OFF** for ten (10) seconds then back on. Touch **OK** to continue.
7. Once the upgrade is complete, touch **OK** to finalize the procedure.
8. When prompted, select **YES** to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.
9. Start the engine to confirm proper operation of the vehicle.

SUBJECT:

SERVICE ACTION: FRONT CAMERA OPERATION  
LOGIC IMPROVEMENT (SA453)

AFFECTED VEHICLE RANGE:

Model	Production Date Range
Seltos (SP2)	November 20,2019 to October 22, 2020

WARRANTY INFORMATION:

**N Code: N99 C Code: C99**

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
V	99211 F1000	0	(SA453) Front Camera Operation Logic Improvement	200117R0	0.3 M/H	N/A	0

<b>* NOTICE</b>
-----------------

<p><b>VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference <u>SA453</u> when accessing the WebDCS system.</b></p>
--

