Special Parts Collection – USA Code: 69BD



Subject

Special Parts Collection - Head Curtain Airbag

Release Date

December 19, 2020

REVISION SUMMARY

Updated GFF labor operation

Affected Vehicles

Country	Beginning Model Year	Ending Model Year	Vehicle	Vehicle Count
USA	2016	2016	Q5	273

Check Campaigns/Actions screen in Elsa on the day of repair to verify that a VIN qualifies for repair under this action. Elsa is the only valid campaign inquiry & verification source.

- ✓ Campaign status must show "open."
- ✓ If Elsa shows other open action(s), inform your customer so that the work can also be completed at the same time the vehicle is in the workshop for this campaign.

69BD Special Parts Collection Program

Audi is conducting a special parts collection program involving the head curtain airbags from selected 2016 model year Audi Q5 vehicles.

Under this program:

- All eligible vehicles showed the Special Parts Collection code 69BD in ELSA on December 04, 2020.
- Owner notification will take place in December 2020 via first-class mail.
- Only vehicles registered & located within the 48-contiguous United States may participate.
- The head curtain airbags will be replaced free of charge by an authorized Audi dealer.
- Time is of the essence. Once the required number of head curtain air bags have been collected, the program will end and no further replacements will be made.
- Return of removed head curtain air bags is <u>mandatory</u>. Claims are subject to cancellation if removed air bags are not returned or if they are improperly returned.

Additional Information

Please alert everyone in your dealership about this action, including Sales, Service, Parts and Accounting personnel. Contact Warranty if you have any questions.

December 2020 69BD Page 1 of 24

Parts Information

Parts Control Type: Free Order	Parts will be managed by Free Order
riee Oldei	

Initial Allocation:	Due to the small number of affected vehicles there will be no parts allocation. Please
NO	reference the Repair Projection Tool (below) to view your potential VIN population.

Repair Projection Tool: (right click to open)	9		
---	---	--	--

Criteria	Quantity	Part Number	P.O.C. Part Description	Ordering Method
04	1	8R0-880-742-L	Airbag (Right)	Free Order
01 1	1	N -912-259-01	Bolt	Free Order
00	1	8R0-880-741-L	Airbag (Left)	Free Order
02	1	N -912-259-01	Bolt	Free Order

U NOTE

The specified part numbers reflect the status at the start of this action. Interim updates made in ETKA can cause a listed part number to become unavailable. In this case, the new part number specified in ETKA should be used.

① NOTE

A supply of parts dedicated to this special program was sent to all PDCs prior to owner notification.

Removed head curtain air bags must be returned to the designated inspection facility. These MUST be returned in their as removed from vehicle condition.

Requests for removed air bags will be available in the Warranty Parts Portal (WPP) once the claim has reached approved status in SAGA. Use the Warranty Parts Portal to obtain the FedEx shipping label and required hazardous material documentation.

The information in this document is intended for use only by skilled technicians who have the proper tools, equipment and training to correctly and safely maintain your vehicle. These procedures are not intended to be attempted by "do-it-yourselfers," and you should not assume this document applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Audi dealer. ©2020 Audi Group of America, Inc. and Audi Canada. All Rights Reserved.

December 2020 69BD Page 2 of 24

Claim Entry Instructions

The labor times listed here may differ from the labor operations and labor times listed in ELSA.

After campaign has been completed, enter claim as soon as possible to help prevent work from being duplicated elsewhere. Attach the Elsa screen print showing action <u>open on the day of repair</u> to the repair order. If customer refused campaign work:

✓ U.S. dealers: Submit the request through Audi Warranty Online under the Campaigns/Update option.

<u>G.o. adaloi.</u> Opinia in oquast in ough, ital. Warani, Grimio and in o <u>Gampaigno pauto</u>		
Service Number	69BD	
Damage Code	0099	
Parts Vendor Code	002	
Claim Type	Sold vehicle: 7 10	
	Unsold vehicle: 7 90	
Causal Indicator	Vehicles assigned only one criteria:	
	Mark airbag* as causal part	
	Vehicles assigned criteria 01 and 02:	
	Due to the special circumstance of this project two claims are required. A claim must be entered for each criteria for vehicles assigned criteria 01 <u>and</u> 02	
	Criteria I.D. 01 – mark right head curtain airbag* as causal part	
	Criteria I.D. 02 – mark left head curtain airbag* as causal part	
	NOTE: Due to the overlap in work steps, the labor for the second head curtain airbag will be claimed at 10 TU.	
Vehicle Wash/Loaner	Do not claim wash/loaner under this action	

Vehicles Assigned Criteria 01 ONLY				
Criteria I.D.	01			
	LABOR			
	Labor Op	Time Units	Description	
	6966 55 99	440	Replace <u>right</u> head curtain airbag	
	0150 00 00	Time stated on diagnostic protocol	Clear repair related faults	
	PARTS			
	Quantity	Part Number	Description	
	1.00	8R0880742L	Airbag (right)*	
	1.00	N 91225901	Bolt	

The repair information in this document is intended for use only by skilled technicians who have the proper tools, equipment and training to correctly and safely maintain your vehicle. These procedures are not intended to be attempted by "do-it-yourselfers," and you should not assume this document applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Audi dealer. ©2020 Audi of America, Inc. and Audi Canada. All Rights Reserved.

December 2020 69BD Page 3 of 24

Vehicles Assigned Criteria 02 ONLY				
Criteria I.D.	02			
	LABOR			
	Labor Op	Time Units	Description	
	6966 56 99	440	Replace <u>left</u> head curtain airbag	
	0150 00 00	Time stated on diagnostic protocol	Clear repair related faults	
			PARTS	
	Quantity	Part Number	Description	
	1.00	8R0880741L	Airbag (left)*	
	1.00	N 91225901	Bolt	

Vehicles Assigned Criteria 01 and 02 (two claims required)				
Criteria I.D.	01			
1 st Claim	LABOR			
	Labor Op	Time Units	Description	
	6966 57 99	440	Replace <u>right</u> head curtain airbag	
	0150 00 00	Time stated on diagnostic protocol	Clear repair related faults	
			PARTS	
	Quantity	Part Number	Description	
	1.00	8R0880742L	Airbag (right)*	
	1.00	N 91225901	Bolt	
Criteria I.D.	02			
2 nd Claim	LABOR			
	Labor Op	Time Units	Description	
	6966 58 99	10	Replace <u>left</u> head curtain airbag	
	PARTS			
	Quantity	Part Number	Description	
	1.00	8R0880741L	Airbag (left)*	
	1.00	N 91225901	Bolt	

December 2020 69BD Page 4 of 24

Customer Letter Example (USA)

<MONTH YEAR>

<CUSTOMER NAME>

<CUSTOMER ADDRESS>

<CUSTOMER CITY STATE ZIPCODE>

This notice applies to your vehicle: <MODEL YEAR> <BRAND> <CARLINE>, <VIN>

Subject: Special Parts Collection 69BD - Head Curtain Air Bags

Dear Audi Owner.

Audi is conducting a special head curtain air bag collection program. Your vehicle has been selected to participate in this program.

This is not a recall. As explained below, we are doing this as part of a safety & quality assurance initiative.

SPECIAL PARTS COLLECTION PROGRAM

- Audi has pre-selected your vehicle to analyze the head curtain air bags. Under this program, we would like to replace one
 or both of these head curtain air bags in your vehicle with new parts FREE of charge.
- Only vehicles registered/located within the 48-contiguous United States are eligible for this program.

HOW TO PARTICIPATE - WHAT YOU CAN DO

- If you would like to participate in this program, please contact an authorized Audi dealer at your earliest convenience. For
 your convenience, you can also visit www.audiusa.com and click on the "Find a Dealer" link to locate a dealer near you
 and schedule this service.
- Head curtain air bag replacement may take up to a day to complete. Please keep in mind that your dealer may need
 additional time for the preparation of the replacement, as well as to accommodate their daily workshop schedule.

If you should have any questions about this communication, please contact Audi Customer Experience at 1-800-253-2834 or via our "Contact Us" page at www.audiusa.com.


Sincerely,

Audi Customer Protection

Time is of the essence. Audi has a specific number of head curtain air bags to collect under this program. Once this goal is reached, the program will end and no more replacements will be made.

December 2020 69BD Page 5 of 24

Repair Overview




- Replace left and/or right head curtain airbag.
 - o Criteria 01 = right
 - Criteria 02 = left

• NOTE

- These repair instructions may differ from the labor operations and labor times listed in ELSA.
- Damages resulting from improper repair or failure to follow these work instructions are the dealer's responsibility and are not eligible for reimbursement under this action.
- This procedure must be read in its entirety prior to performing the repair.
- Due to variations in vehicle equipment and options, the steps/illustrations in this work procedure may not identically match all affected vehicles.
- Diagnosis and repair of pre-existing conditions in the vehicle are not covered under this action.
- When working during extreme temperatures, it is recommended that the vehicle be allowed to acclimate inside the shop to avoid temperature-related component damage/breakage.


December 2020 69BD Page 6 of 24


Required Tools



December 2020 69BD Page 7 of 24

Section A - Check for Previous Repair





• Enter the VIN in Elsa and proceed to the "Campaign/Action" screen.

i TIP

On the date of repair, print this screen and keep a copy with the repair order.

- Confirm the Campaign/Action is open <arrow 1>. If the status is closed, no further work is required.
- Note the Applicable Criteria ID <arrow 2> for use in determining the correct work to be done and corresponding parts associated.



If multiple software update Campaign/Actions are open, they must be performed in order of the Start date <arrow 3>. The oldest should be performed first.

- All Safety Recalls must be completed prior to completing this campaign.
- Proceed to Section B.

The repair information in this document is intended for use only by skilled technicians who have the proper tools, equipment and training to correctly and safely maintain your vehicle. These procedures are not intended to be attempted by "do-it-yourselfers," and you should not assume this document applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Audi dealer. ©2020 Audi of America, Inc. and Audi Canada. All Rights Reserved.

December 2020 69BD Page 8 of 24

Section B - Repair Procedure




WARNING

Risk of injury. Refer to "Warning and Safety Precautions", found in Appendix A at the end of this document.



U NOTE


The procedures shown for head curtain airbag replacement illustrate the driver side. Repeat the steps for removal and installation of trim panels for the passenger side.



- Fold the backrests forward.
- Recline front seats to a 45° angle.

Remove instrument panel side covers:


Pry the instrument panel side cover <1> off using the -3409- <arrow> and remove it.



Remove gap covers:


- Remove the gap cover <1> from the A-pillar trim and the sill trim <arrow>.
- Remove the gap cover upward from the clips on the A-pillar.

69BD Page 9 of 24 December 2020



Remove A-pillar trim:

- Pry out the expanding cap <1> with the "airbag" symbol about 5 mm with a screwdriver <arrow A>.
- The trim is removed from the A-pillar in direction of <arrow B> in different ways depending on which clips are installed in the vehicle.
- If clips with a hook are installed, the trim needs to be pulled just a few millimeters until the hooks engage.
- The clips will then be removed from the A-pillar when the trim is pulled upward in direction of <arrow C>.
- Carefully unclip the A-pillar trim <2> beginning at the top using a -80-200- <arrow B>.
- Push the A-pillar trim upward and remove it <arrow C>.
- Replace damaged clips.




Remove upper B-pillar trim:

- Press belt height adjuster button and bring height adjuster slide into lowest position.
- Unclip the upper B-pillar trim <2> in direction of <arrows A> by inserting the -3409- into the lower edge of the trim.
- Remove the upper B-pillar trim from the bracket on the body in direction of <arrow B> by moving the trim toward the inside and pulling it downward at the same time.
- Lower the upper B-pillar trim down in the passenger compartment and protect it from damage.


The repair information in this document is intended for use only by skilled technicians who have the proper tools, equipment and training to correctly and safely maintain your vehicle. These procedures are not intended to be attempted by "do-it-yourselfers," and you should not assume this document applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Audi dealer. ©2020 Audi of America, Inc. and Audi Canada. All Rights Reserved.

December 2020 69BD Page 10 of 24



Remove lock carrier trim:


- Remove the rear luggage compartment floor.
- Unclip the rear lid end trim panel <1> using the -80-200- diagonally upward in direction of <arrows>.
- Carefully remove the rear lid end trim panel upward and disconnect the connector for the rear lid closed sensor Rear Lid -Closed-Sensor 1 -G525-/Rear Lid -Closed- Sensor 2 -G526-.



Remove gap cover:


- Remove bolts <4>.
- Remove tie downs <3>.
- Remove gap cover <2>.

December 2020 69BD Page 11 of 24



Remove luggage compartment side panel:


- Remove backrest release <6>.
 - Hold the release lever pulled and remove the screw behind the lever.
 - Unclip the cable from the lever.
- Pry out luggage compartment lamp <3> with the -3409- and disconnect it.
- Pry off coat hook <5> with the -3409-.
- Remove bolt <4>.
- Pry the luggage compartment trim away from the body using the -80-200-.



Remove C-pillar trim:


- Remove the expanding clip <2>.
- Unclip the C-pillar trim panel <1> using the -80-200- in direction of <arrow A>.
- Pull the C-pillar trim downward in direction of <arrow B> and remove.

December 2020 69BD Page 12 of 24



Remove roof end panel trim:


 Carefully unclip the rear roof panel trim <1> in the center off the roof frame using the -80-200in direction of <arrow>.



Remove D-pillar trim:


- Remove the expanding clips <1> and <3>.
- Remove the D-pillar trim <2> from the body <arrows> using the -80-200-.
- Versions with a speaker: Disconnect the connector.

December 2020 69BD Page 13 of 24



Remove screen separator mounts:


 Press the cover <1> toward the inside and remove the screws on the screen separator mount <2>.



Remove sunvisors:


- Disengage the sun visor <1> in the center of the vehicle from the sun visor center bracket <2>.
- Unclip the expanding cap <3> using a screwdriver.
- Tilt the sun visor bracket down <arrow> and remove it.
- Versions with lighting: Disconnect the electrical connector and remove the sun visor.

December 2020 69BD Page 14 of 24



Remove front reading lamp:

- Open the eyeglass compartment <2>.
- Remove the bolt <1>.
- Pivot the front interior lamp/reading lamp <3> downward and remove it from the roof trim panel.
- Disconnect the connectors.



Remove sun visor center supports:


 Unclip the sun visor center support cover <1> by sliding the -VAS6416- only about 1 mm under the cap in the direction of <arrow A>.




If the -VAS6416- is inserted farther, it will be located under the sun visor. It is not possible then to pry out the expanding cap.

- Remove sun visor center support <2> in the direction of <arrow B>.
- Remove both sun visor center support covers.

December 2020 69BD Page 15 of 24





Remove all four grab handles:

• NOTE


- There is a risk of destroying the roof grab handle if the silicone brake and spring fall out. Replacement of the grab handle due to improper removal will not be covered under this action.
- Only unclip the expanding caps <2 and 3> up to their lock position. Do not remove them completely.
 - Place the angled screwdriver <4> in the gap behind the clips <2>.
 - Pivot the angled screwdriver in the direction of <arrow>, until the clips slide audibly into the rest position.
 - Repeat the procedure on clip <3>.
 - Remove the roof grab handle <1> from the body opening.
 - Leave the expanding caps in the rest position in the roof grab handle.

For vehilces with a sliding sunroof:


- Open the sun shade.
- To avoid dirtying the headliner, clean the -T40233-.
- Push the -T40233- between the frame <1> for the sliding sunroof and the headliner.
- Loosen the headliner using the -T40233from the sliding sunroof frame all the way around <arrows>, as shown.

The repair information in this document is intended for use only by skilled technicians who have the proper tools, equipment and training to correctly and safely maintain your vehicle. These procedures are not intended to be attempted by "do-it-yourselfers," and you should not assume this document applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Audi dealer. ©2020 Audi of America, Inc. and Audi Canada. All Rights Reserved.

December 2020 69BD Page 16 of 24




 Remove the bolt <1> in the front interior/reading light roof opening.



Continued for all vehicles:

Remove headliner:




The headliner bends easily.

! NOTE


Two technicians are needed to loosen the last connections and to remove the headliner.

 Release the clips in direction of <arrows> on the rear centering clip with a small screwdriver.

December 2020 69BD Page 17 of 24



- Lower the headliner on the left side of the vehicle in direction of <arrow 1>.
- Remove the headliner through the opening for the rear lid in direction of <arrow 2>.



Disconnect the battery:

A WARNING

Accident risk. When working on pyrotechnic components (such as airbags and belt tensioners), the battery must be disconnected with the ignition switched **ON**.


- Turn the ignition ON.
- Access the battery.
- Open the cover <3> over the battery negative terminal.
- Loosen the nut <1>.
- Remove and isolate the battery ground cable terminal from the battery pole.



Before disconnecting the battery, it is recommended to record the customer's radio presets so they can be restored before returning vehicle to the customer.


The repair information in this document is intended for use only by skilled technicians who have the proper tools, equipment and training to correctly and safely maintain your vehicle. These procedures are not intended to be attempted by "do-it-yourselfers," and you should not assume this document applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Audi dealer. ©2020 Audi of America, Inc. and Audi Canada. All Rights Reserved.

December 2020 69BD Page 18 of 24



Remove the head curtain airbag:


- Criteria 01 remove <u>right</u> side head curtain airbag.
- Criteria 02 remove <u>left</u> side head curtain airbag.
- Remove head curtain airbag bolt <3> on the Apillar.
- Remove the head curtain airbag from the clips <1> and <2>.



A WARNING


Before handling pyrotechnic components (for example, disconnecting the connector), the person handling it must "discharge static electricity". This can be done by touching the door striker, for example.

- Release connector lock and disconnect connector <1>.
- Remove cap nuts <2> and <3>.



• Detach the clip <6>.

December 2020 69BD Page 19 of 24




- Unclip the head curtain airbag clips from the body using -VAS211001-.
 - Fold airbag material <1> up to access clips <2>.
 - Guide the plier tips into the openings while holding the pliers open, press the clip catches for the head curtain airbag together and remove the clip.



The clips <2> will become damaged during removal.

• Remove head curtain airbag from vehicle.



Install new head curtain airbag:

A WARNING


Before handling pyrotechnic components (for example, disconnecting the connector), the person handling it must "discharge static electricity". This can be done by touching the door striker, for example.

Crit	Part Number	Part Description
01	8R0-880-742-L	Right head curtain airbag
02	8R0-880-741-L	Left head curtain airbag


- Ensure the black strip <7> is visible along the entire length of the head curtain airbag.
- Ensure the head curtain airbag is not twisted.
- Clip the side curtain airbag retaining tab clips
 through 5> onto the body.
- Clip the clips <6> onto the body.

The repair information in this document is intended for use only by skilled technicians who have the proper tools, equipment and training to correctly and safely maintain your vehicle. These procedures are not intended to be attempted by "do-it-yourselfers," and you should not assume this document applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Audi dealer. ©2020 Audi of America, Inc. and Audi Canada. All Rights Reserved.

December 2020 69BD Page 20 of 24



- Engage the head curtain airbag <4> on the bolt and tighten the cap nuts <2> and <3> by hand.
- Torque the cap nuts <2> and <3> to 9 Nm.
- Connect and lock connector <1>.




- Secure the head curtain airbag with the clips <1> and <2>.
- Attach the tensioning strap and torque new bolt <3> to 3.5 Nm.

Part Number	Part Description
N -912-259-01	Bolt

Assemble all trim in the reverse order of removal:

- Remove trim clips from body using Omega Clip Tool -T40280-.
- Torque fasteners as follows:
 - Interior light screws 1.6 Nm.
 - Screen separator bolts 9 Nm.
 - Luggage compartment screw 3 Nm.
 - Tie down bolts 6 Nm.


December 2020 69BD Page 21 of 24



A WARNING

Ignition must be **ON** when connecting battery. If pyrotechnic components (e.g. airbag, belt tensioner) are not repaired correctly, they may deploy unintentionally after connecting battery. There must not be anyone inside the vehicle when connecting the battery.

- Disconnect the connector <2> from the Battery Monitoring Control Module -J367- <3>.
- Attach the battery ground cable clamp by hand to the battery negative terminal and torque the nut <1> to 6 Nm.
- Reconnect the connector to the Battery Monitoring Control Module -J367-.
- Re-install the luggage compartment floor.
- Cycle the ignition off and back on.
- Set clock to local time.
- Activate the power window regulator onetouch up/down function.
- Check the DTC memories of all the control units and erase under-voltage faults if necessary.



Document vehicle and airbag information:

- Document the following on a piece of paper and attach (tape) it to the removed airbag before repackaging it for return:
 - o VIN#
 - Vehicle mileage
 - Airbag module number <A>

Proceed to Section C

The repair information in this document is intended for use only by skilled technicians who have the proper tools, equipment and training to correctly and safely maintain your vehicle. These procedures are not intended to be attempted by "do-it-yourselfers," and you should not assume this document applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Audi dealer. ©2020 Audi of America, Inc. and Audi Canada. All Rights Reserved.

December 2020 69BD Page 22 of 24

Section C - MANDATORY Parts Return Information

A IMPORTANT

DO NOT detonate the airbag prior to return. Airbags are to be returned in-tact and left in their as-removed state.

- All airbags replaced under Action 69BD must be returned to the designated inspection facility. Requests
 for all airbags will be available in the Warranty Parts Portal (WPP) once the claim has reached Approved
 status in SAGA.
- Airbags not returned or improperly returned are subject to claim cancellation.
- Action 69BD claims will be cancelled in SAGA in the event the airbag requested for return through the WPP are not received or in-transit with FedEx by the request expiration date.
- Use the Warranty Parts Portal to obtain the FedEx shipping label and required hazardous material documentation.

The repair information in this document is intended for use only by skilled technicians who have the proper tools, equipment and training to correctly and safely maintain your vehicle. These procedures are not intended to be attempted by "do-it-yourselfers," and you should not assume this document applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Audi dealer. ©2020 Audi of America, Inc. and Audi Canada. All Rights Reserved.

December 2020 69BD Page 23 of 24

Appendix A – Warning and Safety Precautions

A WARNING

General Safety Precautions when Working with Pyrotechnic Components:

- Pyrotechnic components always contain propellant that generates a gas during combustion. In some components, there is also a supply of pressurized gas to ensure this gas is generated
- This pressurized gas is stored under high pressure in a compressed gas container. Pyrotechnic components are triggered by electrical/mechanical igniters.
- Only trained personnel should perform testing, assembly and servicing work. Airbags do not have a replacement interval.
- Never check with test lamps, voltmeter or ohmmeters.
- Only check pyrotechnic components when they are installed in the vehicle using vehicle diagnosis, testing and information systems approved by the manufacturer.
- When working on pyrotechnic components and the airbag control module, disconnect the battery ground strap while the ignition is switched on. Then cover the negative terminal.
- Wait 10 seconds after disconnecting the battery.
- The ignition must be SWITCHED ON when connecting the battery. There should not be anyone inside the vehicle when doing this.
- Exception: vehicles with batteries in the passenger compartment. In this case, stay outside the range of the airbags and seat belts.
- Wash your hands after touching ignited pyrotechnic components from the restraint system.
- Do not open or repair pyrotechnic components. Use only new components to reduce the risk of injury.
- Do not install pyrotechnic components that have fallen onto a hard surface or show signs of damage.
- Discharge static electricity before handling pyrotechnic components, for example before disconnecting the electrical connector. This can be done by touching grounded metal objects such as the door striker pin.
- Install pyrotechnic components immediately after removing them from their transport packaging. If you must stop working, store the pyrotechnic component in its original transport packaging.
- Do not leave pyrotechnic components lying in the open unattended.
- Do not treat pyrotechnic components with grease, cleaning solutions or similar products.
- Do not expose pyrotechnic components to temperatures above 100 °C, even for brief periods of time.
- People in the immediate vicinity of the workplace must be protected from possible noise and projectiles.
- Pyrotechnic components can trigger unintentionally.
- In the event of deployment:
 - Single-stage inflators: allow airbag to cool down completely. Wait at least 10 minutes before handling.
 - Two-stage inflators: wait for second airbag ignition. Allow airbag to cool down completely. Wait at least 10 minutes before handling.

69BD Page 24 of 24

The repair information in this document is intended for use only by skilled technicians who have the proper tools, equipment and training to correctly and safely maintain your vehicle. These procedures are not intended to be attempted by "do-it-yourselfers," and you should not assume this document applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Audi dealer. ©2020 Audi of America, Inc. and Audi Canada. All Rights Reserved.

December 2020