

60 Noises in the sunroof mechanism

60 20 47 2050904/4 December 7, 2020. Supersedes Technical Service Bulletin Group 60 number 20-41 dated May 6, 2020 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A3, S3	2018	000001 - 050429	Not Applicable
A3 Sportback	2018	000001 - 092806	Not Applicable
RS3	2018	90000 - 905321	Not Applicable

Condition

REVISION HISTORY			
Revision	Date	Purpose	
4	-	Revised header (Added RS3)	
3	05/06/2020	Revised Warranty (Updated Claim Type)	
2	12/05/2018	Revised Service (Added Steps 4-9) Revised Warranty (Updated Labor Operations and Claim Type)	

Customer states:

 Various squeaks, noises, or rattles are heard in the sunroof area. The noises are more easily heard when the sunroof is in the fully closed or tilted position. If the sunroof is fully open, there is no noise.

Technical Background

During a certain production period, the sunroof mechanism sliding rails were contaminated with a lubricant incompatible with the approved lubricant. When the correct approved lubricant was applied to these contaminated areas the correct lubricant did not adhere to these areas. These areas were then susceptible to noises when in contact with adjacent components of the sunroof mechanism.

Production Solution

The production process was corrected.



Service

 The areas of contamination will need to be thoroughly cleaned and dried, then the correct lubricant can be applied. Open the Panoramic sunroof fully. While Figure 1 shows the glass panel removed for clarity, the glass panel does not need to be removed to perform this operation.



Figure 1. Sliding rails exposed showing the area of contamination.

2. Thoroughly clean the areas of the sliding rails shown in the illustration with All Purpose Cleaner G 065567A2 and a lint-free cloth. The area to clean is 15 cm from the rearmost edge of the rail. Perform this cleaning procedure to both sides.




Figure 2. Area of the sliding rail to be cleaned.

3. Finally, lubricate the cleaned areas with Special Lubricant G 060567A2. Perform this lubrication to both sides as well.



4. Completely open the glass lid. The picture (Figure 3) shows the locking mechanism in the guide rail.




Figure 3. The locking mechanism in the guide rail.

In the next picture (Figure 4) the cover has been removed to show what causes the noises.



Note

Please do not remove anything here.

The two components in the circle touch each other and rattle when the glass panel is tilted. To fix the rattle, the grease must get in between the components.




Figure 4. The part that causes noise.



Apply a pea-size amount of grease on a small brush. Use the special paste G 052 141
 A2. Move the brush (as shown in Figure 5) from front to back through the locking mechanism.

Tip: The direction of the movement is very important, otherwise, major damage could be caused to the roof system and the body.



Figure 5. How to apply the grease.

7. The next picture (Figure 6) shows the mechanism unlocked.



Figure 6. Unlocked mechanism.



The following picture (Figure 7) shows the mechanism locked.



Note:

At the end of the repair, the mechanism must be locked.




Figure 7. Locked mechanism.

9. Close the glass panel again. Verify that the condition has been resolved.

Warranty

warranty				
Claim Type:	 110 up to 48 Months/50,000 Miles. G10 for CPO Covered Vehicles – Verify Owner. 			
	If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.			
Service Number:	6028			
Damage Code:	0020			
Labor Operations:	Sliding roof cleaned with maintenance service	6005 2950	See SRT with associated operations	
Diagnostic Time:	GFF	No allowance	0 TU	
	Road test prior to service procedure	0121 0002	10 TU	
	Road test after service procedure	0121 0004	10 TU	



Claim Comment:	As per TSB #2050904/4
Ciaiiii Coiiiiileiit.	A5 per 13B #2030304/4

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Part Number	Part Description	Quantity
G 065567A2	VOLKSWAGEN GROUP G 065 567 A2 Geinigungslösung Gening solution Wrant de nettops Wrant de nettops Gelvente limpleze Satter roztek 3 Mar e 100m²	0.2
G 060567A2	All Purpose Cleaner Volkswagen Goos of A2 Journal Coleimitte J	0.2



G 052141A2	Paste	0.1
	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA

Additional Information

All parts and service references provided in this TSB (2050904) are subject to change and/or removal.

©2020 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.