

 HYUNDAI Technical Service Bulletin	GROUP CAMPAIGN	NUMBER 20-01-045H
	DATE DECEMBER 2020	MODEL(S) SONATA (DN8A)
SUBJECT: SONATA (DN8A) SAFE EXIT ASSIST ACTIVATION PROCEDURE (SERVICE CAMPAIGN T5L)		

★ IMPORTANT

***** Dealer Stock and Retail Vehicles *****

Dealers must perform this Service Campaign on all affected vehicles prior to customer retail delivery and whenever an affected vehicle is in the shop for any maintenance or repair.

When a vehicle arrives at the service department, access Hyundai Motor America's "Vehicle Information Screen (VIS)" screen via WEBDCS to identify open Campaigns.

Description: This bulletin describes the procedure to identify and program certain Sonata vehicles Rear Corner Radars from the Advanced Driver Assistance Systems (ADAS) modules to enable the Safe Exit Assist (SEA) warning feature.

Applicable Vehicles: Certain 2021MY Sonata equipped with ADAS and produced from 07/29/2020 to 11/23/2020

Warranty Information:

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
Sonata (DN8A)	00DA26R0	Safe Exit Assist Activation	0.3 M/H	99140L0000	M72	ZZ3

Note 1: Submit claim on Campaign Claim Entry Screen

Note 2: If a part is found in need of replacement while performing the repair for this Service Campaign T5L, and the affected part is still under warranty, please submit a separate claim using the same Repair Order. If the affected part is out of warranty, submit a prior approval request for goodwill consideration prior to performing the work.

Service Procedure:

1. Press the **Engine Start Stop** button to start the vehicle with the engine off.



2. Insert the GDS scan tool into the vehicle's Onboard Diagnostic II (OBDII) port.

NOTICE


The GDS scan tool must sit flush inside the OBD II port, and the Function light must illuminate before proceeding.



- Turn on the GDS tablet, and select **S/W Management**.


NOTICE

An error message will appear on GDS screen if the scan tool is not properly inserted in the OBD II port after selecting S/W Management.



- After selecting S/W management, a list of onboard vehicle components should appear on the GDS screen.


Select **Rear Corner Radar-Left**.



5. Select **BCW (BSD) variant coding** from the drop down menu.

CAUTION

Properly select all icons to avoid erasing other software.




6. After selecting BCW (BSD) variant coding, two instruction screens will appear.


Select **OK**.

CAUTION

Do not perform recalibration of the BCW radar after variant coding is complete as the onscreen instructions states.




7. Select **OK**.




8. Select **SEA Status** then select **ENABLE** from the “DISABLE/ENABLE” drop down tab.

Select **OK**.



9. Select **OK**, and repeat the procedure for **Rear Corner Radar-Right**.



10. **Verification after BSD Variant Coding:**

Vehicle equipped with AVN:

Restart the vehicle, then access the AVN Headunit.

Select **Set-up**, then choose the vehicle icon. Select **Driver Assistance** then **Blind Spot Safety**. A check mark should be placed at **Safe Exit Assist**.



Vehicle equipped with D-Audio:

Restart the vehicle, then select the mode button on the steering wheel to access the cluster menu.

Select **User Settings** then **Driver Assistance**. Select **Blind Spot Safety** from the drop down menu. A check mark should be placed at **Safe Exist Assist**.

