

GROUP	NUMBER		
CAMPAIGN	20-01-004H-3		
DATE	MODEL(S)		
DECEMBER 2020	APPLICABLE VEHICLES BELOW		

SUBJECT:

THETA GDI ENGINE DTC P1326 - ENGINE INSPECTION / REPLACEMENT (SERVICE CAMPAIGN T3G)

This TSB supersedes TSB# 20-01-004H-2 to update the Service Procedure Flowchart and Service Procedure contents to reflect various process revisions.

* IMPORTANT

*** Dealer Stock & Retail Vehicles ***

Dealers must perform this Service Campaign on all affected vehicles prior to customer retail delivery and whenever an affected vehicle is in the shop for any maintenance or repair.

Description: Applicable vehicles with 2.0L Turbo and 2.4L GDI engines may experience the Check Engine warning lamp illuminated with DTC P1326. Follow the procedure to inspect the vehicle and replace the engine or update the engine ECU software based on the inspection results.

Applicable Vehicles:

Certain 2011-2014 MY Sonata (YF) vehicles with 2.0L Turbo and 2.4L engines

Certain 2015-2019 MY Sonata (LF) vehicles with 2.0L Turbo and 2.4L engines

Certain 2013-2018 MY Santa Fe Sport (AN) vehicles with 2.0L Turbo and 2.4L engines

Certain 2019 MY Santa Fe (TM) vehicles with 2.0L Turbo and 2.4L engines

Certain 2014-2015 MY Tucson (LM) vehicles with 2.4L engines

Certain 2018-2019 MY Tucson (TL) vehicles with 2.4L engines

Certain 2019 MY Veloster N (JSN) vehicles with 2.0L Turbo engines

SST Information:

Part Number / Figure	Note		
09314-3Q100-01	Only needed if engine replacement is required. Refer to TSB 19-FL-001H for the		
	detailed usage instructions.		
09353-2B000	Order replacements through Bosch at 1-866-539-4248.		
128 — 4 112 — 17 3 — 102 — 17 3 — 102 — 17 3 — 103 — 17 3 — 104 — 17 1	Required to drain oil if necessary. Order from ULINE at 800-295-5510 or ULINE.com. An alternative container can be used but it must have clear markings to indicate fluid levels in quarts (1-4 quarts) for PA Approval purposes.		
	09314-3Q100-01 09353-2B000 4 - 128 - 4 112 - 17 3 - 102		

SST Information (cont.)

Part Name	Part Number / Figure	Note		
BEARING CLEARANCE TESTER SET (BEARING TOOL)	(1) TEST HOSE (2) MAIN HOSE (3) POWER SUPPLY CABLE One BEARING CLEARANCE TESTER SET provided to dealers. (Additional units can be ordered.)	Confirm the following pressures meet requirements. The correct ranges for AP/VC air pressures are also indicated with red/blue decals on the gauges: Shop air supply: 50 psi minimum AP: 0.1 ~ 0.11MPa VC: -73 ~ -83Kpa (Refer to TSB 20-GI-009H or later for calibration procedure) For Bearing Clearance Tester software related issues, contact GITA at: 888-437-0308 For Bearing Clearance Tester		
	KQ231-2T110QQH	hardware related issues, contact Techline at: 800-325-6604 BEARING CLEARANCE TESTER SET (BEARING TOOL)		
	KO224 2T400OOLI	(includes A - F)		
	KQ231-2T100QQH	(A) BODY (B) SPARK PLUG ROD		
	KQ231-2T101QQH	(CLEARANCE GAUGE)		
	KQ231-2T102QQH	(C) CRANK ROTATOR TOOL		
	KQ231-2T103QQH	(D) CLEARANCE GAUGE		
	KQ231-2T104QQH	(E) POWER SUPPLY CABLE		
	KQ231-2T105QQH	(F) TEST HOSE (AIR HOSE FOR CLEARANCE GAUGE)		

Optional Tool:

Part Name	Part Number / Figure	Note	
17 mm 12-Point Metric Flank Drive® Reversible Ratcheting	(Snap-on) SRXRM17	For unfastening torque converter bolts to separate engine/trans	
Box/ Speed Open-End Combination Wrench	17mm Snap-on 17mm	between bellhousing if engine cannot rotate.	

TSB #: 20-01-004H-3 Page 2 of 20

Parts Information:

NOTE: Use the **Service Process Results Worksheet** in the following page as a guide to determine the appropriate Part Number(s).

- 1. Order the required parts based on the vehicle inspection results outlined in the Service Procedure Flowchart. (Use the **Service Process Results Worksheet** in the following page as a guide to determine the appropriate part numbers.)
- 2. Refer to TSB # 20-01-024H-2 (or latest revision) for parts information
- 3. Refer to HMA Warranty Policy prior to ordering a reman engine. A standard service engine or QQH engine is required in certain cases.

Warranty Information:

NOTE: Use the **Service Process Results Worksheet** in the following page as a guide to determine the appropriate Op Code.

- 1. The Campaign 953 Engine ECM Update is only required if new software is available. In this case, choose one of the following methods:
 - Select a Campaign T3G Op Code with the ECM update included if available, OR
 - > Submit a separate campaign claim for the ECM update using Campaign 953 op codes (in addition to submitting applicable T3G op code)
- 2. Refer to TSB # 20-01-024H-2 (or latest revision) for OP Codes
- 3. Campaign T3G OP codes for engine replacement should only be used if engine replacement is deemed necessary by the service procedure in this TSB.
 - > Refer to Prior Approval Submission Documentation at last page for checklist of PA items.
 - General engine replacement for conditions outside of those contained in this TSB are not covered by Campaign T3G.

Engine Oil Maintenance Information

Poor oil maintenance reduces the engine oil lubrication and cooling capacities. As a result, internal engine parts can be damaged resulting in abnormal wear to internal engine parts, excessive carbon deposits, sludge, and other various conditions. An inspection for these conditions and others may be required prior to engine approval.

NOTICE

Engine oil is used to lubricate, cool, and operate various engine parts. Engine oil changes and engine oil level checks are required on a regular basis for all engines.

Engine oil level checks and top-ups are recommended if they are needed prior to the end of an oil change interval.



Piston Ring Deposits



Oil Sludge



Excessive Wear


TSB #: 20-01-004H-3 Page 3 of 20

Service Process Results Worksheet: (Print copies of the form below in this page for multiple uses.)


6-Digit VIN:	Repair (Order#:				
Options / Tests / Procedures	(Circle ALL Vehicle Options / Test Results / Performed Procedures That Apply)					
Vehicle Model Year	11	12	13	14	15	
Vernicie Moder Tear	16	17	18	19		
Vahiala Madal Tuna	SONATA		S	SANTA FE SPORT		
Vehicle Model Type	TU	TUCSON		VELOSTER N		
Vehicle Engine Size		2.4L		2.0T		
Smart Cruise Control (SCC)	Yes			No		
All Wheel Drive (AWD)	Yes			No		
Crank Rotation	Yes			No		
(w/ 94 lb-ft. or less)	100					
External Lower End Damage	DAMAGED		1	NOT DAMAGED		
Oil Drain Procedure Required	Yes Yes			No No NO PASS		
Bearing Clearance Test Performed						
Bearing Clearance Test Result		PASS				
Abnormal Engine Noise		Yes		No		
Knock Sensor Replaced (in this Repair Order)	Yes			No		
Replaced Engine (in this Repair Order)	Yes			No		
Replacement Engine (if replaced)	NEW			REMAN		
ECM Newly Updated (in this Repair Order)	Yes			No		
Contacted Techline	Yes			No		

TSB #: 20-01-004H-3 Page 4 of 20


Service Procedure Flowchart:



TSB #: 20-01-004H-3 Page 5 of 20



TSB #: 20-01-004H-3 Page 6 of 20



TSB #: 20-01-004H-3 Page 7 of 20

Service Procedure:

Initial Inspection:

- 1. Scan for DTC P1326 using the GDS.
 - ❖ If DTC P1326 (or any other code) is present, take screenshot of Freeze Frame data for PA using GDS screen capture if any DTCs are present and proceed to Step 2.
- 2. Check for any sludge under the engine oil filler cap.
 - ➤ Using STUI on the GDS, take and submit a picture of the oil cap underside with the VIN in the background of the photo (RO or last 6 digits written on paper). **VIN must be legible.**
 - Sludge under oil cap: Submit Warranty Prior Approval (PA).
 - ❖ No sludge under oil cap: Continue to next step.
- 3. Check for any engine oil on the engine oil dipstick.
 - ➤ Using STUI on the GDS, take and submit a picture of the dipstick with the VIN in the background of the photo (RO or last 6 digits written on paper). **VIN must be legible.**
 - ❖ No engine oil on dipstick: Submit Warranty Prior Approval (PA)
 - Engine oil on the dipstick: Continue to Engine Rotation Check.

Engine Rotation Check:

- 1. Rotate the crankshaft with the crank rotator SST.
- ➤ If the crankshaft cannot be turned with a moderate force, then measure the force required to turn the crankshaft with a torque wrench.
- If the SST or shop tools do not fit the specific vehicle type, remove the front passenger wheel and wheel liner or underbody tray as needed to rotate the crankshaft.

NOTICE

If other engine accessory components are seized, remove the engine accessory belt prior to completing the engine rotation check.

- If the crankshaft rotates normally:
 - o Proceed to Bearing Inspection and follow the procedure sequence in Flow Chart A.
- If the force required for rotating the crankshaft is greater than 94 lb-ft., documentation through STUI video is required.
 - o Follow the procedure sequence in **Flow Chart B** and note the following differences.
 - > If there is NO lower end damage:
 - o Follow the Oil Drain Procedure in the following page.
 - > If there is external lower end damage:
 - Using STUI in the GDS, submit a picture of the damage with the VIN in the background of the photo (RO or last 6 digits written on paper). VIN must be legible.
 - Follow the Oil Drain Procedure in the following page.

TSB #: 20-01-004H-3 Page 8 of 20

NOTICE

PA Approval is required for engine replacement. Submit PA and refer to the Dealer Best Practices guide for the latest requirements for engine approval.

- 1) If engine does not rotate normally, a STUI video including the following is required:
 - VIN Plate (at windshield or on door jamb)
 - Attempt to rotate the crankshaft
- 2) Save the crankshaft rotation torque value
- 3) A picture of the lower end damage is required if present


Additional documentation may be required:

- > Refer to Prior Approval Submission Documentation at last page for PA required items.
- Use STUI feature on the GDS to take and submit pictures and videos.

Oil Drain Procedure:

- 1. Remove the engine oil filler cap (A) and engine oil level gauge (B).
- 2. Lift up the vehicle and remove the oil drain plug (C).

- 3. Drain the engine oil into a container. The 1-4 quart level should be clearly marked and visible on the container. Using STUI in the GDS, take and submit a picture of the oil container with the drained oil level clearly visible and the VIN in the background of the photo (RO or last 6 digits written on paper) for records, if needed. VIN must be legible.
- 4. Submit PA for engine replacement approval.







TSB #: 20-01-004H-3 Page 9 of 20

Bearing Inspection:

1. Connect the main hose (shop air supply) and test hose to the bearing tool (with other end of the test hose disconnected). (The power to the bearing tool main unit is not necessary at this time.)


Confirm the shop air pressure and AP/VC pressures on the bearing tool meet requirements. The correct ranges for AP/VC air pressures are also indicated with red/blue decals on the gauges. Using STUI in the GDS, take and submit a picture of the gauges with the pressure levels clearly visible and the VIN in the background of the photo (RO or last 6 digits written on paper) for records.


Shop air supply: 50 psi minimum

AP/VC air pressure calibration check:

- a) Connect the main air compressor hose.
- b) Connect the test hose. (The other end of the test hose should be left disconnected from the spark plug rod.)
- c) Confirm that the AP/VC toggle switch at top is in the middle position.
- d) Inspect the AP/C gauge indicators and compare to the specification range:

AP: 0.1 ~ 0.11MPaVC: -73 ~ -83Kpa





NOTICE

Do not continue if any of the above readings are out of specification range.

- Adjust shop air to consistently provide at least 50 PSI of air pressure or greater.
- Do not use a portable air compressor to perform the bearing clearance testing.
- Be sure to check that the shop air water separator is functioning correctly.
- If any of the AP/VC air pressure indications are out of the specified range, recalibration of the Bearing Clearance Tester is required.
 - Refer to latest instructions outlined in the Engine Bearing Clearance Tester Calibration Procedure TSB 20-GI-009H or later for calibration procedure.


NOTICE

For Bearing Clearance Tester <u>software</u> related issues, contact GITA at: 888-437-0308 For Bearing Clearance Tester hardware related issues, contact Techline at: 800-325-6604

TSB #: 20-01-004H-3 Page 10 of 20

2. Remove the engine cover and the 4 ignition coils.

Tightening Torque (ignition coils): 9.8 - 11.8 N·m (1.0 - 1.2 kgf·m, 7.2 - 8.7 lb·ft)



Tightening Torque: 14.7 - 24.5 N·m (1.5 - 2.5 kgf·m, 10.9 - 18.0 lb·ft)

4. Insert the spark plug rod SST (A) into Cylinder #1 spark plug hole and turn until hand tight. Insert the clearance gauge SST into the spark plug rod and tighten using the thumb screw.

NOTICE


DO NOT connect the test air hose to the clearance gauge at this time.

- 5. Connect the GDS to the vehicle and turn the ignition 'ON'.
- 6. Swipe up on the 'More' tab at the bottom of the GDS home screen. Select the 'Special Inspection' function.
- 8. Enter the vehicle info into the GDS as prompted then select 'Next'.










TSB #: 20-01-004H-3 Page 11 of 20

- 9. Connect the GDS to the clearance gauge SST (gauge) via Bluetooth:
 - Press the "Set' button (B) on the gauge to turn it on.
 - Press the "Set" (B) and "Mode" (C) buttons at the same time for about 4 sec until the "reset" message is displayed.
 - Select the gauge in the list of devices on the GDS. Select the 'Refresh' icon (D) if the gauge doesn't appear automatically.



- Check that the ball point tip (E) of the clearance gauge SST is securely installed to the tool as shown. Do not continue if ball point tip (E) is loose or missing.
- 10. Turn the ignition 'OFF' and remove the VCI.



NOTICE

If more than one device appears in the list of devices, there is another device in range. Move away from the other device to pair the gauge.





11. Follow the instructions on the GDS to start the test and select 'Next'.

NOTICE

- For the following steps, the Crank Rotator Tool or a long handled wrench should be used for moving the crankshaft slowly and precisely.
- Ensure the test hose is disconnected from the clearance gauge when finding TDC piston depth.

NOTICE

Please take note of the following crank/piston position definitions.

- ***** BTDC (Before Top Dead Center)
- **❖** TDC (Top Dead Center) ← Find TDC during the compression stroke.
- ATDC (After Top Dead Center)

In the following steps, the TDC point for testing must be at MAX (piston height) value minus 0.03mm as the crank has moved slightly into ATDC (from its TDC dwell point).

If TDC is difficult to find, refer to Shop Manual Section Location: Engine Mechanical System
 > Timing System > Timing Chain

TSB #: 20-01-004H-3 Page 12 of 20

- 12. To find TDC compression (TDC), rotate the crankshaft with the crank rotator SST at least one cycle (1/2 turn). (If the SST does not fit the specific vehicle type, remove the front passenger wheel and wheel liner or underbody tray as needed to rotate the crankshaft using standard shop tools.)
- Monitor the piston height value on GDS screen or the clearance gauge SST while rotating the engine clockwise using the Crank Rotator Tool.
 - ➤ Rotate the engine SLOWLY as the value increases towards a MAX value. (BTDC → TDC)
 - When the value changes direction (increasing/BTDC → TDC → decreasing/ATDC), stop rotating the crank when the piston height is at MAX value minus 0.03mm.



NOTICE

The testing point is slightly towards ATDC from TDC when the piston has moved down 0.03mm from its highest position.


- 13. Select 'Next' when TDC is found.
 - Ideal set point for testing from TDC is found when the maximum value minus 0.03mm is reached on the clearance gauge SST (F).
 - The value is also displayed on the GDS.
- 14. Once the set point for bearing testing is found, select 'Start' in the GDS screen and proceed directly to the next step below.
 - ➤ Do not turn the crank rotator SST until instructed to do so.

Sylvac Sy

NOTICE

The value at TDC varies depending on the specific vehicle and engine type.

15. Connect the test hose (1) to the spark plug rod SST and to the bearing tool SST.



TSB #: 20-01-004H-3 Page 13 of 20

- 16. Connect the SST power cables to a fully charged 12V battery or to an external AC/DC power supply.
 - Turn the bearing tool SST power switch 'ON'



NOTICE


*** Bearing Tool SST Power Check ***


- a) Supply 12 volts (or an alternate external AC/DC 13.8 volt power supply with at least ~2 amp output) to the power cable (3) connected to the bearing tool SST.
- b) Turn power switch to ON.
- c) Toggle AP/VC transfer switch between AP <> VC.
 - ❖ The solenoids should "click" while switching between AP/VC when the unit is ON.
 - ❖ If the solenoids are not switching, then check the power cable or the power supply.
- 17. Locate the AP/VC switch on the bearing tool SST and switch it to the AP Position.
- 18. Follow the instructions on the GDS to test each cylinder. Cylinder #1 is checked first.
 - ➤ The cylinders will be checked per the engine firing order: #1→#3→#4→#2.
- 19. On the bearing tool SST, change the AP/VC switch to the VC position when instructed by the GDS.


NOTICE

If the bearing measurement value does not change when the AP/VC is switched or the "Unable to measure" message appears on the GDS, rotate the crankshaft further as the exhaust valves could be open. Set the crankshaft to TDC again (Step 11).

Ensure the test hose is disconnected from the clearance gauge SST when finding TDC.








TSB #: 20-01-004H-3 Page 14 of 20

20. Continue following the instructions on the GDS to complete the bearing inspection. Check the engine oil level and select the level in the GDS.





21. If the test result is "PASS":

- a) Save a screenshot of the results screen.
 - If there is audible engine noise:
 - Refer to HTSS "Fix it Right" under symptom: "Engine Noise-Undetermined"
 - Using STUI on the GDS, record and submit a video of the engine noise 1-2 ft above the valve cover. Include the VIN Plate (at windshield or on door jamb) in the beginning of the video.
 - Follow remainder of Flow Chart A to complete the procedure.
 - If there is no audible engine noise:
 - Follow remainder of Flow Chart A to complete the procedure.
- b) Reinstall all components in the reverse order of removal.
- c) Check for DTCs and perform the appropriate diagnostic service. Ensure no warning lights are present to complete the procedure.

If the test result is "NO PASS":

- a) Save a screenshot of the results screen.
- b) Submit PA for engine replacement approval.
- Follow remainder of Flow Chart A and Engine Replacement section of this TSB to complete the service procedure.
- d) Check for DTCs and perform the appropriate diagnostic service. Ensure no warning lights are present to complete the procedure.





NOTICE

PA Approval is required for engine replacement. Submit PA and refer to the Dealer Best Practices guide for the latest requirements for engine approval.

Refer to Prior Approval Submission Documentation section at the last page of this TSB for the itemized checklist.

TSB #: 20-01-004H-3 Page 15 of 20

Engine Replacement:

- 1. Continue with engine replacement if necessary according to the Service Procedure Flowchart.
- 2. Follow the applicable shop manual to remove the engine from the vehicle. The specific method for removal varies by model.
 - **Shop Manual Section Location:** Engine Mechanical > Engine And Transaxle Assembly > Engine And Transaxle Assembly > **Repair Procedures**


NOTICE


Record the audio station presets (XM, AM, FM, etc.) prior to disconnecting the battery.

3. Certain replacement engines must be prepared prior to installation. Some components from the existing engine must be transferred to the new engine.


NOTICE

Take special care of the original engine parts that will be required for reinstallation on to the replacement engine.






- 4. **(For 2.4L with ULEV / FED emissions only)** 2.4L replacement engines are produced with the exhaust manifold studs configured for SULEV / CAL emissions package.
 - Two exhaust studs must be relocated on the new engine and 1 exhaust stud must be transferred from the old engine.
 - Use a commercially available stud removal tool or use the double-nut technique to complete this step.



SULEV / CAL Spec

ULEV / FED Spec



Exhaust Stud Position Relocation Information

TSB #: 20-01-004H-3 Page 16 of 20

5. Remove and reinstall the engine knock sensor from the old engine to the new engine.

Knock Sensor Fastener Tightening torque: 21Nm (15.5lb-ft)

NOTICE

Ensure the knock sensor is torqued to specification using a torque wrench.

- Improper installation can result in DTC codes.
- 6. If 21101-2GK70QQA engine is used:
- Install the oil filler cap from the old engine to the new one.
- Install the drive plate/flywheel on the new engine using new bolts (QTY 7).
 - ❖ Drive Plate Tightening torque: 111.7 ~ 127.5 Nm (86.8 ~ 94.1 lb-ft)
- 7. Follow the published procedure outlined in **TSB 19-FL-001H** to remove and reinstall the following GDI high pressure fuel system components from the existing engine to the new engine:
- GDI High Pressure Pump
- Fuel Injectors (4)
- Fuel Rail

The corresponding Service Kits will supply the required new parts per TSB 19-FL-001H to complete the transfer of the above existing parts.

- 8. Install the new oil cooler hoses if applicable.
- 9. Reconnect and reinstall the engine front harness.





A CAUTION

Follow TSB 19-FL-001H carefully and replace the following newly supplied parts from the Service Kits:

- Mounting flange O-ring (for High Pressure Pump)
- O-rings, Backup Rings, Washer Seals, Combustion Seal Rings, and clips (for Fuel Injectors)
- Fuel Pipe (between High Pressure Pump and Fuel Rail)

In addition, the Service Kits include (1) Exhaust Pipe Gasket. Install this new gasket when attaching the front and center muffler assemblies together during the engine installation.

TSB #: 20-01-004H-3 Page 17 of 20

10. Follow the published Service Information from the applicable **Shop Manual** to reinstall the Sub Engine Assembly.

Shop Manual Section Location: Engine
Mechanical > Engine And Transaxle Assembly >
Engine And Transaxle Assembly > Repair
Procedures

NOTICE

Be sure to replace the following newly supplied parts from the Service Kit:

- Oil Level Rod & Oil Level Guide Assy.
- Intake Manifold Gaskets (4)
- Exhaust Manifold Gasket
- Fuel Pipe Assembly
- (2.0T Only) Turbo Oil Feed Hose & Pipe
- (2.0T Only) Turbo Oil Drain Gasket (2)
- (2.0T Only) Oil Drain Gasket
- (2.0T Only) Gasket (2)
- 11. Connect the (2) oil coolant hoses between the oil cooler and the water temperature control assembly.
 - ➤ Fill the cooling system with 50/50 ~ 70/30 (Water/Anti-Freeze) coolant mixture.

NOTICE

If the torque converter has moved from the fully inserted position, carefully push inward and rotate the torque converter until the converter is recessed approximately 5/16" - 9/16" (8 -14 mm) into the transaxle case when reinstalling the automatic transaxle.

Check the depth of the torque converter to confirm it's fully installed in the transmission otherwise the oil pump may be damaged resulting in transmission failure.



12. Fill the engine crankcase:

- a) Add 5.8 quarts for the initial dry fill of the engine.
- b) With the fuel system disabled temporarily, crank the engine for several seconds to prime the lubrication system prior to starting the engine.

> Recommended Oil Specifications:

- o For all models excluding Veloster N (JSN):
 - 5W-30 Full Synthetic type with API SN/SN+/SP, ILSAC GF4/GF5 or higher service grade
- o For Veloster N (JSN):
 - 0W-30 (or 5W30 if not available) Full Synthetic type with SN/SN+/SP, ILSAC GF4/5 or higher grade
- 13. Start the engine to warm it up and begin the cooling system air bleeding process.
 - Check for any leaks during this time.
 - After the engine has warmed up to normal operating temperature, turn the engine off, wait a few minutes, and then adjust the engine oil level to near the "F" mark as shown.



TSB #: 20-01-004H-3 Page 18 of 20

- 14. Refer to Campaign 953 to update the Engine ECM if new software is available.
- 15. When all fluids have been fully filled and all work quality checks are completed:
 - a) Set the customer's audio station presets.
 - b) Relearn the Steering Angle Sensor using the GDS.
 - c) <u>Clear DTC P1326 with engine ON</u>. P1326 may reset if it's not cleared with the engine running. Then check for other DTCs and perform the appropriate diagnostic service. Ensure no warning lights are present.
 - d) Reset the engine adaptive values using the GDS.
 - e) Perform a short road test to confirm normal vehicle drivability.

NOTICE

- Clear DTC P1326 with engine ON. P1326 may reset if not cleared with the engine running.
- Reset engine adaptive values.

TSB #: 20-01-004H-3 Page 19 of 20

Prior Approval Submission Documentation:

- Refer to chart below for items needed for submissions based on condition.
- If current condition does not fall within the chart below, contact Techline.

	Cannot Rotate Crankshaft @94lb-ft / Damaged	Knocking Concern & BCT Test "PASS"	Sludge on Oil Cap or No Oil on Dipstick	132/162 Kurtosis "NO PASS"	T3G Bearing Clearance "NO PASS"
Repair Order	✓	✓	✓	N/A	N/A
Engine Diagnostic Worksheet	✓	✓	✓	N/A	✓
Towing Invoice	If Available	If Applicable	If Applicable	N/A	N/A
GDS DTC Freeze Frame Screen Print	✓	✓	✓	N/A	✓
Two Sound Tests Uploaded	N/A	N/A	N/A	✓	N/A
One Bearing Test Uploaded	N/A	~	N/A	N/A	✓
BCT Calibration Photo**	N/A	✓	N/A	N/A	✓
Photo of Oil Cap**	✓	✓	✓	N/A	✓
Photo of Oil Dipstick**	✓	✓	✓	N/A	✓
Photo of Oil Drain Measurement	✓	N/A	If Requested	N/A	N/A
Crank Rotation Video	✓	N/A	N/A	N/A	N/A
Engine Noise Video	N/A	✓	N/A	N/A	N/A
Photo of Cylinder Block Damage**	If Applicable	N/A	N/A	N/A	N/A
Copy of Maintenance Records	If Requested by PA	If Requested by PA	If Requested by PA	N/A	If Requested by PA
Photo of Valvetrain**	If Requested by PA	If Requested by PA	If Requested by PA	N/A	If Requested by PA
Photo of Accident Damage**	If Applicable	If Applicable	If Applicable	N/A	If Applicable

**Proper Photos / Videos:

- VIN in view when photo is taken of the item in question. (Windshield or doorjamb VIN Plate)
 - o **Exception:** For oil Measurement photo, a Repair Order in photo will suffice.
- Photo taken with clear focus, showing the item being presented.
- BCT Connection Calibration Test show connections and gauges clearly (up to two photos)
- Crank Rotation Video and Engine Noise Video start at the Windshield VIN Plate and move to the front of the engine showing no crankshaft movement or noise (as applicable) in a continuous video beginning to end.
 - o ***Returned engines may be inspected by WTC for a seized condition***

Media Submission Process:

All photos / videos will be submitted via Single Technician User Interface (STUI).
 (See Page 4 of Tech Net Times Vol 30 Issue 7 for additional details.)

TSB #: 20-01-004H-3 Page 20 of 20