

#### SIB 61 11 20

2020-12-21

# WHEN LOCKING VEHICLE, DOORS ARE LOCKED BUT VEHICLE IS NOT SECURED

This Service Information Bulletin (Revision 2) replaces SI B61 11 20 dated November 2020.

What's New (Specific text highlighted):

- · Procedure updated to all models
- · Target I-level updated for all vehicles

#### **MODEL**

E-Series	Model Description	Affected Option Code		
F44	2 Series Gran Coupe			
F91	M8 Convertible			
F92	M8 Coupe			
F93	M8 Gran Coupe			
F95	X5 M Sports Activity Vehicle			
F96	X6 M Sports Activity Vehicle			
G05	X5 Sports Activity Vehicle	Only vehicles without SA322 Comfort		
G06	X6 Sports Activity Vehicle	Access.		
G07	X7 Sports Activity Vehicle	ity Vehicle		
G14	8 Series Convertible			
G15	8 Series Coupe			
G16	8 Series Gran Coupe			
G20	3 Series Sedan			
G22	4 Series Coupe			
G29	Z4 Roadster			

## **SITUATION**

The customer complains that when locking the vehicle from the outside using the remote control:

- The doors lock
- The alarm system is not activated
- The side mirrors (when the function is activated) do not fold in

#### **CAUSE**

Due to a software error on the Body Domain Controller (BDC), it identified the remote control as being inside even though the remote control is actually located outside the vehicle. This caused the doors to be locked without securing the vehicle.

# **PROCEDURE**

F44, G20, G29:

- 1. Perform diagnosis with the latest version of ISTA, working through test module, if needed.
- Is the vehicle current integration level up to S18A-20-03-530 or higher?

YES: Do not program the vehicle and perform diagnosis with ISTA

NO: Proceed to Step 3

3. Program the vehicle using ISTA **4.22.3** or higher (released March 2020).

Model	Target integration level
F44	
G20	<b>S18A-20-03-530</b> or higher
G29	

- 1. Perform diagnosis with the latest version of ISTA, working through test module, if needed.
- 2. Is the vehicle current integration level up to \$18A-20-11-5xxor higher?

YES: Do not program the vehicle and perform diagnosis with ISTA

NO: Proceed to Step 3

3. Program the vehicle using ISTA **4.27.2** or higher (estimated release Mid December, pending verification).

	Target integration level		
Model			
F44			
F91			
F92			
F93			
F95			
F96			
G05	0404 00 44 500 111		
G06	<b>S18A-20-11-500</b> or higher		
G07			
G14			
G15			
G16			
G20			
G22			
G29			

Note that ISTA will automatically reprogram and code all programmable control modules that do not have the latest software.

#### Always connect a BMW-approved battery charger/power supply (SI B04 23 10).

For information on programming and coding with ISTA, refer to DealerSpeed / TIS / Technical Documentation / Diagnostics and Programming / Programming Documentation.

Note: Until the I-level solution is available, it is only possible to SECURE the vehicle if:

- The customer unlocks the vehicle again with the remote control,
- Opens the driver's door and closes it again,
- Locks the vehicle at a greater distance (> approx.. 3.5' (1 meter)) from the vehicle using the remote control

## **WARRANTY INFORMATION**

During this workshop visit, the affected vehicle may also show one or more programming and encoding Technical Campaign repairs open. The programming and encoding procedure may only be invoiced one time.

Please do not wait for the software release identified in this bulletin, update the vehicle to the current available I-level by performing and submitting for one of these open Technical Campaigns instead. Please be sure to also perform any additional work the campaign repairs require and/or close the remaining open programming and encoding the Campaign repairs as outlined in the corresponding Service Information Bulletin.

When the BMW software solution identified in this bulletin is released:

If available, update the software by performing any newer open applicable Technical Campaign repairs.

If qualifying Technical Campaign repairs are not listed or are not open, the BMW software solution (when available) will then be covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks or the BMW Certified Pre-Owned Program, claim the repair as described below.

Defect Code:	6138270200	BDC Body Domain Controller software equipment fault	error / internal
Labor Operation	Description		Labor Allowance
00 00 006	Performing vehicle test (with vehicle diagnosis system – checking faults) (Main work)		Refer to AIR
Or:			
00 00 556	Performing vehicle test (with vehicle diagnosis system – checking faults) (Plus work)		Refer to AIR
And:			
61 21 528	Connect an approved battery charger/power supply (indicated in AIR as Charging battery)		Refer to AIR
And, as necessary:			
61 00 006 Performing veh		hicle diagnosis – test module	Work time (WT)
And:			
61 00 730 Programming/encoding control		encoding control unit(s)	Refer to AIR

If you are using a Main labor code for another repair, use the Plus code labor operation 00 00 556 instead of 00 00 006

Refer to AIR for the corresponding flat rate unit (FRU) allowances.

Work time labor operation code 61 00 006 is not considered a Main labor operation; however; it does require an individual punch time to support the FRU amount claimed and an explanation on the repair order and in the claim comments section.

## **Programming and Encoding - Vehicle Control Units (RO and Claim Comments Required)**

The programming procedure automatically reprograms and encodes all vehicle control modules which do not have the latest software I-level. If one or more control module failures occur during this programming procedure:

Please claim this consequential control module-related repair work (including performing the IRAP
Control Unit Recovery procedure first as required, refer to the SIB in AIR) under the defect code listed
in this bulletin with the applicable AIR labor operations.

Please explain this additional work (The why and what) on the repair order and in the claim comments section

For control module failures that occurred prior to performing this programming procedure:

When covered under an applicable limited warranty, claim the applicable test plan and the
corresponding control module-related repair work using the applicable defect code and labor
operations in AIR (including diagnosis with separate punch times).

#### Other Repairs:

If other eligible and covered work is performed as a result of performing the ISTA diagnostics and related test plans, claim this work with the applicable defect code and the labor operations that are listed in AIR (including diagnosis with separate punch times).

### QUESTIONS REGARDING THIS BULLETIN

Technical Inquiries	Submit feedback at the top of this bulletin
Warranty Inquiries	Submit an IDS ticket to the Warranty Department
Parts Inquiries	Submit an IDS ticket to the Parts Department