



**NUMBER:** 08-063-20

**GROUP:** 08 - Electrical

**DATE:** June 13, 2020

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**This Service Bulletin is also being released as Rapid Response Transmittal (RRT) 20-038, dated June 13th, 2020. All applicable Sold and Un-Sold RRT VINs have been loaded. To verify this RRT service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty.**

**SUBJECT:**

Flash: Security Gateway Module (SGW) Enhancements

**OVERVIEW:**

This bulletin involves reprogramming the SGW with the latest available software.

**MODELS:**

2020 (M7) Jeep Compass

**NOTE: This bulletin applies to vehicles within the following markets/countries: EMEA.**

**NOTE: This bulletin applies to vehicles built on or after January 14, 2020 (MDH 0114XX) and on or before April 27, 2020 (MDH 0427XX) equipped with 1.3L I4 Turbo Multiair DI Engine W/ESS (Sales Code EYF).**

**SYMPTOM/CONDITION:**

The SGW in these vehicles was flashed with a calibration intended to be paired with a different software version.

No symptoms will be observable to the customer. Diagnostic services will still work correctly (e.g. vehicle scan, DTC read, etc.). However, the vehicle security firewalls will be lacking.

Diagnostic Trouble Codes (DTCs) may be present. The technician will receive no notification indicating there is any problem with the SGW.

**DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair.

**REPAIR PROCEDURE:**

**NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.**

**NOTE: If this flash process is interrupted/aborted, the flash should be restarted.**

1. Does the SGW have the latest software already installed?
  - YES>>> This bulletin has been completed, use inspect LOP (18-19-20-99) to close the active RRT.
  - NO>>> Proceed to [Step 2](#).
2. Reprogram the SGW module with the latest available software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
3. Clear any DTCs that may have been set in any modules due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
18-19-20-99	Module, Security Gateway (SGW) - Inspect (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
18-19-20-9A	Module, Security Gateway (SGW) - Inspect and Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.

**NOTE: The expected completion time for the flash download portion of this procedure is approximately 2 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.**

**FAILURE CODE:**

**The dealer must choose which failure code to use depending on if this is a Rapid Response Transmittal (RRT) or Service Bulletin.**

- The "RF" failure code is required for essential module flash/reprogramming and can only be used after confirmation that the VIN is included on the RRT.
- The failure code "RF" (Required Flash) can no longer be used on Service Bulletin flashes. **The "RF" failure code must be used on an RRT.**
- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used. When utilizing this failure code, the 3C's must be supplied.

RF	Required Flash - RRT
CC	Customer Concern