



NUMBER: 23-018-20 REV. A

GROUP: 23 - Body

DATE: June 17, 2020

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This bulletin supersedes Service Bulletin 23-018-20, dated June 10, 2020, which should be removed from your files. All revisions are highlighted with **asterisks**** and include an inspection procedure and LOPs.**

SUBJECT:

Active Head Restraint (AHR) Inadvertent Deployment - X88 Warranty Extension

OVERVIEW:

This bulletin involves inspecting the sled bracket striker pin and possibly replacing a front seat AHR that has inadvertently deployed.

MODELS:

2014 - 2015 (WD) Dodge Durango

NOTE: This bulletin applies to vehicles within the following markets/countries: North America.

SYMPTOM/CONDITION:

Customers may comment on the following:

- The AHR is deployed on one or both front seats and will not reset.

DIAGNOSIS:

If the customer describes the symptom/condition listed, perform the Inspection Procedure.

NOTE: There will be no Diagnostic Trouble Codes (DTCs) with the symptom/condition listed.

1. **Verify the sled bracket striker pin is attached to the sled bracket (Fig. 1) and (Fig. 2) .




Fig. 1
Normal Deployed Position - AHR Can Be Reset

- 1 - Striker Pin Correctly Attached To The Sled Bracket
- 2 - Latch Pawls
- 3 - Sled
- 4 - Sled Bracket With Pin Attached
- 5 - Tilt Clip




Fig. 2
Deployed AHR Has Failed And Will Not Reset

- 1 - Sled Bracket Failed
- 2 - Striker Pin Fastened/Locked To Latch (**Will Not Reset**)

2. Is the striker pin attached to the sled bracket (Fig. 1) ?

- YES >>> This bulletin has been completed, use inspection LOP (23-20-48-98) to close the bulletin.
- NO >>> The striker pin is locked in the AHR latch (Fig. 2) . Proceed to Step 1 of the Repair Procedure.**

PARTS REQUIRED:

NOTE: Due to complexity of this warranty extension campaign, inspection must be performed and confirmation of failure must be completed before ordering parts.

Only order parts if the Active Head Restraint will not reset. The failure rate for this condition is extremely low.

Fig. 3

Qty.	Part No.	Description
(AR)	5PN14DX9AA	Leather Trim Black Front Active Head Restraint
(AR)	5PN14HL1AA	Leather Trim Black/Beige Front Active Head Restraint
(AR)	5RX96DX9AA	Cloth Trim Black Front Active Head Restraint
(AR)	5RX96HL1AA	Cloth Trim Black/Beige Front Active Head Restraint
(AR)	5RX56DX9AA	Cloth Trim Black Front Active Head Restraint
(AR)	5RX56GT5AA	Cloth Trim Black/Tan Front Active Head Restraint
(AR)	5RX56HL1AA	Cloth Trim Black/Beige Front Active Head Restraint
(AR)	5RX56JRRAA	Leather Trim Black/Red Front Active Head Restraint

NOTE: This service bulletin does not cover replacement of all AHRs. Only replace AHRs that have been deployed with broken and failed sled brackets.

REPAIR PROCEDURE:

1. Replace the AHR. Refer to the detailed procedures available in DealerCONNECT > Service Library> under: 23 - Body/Seats/Headrest, Front/Removal/Installation.

POLICY:

Vehicles included in this Service Bulletin have a warranty extension to a 10 Year/Unlimited Mileage from in-service date warranty period for this repair. See Warranty Bulletins: U.S. D-20-10, Canada SAB 2020-15 and Mexico BG-12-20, for details associated with the warranty extension.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
**23-20-48-98	Headrest/Active Headrest (Front Row) - Inspect One or Both (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
23-20-48-99	Headrest/Active Headrest (Front Row) - Replace One (0 - Introduction)	6 - Electrical and Body Systems	0.3 Hrs.
23-20-48-9A	Headrest/Active Headrest (Front Row) - Replace Both (0 - Introduction)	6 - Electrical and Body Systems	0.5 Hrs.**

FAILURE CODE:

ZZ	Service Action
----	----------------