



NUMBER: 07-001-20 REV. C

GROUP: 07 - Cooling

DATE: June 24, 2020

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This bulletin supersedes Service Bulletin 07-001-20 REV. B, dated May 27, 2020, which should be removed from your files. All revisions are highlighted with **asterisks**** and include additional market and clean date.**

SUBJECT:

Water Pump Inlet Tube Fastener Torque

OVERVIEW:

This bulletin involves checking the torque on the water pump inlet tube fasteners to possibly eliminate coolant leak at this location.

MODELS:

2018 - 2020 (JL) Jeep Wrangler

NOTE: This bulletin applies to vehicles within the following markets/countries: North America, APAC, EMEA and **LATAM****.**

NOTE: This bulletin applies to vehicles built before **June 24, 2020 (MDH 0624XX)**** equipped with a 2.0L I4 DOHC DI Turbo Engine W/ESS (Sales Code EC1) or 2.0L I4 DOHC DI Turbo Etorque Engine (Sales Code EC3).**

SYMPTOM/CONDITION:

The customer may describe either a coolant leak or the coolant level is low.

DIAGNOSIS:

If the customer describes the symptom/condition listed above, perform the Diagnosis Procedure.

1. Pressure check the coolant system. Refer to the detailed service procedures available in DealerCONNECT> Service Library under: Service Info>07 - Cooling / Diagnosis and Testing >Leak Testing>Pressure Tester Method.
2. Was coolant found to be leaking from the water pump inlet tube at the engine (Fig. 1) ?
 - YES>>> Proceed to [Step 1](#) of the Repair Procedure.
 - NO>>> Coolant was not leaking from this area. This Bulletin does not apply. Normal diagnosis should be performed.

REPAIR PROCEDURE:

1. Torque the water pump inlet tube fasteners to exactly 11 N·m (97 in. lbs) (Fig. 1) .




Fig. 1
Water Pump Inlet Tube Fasteners

- 1 - Water Pump Inlet Tube
2 - Fasteners

2. Pressure check the coolant system. Refer to the detailed service procedures available in DealerCONNECT>Service Library under: Service Info>07 - Cooling / Diagnosis and Testing >Leak Testing>Pressure Tester Method.
3. Is coolant still leaking from the water pump inlet tube at the engine (Fig. 1) ?
 - YES>>> Further diagnosis should be performed.
 - NO>>> This bulletin has been completed.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
07-62-04-90	Tube, Water Pump Inlet - Pressure Test Cooling System and Re-Torque Fasteners (2 - Skilled)	1 - Engine Repair and Performance	0.5 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------