

Symptom-based workshop manual

Service

134/18 ENU 1001

1

Symptom - Engine - Engine Problems and Engine Noise: Also Replacing Ignition Coils (SY 134/18)

Model Line: 911 (991)

Boxster (981)/Cayman (981)

Model Year: As of 2014 up to 2016

Subject: **Ignition coil**

Symptom: Customers complain about engine problems or loud engine noise. The following fault memory entries **may** also be stored:

- P0301 Misfire
- P0302 Misfire
- P0303 Misfire
- P0304 Misfire
- P0305 Misfire
- P0306 Misfire

Cause: Defective diodes in the ignition coil (for switch-on spark suppression) can cause engine problems.

Remedial Action:

In the event of a customer complaint, check the cylinder liner for damage. In the event of replacing the short block, install new coils at the same time. All ignition coils must be replaced in addition to the damaged components, see \Rightarrow Workshop Manual '282020 Removing and installing ignition coils'.

Date of Introduction:

Modified ignition coils have been used during production since 05 February 2016.

Parts Info:



Information

The following points must be observed in relation to the part numbers listed below and the relevant vehicle (depending on equipment):

- Part number indexes will increase over time. Before performing repairs, cross reference with PET (Porsche Spare Parts Catalog), for newer parts (higher index).
- PET must be checked to determine if additional components are needed.
- Particular/modified components, whose part numbers are listed accordingly, are required for the remedial action.

9A1.602.104.07 – **NEW** – \Rightarrow Ignition coil (required: all six)

Service 1001 ENU 134/18

Symptom-based workshop manual

Invoicing: The work involved is invoiced under the labor operation:

APOS	Labor operation	I No.
28202006	Removing and installing ignition coils	

For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	10010	Engine
Damage type (SA4)	1713	seized

References: ⇒ Workshop Manual '282020 Removing and installing ignition coils'

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.