



Technical Service Bulletin

19 Low coolant light is on, the coolant expansion tank display is incorrect

19 21 11 2061918/1 January 29, 2021.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All	2017 - 2021	All	Not Applicable

Condition

Customer states:

- The coolant warning lamp appears in the instrument cluster.

Workshop findings:

- When checking the coolant level visually on the coolant expansion tank the level is between minimum and maximum as it should be.

Technical Background

Due to the large coolant circuit capacity, there is significant fluctuation in the coolant level when the coolant cools down and heats up. If the coolant circuit is incorrectly filled or bled, this can lead to sporadic illumination of the low coolant level warning lamp.

Production Solution

Not applicable.

Service

When processing this concern, follow the points below:

- The coolant level in the coolant expansion tank must be adjusted/checked in cold conditions according to the Elsa repair manual.
- The connector (including pins and connector contacts) should be checked carefully.
- The contact surfaces of the pins and connector contacts must be free of impurities and damage.
- After disconnecting and reconnecting the connector, perform a key cycle and check if the concern returns again. If it does then continue with normal diagnosis outside of this TSB.



Technical Service Bulletin

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	1940		
Damage Code:	0040		
Labor Operations:	Check coolant expansion tank	1940 0199	30 TU
	Check coolant expansion tank	1094 0099	30 TU
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2061918/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (2061918/1) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.