



# Technical Service Bulletin

---

## 91 Parking assistance provides false warnings

91 21 64 2024323/7 January 25, 2021. Supersedes Technical Service Bulletin Group 91 number 19-88 dated September 12, 2019 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
All	2005 - 2022	All	Not Applicable

## Condition

REVISION HISTORY		
Revision	Date	Purpose
7	-	Revised header (Added MY21 - 22)
6	09/12/2019	Revised header (Corrected Elsa display issue) Revised <i>Service</i> (Added Tip)
5	07/26/2017	Revised header (Added model years) Revised <i>Technical Background</i> (Added QR codes) Revised <i>Warranty</i> (Added Claim Types and updated Labor Operation)

### Customer states one of the following:

- Parking aid sporadically warns of obstacles when none exist.
- Parking aid is inoperative or provides a constant warning.

## Technical Background

- Various parking aid sensor fitting issues.
- Environmental conditions.



# Technical Service Bulletin

---

Please review the informational video before attempting the repair procedure: <https://audi-external.kzoplatform.com:443/swf/player/342> (Figure 1).



*Figure 1. False parking system warnings.*

Please review the informational video before attempting the repair procedure: <https://audi-external.kzoplatform.com:443/swf/player/343> (Figure 2).



*Figure 2. Parking system malfunctions.*

## Production Solution

Not applicable.

## Service

Misaligned parking aid sensors or various vehicle mountings can cause parking aid malfunctions. This TSB provides tips for diagnosing parking aid systems.

1. Confirm there is no obvious obstructions due to aftermarket components, physical vehicle damage, excessive dirt/snow, or stickers.
2. Check the vehicle fault memory and proceed according to GFF.



# Technical Service Bulletin

---

- If GFF identifies a problem with a specific sensor, proceed with the test plan.
- If GFF does not identify a specific sensor, check MVBs in the master module for the parking aid sensors. Based on the vehicle, these can be found in the guided functions or OBD of module 09, 76 or A5.



**Tip:** Below is an example of module 76 MVB. When diagnosing the system you can check the response values for the sensors. Compare the sensor values to one another while moving a test object closer/further away, they should all respond similarly.

**MVBs for distance calculations** (255 = no obstruction). If an obstruction is identified but none exists, proceed to step 3.



**Tip:** Vehicles can be equipped with 4, 8 or 12 channel parking aid systems. Refer to Elsa for vehicle-specific information.

3. Check parking sensors (Figure 3) for obvious issues:

- Mechanical damage (stone chips, scratches).
- Dirt, ice, foreign bodies, and/or foil adhered to the sensor.
- Damage to the bumpers that may indicate an accident (or paint indicating a previous incident).



**Figure 3.** Stone chips causing sensor failure.



**Tip:** Exterior damage to the vehicle, including stone chips and scratches, is not covered by Audi Warranty. When painting sensors, the special painting instructions for parking sensors in the paint repair manual must be observed.

4. Check for non-Audi Genuine Accessories which can interfere with parking aid operation, including:

- Aftermarket towing bar.
- Aftermarket lowering kit.
- Aftermarket spoiler or air deflector.
- Aftermarket bumper.



# Technical Service Bulletin

---

5. For 8 and 12 channel systems, check the installation of the front license plate holder for:
  - Protrusion. The license plate and holder must fit on flat.
  - Bent corners. Any bent-open corners may cause false readings.
  - Correct fit. Oversized license plate holders or frames can obstruct parking aid sensors.
6. Pressure check for a tight fit and correct attachment of the parking sensors (Figure 4). If the sensor is not snug or feels loose, remove the bumper and reinstall the sensor.



**Figure 4.** A pressure check on a parking aid sensor.

7. Check that the decoupling ring is correctly seated (Figures 5 - 7). If the ring is folded or bulging, remove the bumper and reinstall the sensor.






# Technical Service Bulletin

---

**Figure 5.** A correctly seated decoupling ring.



**Figure 6.** An incorrectly seated decoupling ring (bulging).




**Figure 7.** An incorrectly seated decoupling ring (folded).




# Technical Service Bulletin

---


8. Verify that the sensor is centered inside of the mounting hole (Figures 8 - 9). If the sensor is mounted off-center, remove the bumper and reinstall the sensor.



**Figure 8.** A correctly centered parking aid sensor.



**Figure 9.** An off-center parking aid sensor.




# Technical Service Bulletin

---

9. Ensure the sensor sits flush with the bumper (Figures 10 - 11). If the sensor is recessed or bulging, remove the bumper and reinstall the sensor.



**Figure 10.** A correctly installed parking aid sensor.



**Figure 11.** A recessed parking aid sensor.

10. Re-evaluate the concern:
- If an issue was identified and the concern was remedied, proceed to step 15.
  - If no issues were identified and the concern cannot be duplicated, proceed to step 15.
  - If the concern still persists, continue to step 11.





# Technical Service Bulletin


---

11. Remove the bumper and check the connectors on the sensors, the socket box of the bumper, on the control module for parking assistance and on the sound generator of the parking assistance for:
- Corrosion.
  - Water ingress or water marks.
  - Bent-open pins.
  - Pushed-back pins.
  - The correct fit of plug seal.



**Tip:** If a specific sensor is identified by the diagnostic tester, proceed forward for that specific sensor only.

12. Check the cables in the bumper for damage and sufficient length (Figures 12 - 13). Cables that are too short can cause damage to the harness.
- If the cable is damaged, repair the cable using VAS Repair Kit 1978.
  - If the cable is too tight, correct the routing by moving the support clip so the cable is no longer under tension.




**Figure 12.** A correctly installed cable with sufficient length.






# Technical Service Bulletin

---



**Figure 13.** A sensor cable with insufficient length.

13. Check the connectors on the parking sensors and the socket box for correct installation (Figures 14 - 15). If the connectors are not installed properly, reinstall.




**Figure 14.** A correctly installed parking aid sensor connector.



# Technical Service Bulletin

---



**Figure 15.** A parking aid sensor connector that is not seated correctly.

14. Re-evaluate the concern:

- If an issue was identified and the concern was remedied, proceed to step 15.
- If the concern still persists, swap affected parking aid sensors or control modules until the issue is identified, remedy the concern, then proceed to step 15.

15. Various environmental factors can cause incorrect warnings. Notify the customer that the following may affect parking aid operation:


- High plants and curbs.
- Gravel paths, cobblestone paths, potholes, grates, and sharp bends in the road, slopes, driveways, or ramps.
- Water on the parking sensors.
- Ice or snow on the parking sensor or the bumper.
- Exhaust gases of the vehicle under certain weather conditions.
- Conflicting ultrasound sources (pneumatic brakes on trucks, animal alarms, parking aid systems of other vehicles, etc.).
- Fluorescent lighting.

## Warranty

Accounting for an incorrectly fitted license plate holder or for cleaning the sensors is not permitted under warranty.

For the potential remounting of parking assist sensor, replacing of the parking assist sensor bracket, or repairing system wiring:

<b>Claim Type:</b>	<ul style="list-style-type: none"><li>• 110 up to 48 Months/50,000 Miles.</li><li>• G10 for CPO Covered Vehicles – Verify Owner.</li><li>• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.</li></ul>
--------------------	---



# Technical Service Bulletin

<b>Service Number:</b>	9175		
<b>Damage Code:</b>	0010		
<b>Labor Operations:</b>	Remove and install the rear parking aid sensor	9175 XXXX	See SRT with associated operations
	Remove and install the front parking aid sensor	9175 XXXX	See SRT with associated operations
	Remove and install the rear bumper	6369 19XX	See SRT with associated operations
	Remove and install the front bumper	6329 19XX	See SRT with associated operations
	Lane Change Assist recalibration (if necessary)	9635 XXXX	See SRT with associated operations
	Repair wiring harness	9175 4199	Max 30 TU
<b>Diagnostic Time:</b>	GFF	0150 0000	Time stated on diagnostic protocol (Max 30 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
<b>Claim Comment:</b>	As per TSB #2024323/7		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

## Additional Information

All parts and service references provided in this TSB (2024323) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.



# Technical Service Bulletin

---

©2021 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.