Technical Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



Subject:

LIGHT RESISTANCE AND/OR UNUSUAL NOISE WHEN TURNING STEERING WHEEL LEFT OR RIGHT	Bulletin No.: 06-001/21
	Last Issued: 01/20/2021

BULLETIN NOTES

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted in Red text.

Previous TSBs:	Date(s) Issued:
06-001/20	02/05/20
06-005/19	7/22/2019
06-002/18	09/14/2018

APPLICABLE MODEL(S)/VINS

US Spec.:

2016-2020 CX-3 vehicles with VINs lower than JM1 DK**** ** 462318 (Produced before Oct. 11, 2019)

Mexico Spec.:

2016-2018 CX-3 vehicles with VINs lower than JM1 DK**** ** 462318 (Produced before Oct. 11, 2019) 2016-2020 Mazda2 vehicles (without Lane-keep assist)

NOTE: Mazda2 equipped with Lane-keep assist system is not applicable to this service bulletin due to a difference of part supplier.

DESCRIPTION

Some vehicles may exhibit a light resistance and/or an unusual noise when turning the steering wheel in either direction. This concern may be caused by insufficient lubrication of the gear due to uneven and deteriorated grease. To eliminate this concern, the production process for the steering shaft has been further modified.

Customers having this concern should have their vehicle repaired using the following repair procedure.

Page 1 of 5

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

REPAIR PROCEDURE

- 1. Verify the customer concern.
- 2. Inspect the label on the bottom of the steering motor.
- 3. Record the 2nd, 3rd and 4th digits of the lot number.

NOTE: The red circle shown below is the steering motor part number.



Example: The lot number in the sample part below is "CE62116". The 2nd, 3rd and 4th digits are "E62".



Page 2 of 5

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

© 2021 Mazda North American Operations, U.S.A.

01/20/2021 12:27 PM tlawrenc

4. Using the three (3) digits found from the lot number inspection, determine the necessary action using the table below.

2nd, 3rd and 4th Digits of Lot Number	Necessary Action
D**, E**, F**, G**, H** or J**	Proceed to Step 5 of this bulletin
K1*-K7*, K81-K89, K8A-K8T	and replace the steering shaft with a modified part.
K8U, K8V, K8W, K8X, K8Y, K9*, KA*, KB* or KC*	This bulletin does not apply. The steering shaft
L**	is already modified, do not replace it. Refer to MGSS online for further diagnosis.

* can be any number or letter.

Examples:

- E62 = Proceed to Step 5 of this bulletin and replace the steering shaft with a modified part.
- **KCA** = This bulletin does not apply. The steering shaft is already modified, do not replace it. Refer to MGSS online for further diagnosis.

5. Replace the steering shaft with a modified one according to the instructions on MGSS online:

- CX-3: (STEERING WHEEL AND COLUMN REMOVAL/INSTALLATION)
- Mazda2: (STEERING WHEEL AND COLUMN REMOVAL/INSTALLATION)

6. Verify the repair.

Page 3 of 5

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

PARTS INFORMATION

Parts Number Description Qty. Notes DA7H-32-100N Shaft, Steering 1 2016-2017 Mazda2 1 2018-2019 Mazda2 DG7L-32-100F Shaft, Steering DHM1-32-100A Shaft, Steering 1 2020 Mazda2 DB4G-32-100K Shaft, Steering 1 2016-2017 CX-3 DH1E-32-100D 2018-2019 CX-3 Shaft, Steering 1 DM6F-32-100C Shaft, Steering 1 2020 CX-3 B455-32-099B Shaft, Bolt 1 [R] D10J-32-099 Shaft, Bolt 1 [R] 1 [R] (*1) 9YA0-11-003A Bolt 2 [R] (*2) KA01-66-154 Bolt, Set

NOTE: Mazda2 equipped with Lane-keep assist system is not applicable since the part supplier is different.

NOTE 1: The steering shaft part numbers have not been changed by this modification. Refer to the lot number inspection above to determine if the steering shaft is a modified part or not.
NOTE 2: Select applicable steering shaft and replacement parts according to the GEPC.
[R] = Replace

[R] Parts (*1) (*2) Location:

Page 4 of 5

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical----including photocopying and recording and the use of any kind of information storage and retrieval system ----without permission in writing.

Bolt at Steering Wheel	Bolt Set at Start Stop Unit
R	R

WARRANTY INFORMATION

NOTE:

• This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.

- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	31
Damage Code	91
Part Number Main Cause	****-32-100*
Quantity	1
Operation Number / Labor Hours:	XXP66XRX / 0.9 Hr. (includes steering shaft unit, RR)

Page 5 of 5

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.