

Service Alert

Mazda North American Operations
Irvine, CA 92618-2922

**Subject:**

M-MDS (MDARS) SHOWS FRONT RADAR SENSOR DYNAMIC AIMING IS INCOMPLETE

Service Alert No.: SA-010/21

Last Issued: 01/29/2021

BULLETIN NOTES

This service alert supersedes the previously issued service alert listed below. The changes are noted in Red text.

Previous Service Alert:	Date(s) Issued:
SA-050/20	05/05/20
SA-009/19	11/17/19 and 05/13/19

APPLICABLE MODEL(S)/VINS


2019-**2021** Mazda3

2020-**2021** CX-30

DESCRIPTION

Some vehicles may experience M-MDS (MDARS) showing the front radar dynamic aiming is incomplete. This may be caused by:

- Faulty front radar sensor software logic (MDARS showing the front radar dynamic aiming is incomplete although the procedure is completed).
- Front radar sensor out of alignment due to vehicle accident.**



Page 1 of 7

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

REPAIR PROCEDURE


Perform the appropriate Repair Procedure according to the table if M-MDS (MDARS) is showing the front radar sensor dynamic aiming is incomplete.

APPLICABLE MODEL(S)/VINS	Repair Procedure
2019-2020 Mazda3 (Mexico built) with VINS starting with 3MZ (produced before September 29, 2020) 2019-2020 Mazda3 (Japan built) with VINS starting with JM1 (produced before April 20, 2020) 2020-2021 CX-30 (produced before September 29, 2020)	Repair Procedure A
2021 Mazda3 (Mexico built) with VINS starting with 3MZ (produced after September 29, 2020) 2020-2021 Mazda3 (Japan built) with VINS starting with JM1 (produced after April 20, 2020) 2021 CX-30 (produced after September 29, 2020)	Repair Procedure B

Repair Procedure A

1. Check for a "Front Radar Malfunction. Drive Safely/Safety and Driver Support Systems Partially Disabled" warning message and warning light ON?

Is the warning message displayed and warning light ON?



- **Yes:** Go to step 3.
- **No:** Go to step 2.

2. Erase DTC's. The front radar dynamic aiming is completed. NO further action is needed.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

3. Check if any DTCs are stored.

Are C1A67:54 (Front radar sensor aiming adjustment not implemented) and C1A67:76 (Front radar sensor aiming error) stored?

- **Yes:** Go to next step.
- **No:** This service information does not apply. Go to MGSS for normal diagnosis.


4. Inspect Front Radar Sensor alignment. Go to M-MDS (MDARS).

a. Datalogger

b. New Setup

c. ECU - FR

d. Select PIDs
Horizontal deviation: FR-AIM_ANG_HORZ_DYN
Vertical deviation: FR-AIM_ANG_VERT_DYN
e. Select Start



Horizontal and Vertical deviation specification: Lower than 4.2 degrees
NOTE: If either of the PIDs exceeds 4 deg, front radar sensor dynamic aiming will fail.

NOT Correct: Horizontal or Vertical deviation is out of specification

Go to next step.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Correct: Horizontal and Vertical deviation is within specification


Repeat front radar sensor dynamic aiming

- Mazda3 - [FRONT RADAR SENSOR AIMING](#)
- CX-30 - [FRONT RADAR SENSOR AIMING](#)



5. Adjust the Front Radar Sensor alignment.

- AIM_ANG_VERT_DYN is between +4.0 and +4.5deg : Add one 0.5mm thick washer at A.
- AIM_ANG_VERT_DYN is between +4.6 and +5.1deg : Add two 0.5mm thick washers at A.
- AIM_ANG_VERT_DYN is between -4.0 and -4.5deg : Add one 0.5mm thick washer at B.
- AIM_ANG_VERT_DYN is between -4.6 and -5.1deg : Add two 0.5mm thick washers at B.
- AIM_ANG_HORZ_DYN is between +4.0 and +4.5deg : Add one 0.5mm thick washer at C.
- AIM_ANG_HORZ_DYN is between -4.0 and -4.5deg : Add one 0.5mm thick washer on the both A and B.



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

6. Repeat front radar sensor dynamic aiming.

- Mazda3 - [FRONT RADAR SENSOR AIMING](#)
- CX-30 - [FRONT RADAR SENSOR AIMING](#)

NOTE:

- If the “Front Radar Malfunction. Drive Safely/Safety and Driver Support Systems Partially Disabled” warning message and warning light are no longer displayed, erase DTC's. The front radar dynamic aiming is completed. NO further action is needed.
- If the front radar sensor dynamic aiming fails after following MGSS instructions, contact Hotline for latest repair information.

Repair Procedure B

1. Check if any DTCs are stored.

Are C1A67:54 (Front radar sensor aiming adjustment not implemented) and C1A67:76 (Front radar sensor aiming error) stored?

- **Yes:** Go to next step.
- **No:** This service information does not apply. Go to MGSS for normal diagnosis.


2. Inspect Front Radar Sensor alignment. Go to M-MDS (MDARS).

a. Datalogger

b. New Setup



c. ECU - FR

d. Select PIDs
Horizontal deviation: FR-AIM_ANG_HORZ_DYN
Vertical deviation: FR-AIM_ANG_VERT_DYN
Select Start



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by “do-it-yourselfers.” Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical—including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.


Horizontal and Vertical deviation specification: Lower than 4.2 degrees **NOTE:** If either of PIDs exceeds 4 deg, front radar sensor dynamic aiming will fail.

<p>NOT Correct: Horizontal or Vertical deviation is out of specification.</p> <p>Go to next step.</p>	
<p>Correct: Horizontal and Vertical deviation is within specification.</p> <p>Repeat front radar sensor dynamic aiming.</p> <ul style="list-style-type: none"> • Mazda3 - FRONT RADAR SENSOR AIMING • CX-30 - FRONT RADAR SENSOR AIMING 	

3. Adjust the Front Radar Sensor alignment.

- AIM_ANG_VERT_DYN is between +4.0 and +4.5deg : Add one 0.5mm thick washer at A.
- AIM_ANG_VERT_DYN is between +4.6 and +5.1deg : Add two 0.5mm thick washers at A.
- AIM_ANG_VERT_DYN is between -4.0 and -4.5deg : Add one 0.5mm thick washer at B.
- AIM_ANG_VERT_DYN is between -4.6 and -5.1deg : Add two 0.5mm thick washers at B.
- AIM_ANG_HORZ_DYN is between +4.0 and +4.5deg : Add one 0.5mm thick washer at C.
- AIM_ANG_HORZ_DYN is between -4.0 and -4.5deg : Add one 0.5mm thick washer on the both A and B.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



4. Repeat front radar sensor dynamic aiming.

- Mazda3 - [FRONT RADAR SENSOR AIMING](#)
- CX-30 - [FRONT RADAR SENSOR AIMING](#)

NOTE:

- If the front radar sensor dynamic aiming completes, erase DTC's. The front radar dynamic aiming is completed.
- If the front radar sensor dynamic aiming fails after following MGSS instructions, contact Hotline for latest repair information.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.