
Y1A Taycan SiriusXM Not Available (Greyed Out)

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Taycan	2021	Y1A	N/A	N/A

Revision History

Revision	Release Date	Changes
0	February 12, 2021	Original document

Condition

The customer reports SiriusXM is not available as a source in the PCM. The option for SiriusXM is greyed out. Dealers often observe this failure early in the service life of the vehicle, perhaps right after PDI or when activating satellite radio service or Connect service.

Technical Background

This is not a SiriusXM service issue nor is it a Connect services issue. The user interface within the PCM screen does not allow the PCM to confirm SiriusXM service is available. This presents a "deadlock" condition. The workaround below allows for a one-time confirmation. This confirmation should permanently undo the deadlock.

Service Information

If the vehicle has the condition described above, follow these steps:

1. Press the Joker-key (‘◆’ button) on the steering wheel. This will allow you to assign a function to the Joker-key. A popup should appear on the PCM center display.
2. Press the button labeled “change button assignment.”
3. Choose “steering wheel button.”
4. Choose “change source.”
5. Go to Media on the PCM screen.
6. Change the source to SiriusXM via the Joker-key on steering wheel.

Confirm the source is available and no longer greyed out.

Search Items

Taycan, SXM, XM, satellite, SDARS, PCM6

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.
