

SSM 49558 - 2021 F-Super Duty - 10R140 Automatic Transmission – Harsh Engagement/Harsh Shift/Delayed Shift With Or Without DTCs

Some 2021 F-Super Duty vehicles, with 5,000 miles (8,000 km) or less may exhibit harsh or delayed engagement/shift concerns with or without transmission diagnostic trouble codes (DTC) in the powertrain control module (PCM) or the transmission control module (TCM). Most concerns at low mileage may be addressed with the accelerated main control break-in routine. Refer to Workshop Manual, Section 307-01 Diagnosis and Testing, DTC Chart and/or Diagnosis By Symptom to identify the clutch(s) to be cycled. This routine cycles the shift solenoids and clutch control valves to remove contamination that may be sticking the valves and must be performed along with an adaptive learning drive cycle before attempting internal service. For claiming, use causal part 7A100 and applicable labor operations in Section 7 of the Service Labor Time Standards Manual.

APPLICABLE VEHICLES
2021 TRUCK: FE P558N SUPER DUTY