Subject: Engineering Information – Service Airbag Lamp Illuminated on Driver Information Center (DIC), DTCs B15DF and/or

B15E3 Set

Attention: Proceed with this EI ONLY if the customer has commented about this concern AND the PIE number is listed in the

Global Warranty Management / Investigate History link (GWM/IVH). If the customer has not commented about this condition or the El does not show in GWM/IVH, disregard the PIE and proceed with diagnostics found in published service information. THIS IS NOT A RECALL — refer to latest version of Service Bulletin 04-00-89-053 for more details

on the use of Engineering Information bulletins.

This EI has been revised to update Steps under the Correction. Please discard PIE0606.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Cadillac	CT4	2020	2021	_	_	_	_

Involved Region or Country	North America	
Condition	Important: If the customer did not bring their vehicle in for this concern, DO NOT proceed with this EI. Some customers may comment that the service airbag lamp is illuminated on the driver information center (DIC). Technicians may find one or both of the following DTCs set: B15DF: Co-Driver Thorax Module High Control B15E3: Driver Thorax Module High Control	
Cause	GM Engineering is attempting to determine the root cause of the above condition. Engineering has a need to gather information on vehicles PRIOR to repair that may exhibit this condition. As a result, this information will be used to "root cause" the customer's concern and develop/validate a field fix.	

Correction

If you encounter a vehicle with the above concern, perform the following steps and contact the engineer listed below with your findings.

- 1. Verify that the vehicle has DTCs B15DF and/or B15E3 active or in history.
- 2. Contact the Engineer (the engineer may have additional directions other than described below).
- 3. Connect the MDI tool and monitor resistance loop for the seats (loop 11 for driver side DTC B15E3, loop 12 for passenger side B15DF).

Note: Watch for resistance spikes up and down and monitor the resistance through all proceeding steps (normal resistance is ~2.5 ohms).

- 3.1. If no spikes are present, sit in the seat and move around (press into seat back and bolster) while monitoring resistance for jumps.
- 4. Move the seat all the way rearward and all the way up while monitoring for any changes in resistance.
- 5. Disconnect the seat harness from body harness, resistance should spike as there is an open circuit.
- 6. Reconnect the seat harness to the body harness.

Note: If resistance is bouncing, call the engineer listed BEFORE proceeding.

- 7. With the MDI tool still plugged in and actively monitoring the resistance for given loop, unzip the seat trim and reveal the seat airbag/wire harness connection without disturbing as little as possible.
- 8. Take a picture of the connection without disturbing the area and visually verify that the connector is properly and fully connected.
- **9.** While monitoring resistance for spikes, tap on the harness.
 - 9.1. If spikes occur, pause, and tap again. If spikes replicate, move to step 9.2 below. Otherwise move to step 10.
 - **9.2.** Cut the harness as close to the seat back as possible.
 - **9.3.** Attach the ohm meter to the connector side of the harness and take the reading as you tap on the harness. If spiking occurs, remove the airbag **WITHOUT** disconnecting/disturbing the connector and send the airbag with connector to the Warranty Parts Center (WPC).
- 10. Tap on the connector (actively monitoring resistance).
 - 10.1. If spikes occur, pause, and tap again. If spikes replicate, move to step 10.2 below.
 - 10.2. Cut the harness as close to the seat back as possible.
 - 10.3. Remove the airbag WITHOUT disconnecting/disturbing the connector and send the airbag with connector to the WPC.

Contact Information

The Contact Information has been redacted.

Please include the following information if leaving a message:

- Technician name
- Dealer name and phone number
- Complete VIN and repair order (R.O) number

On the repair order, document the date and time the call was placed (even if the engineer was not reached).

If engineering is unable to return the call within one hour, proceed with diagnosis and repair based on information found in SI.

Warranty Information

If engineer was contacted or required information was provided, use:

Labor Operation	Description	Labor Time			
6486078*	Engineering Information - Service Airbag Lamp Illuminated On (DIC), Multiple DTCs Set	1.0 hr			
*This is a unique labor operation for bulletin use only.					

Version	2
Modified	Released December 14, 2020 January 13, 2021 – Updated Steps under the Correction