



01-21-06 - Update Programming Engine/Motor Control Module -J623-, Release date: 3/3/2021 Various Fault Codes Stored

Condition

| Applicable Vehicles | | | | | |
|---------------------|------|-----------------------|-------------|-------------------|--------------|
| Model(s) | Year | Eng. Code | Trans. Code | VIN Range From | VIN Range To |
| Jetta | 2020 | 1.4T (DGXA / DJXA) | All | All | All |

| Revision Table | | | |
|-----------------|----------------|----------------|-----------------------|
| Instance Number | Published Date | Version Number | Reason For Update |
| 2062519/1 | 3/3/21 | 01-21-06 | Original publication. |



This software update also includes modification for: P00FE, P0133, P2279, P0135, P0410, P0491 and P268A DTCs.

One or more of the following fault codes may be stored in the Engine/Motor Control Module -*J623*- Fault Memory:

| DTC | Description |
|-------|---|
| P00FE | EVAP System Purge Vapor Line Restricted/Blocked |
| P0133 | O2 Sensor Circ.,Bank1-Sensor1 Slow Response |
| P2279 | Intake Air System Leak |
| P0135 | O2 Sensor Heater Circ.,Bank1-Sensor1 Malfunction |
| P0410 | Sec.Air Inj.Sys. Malfunction |
| P0491 | Secondary Air Injection System (Bank 1) insufficient flow |
| P268A | Fuel Injector Calibration Not Learned/Programmed |

Technical Service Bulletin

Transaction No:

2062519/1



01-21-06 - Update Programming Engine/Motor Control Module -J623-, Release date: 3/3/2021 Various Fault Codes Stored



DO NOT diagnose or replace components due to P00FE, P0133, P2279, P0135, P0410, P0491 and P268A faults **before** performing the update function as explained in this bulletin.

Technical Background

Updated programming of the Engine/Motor Control Module -*J623*- software is based on most recent engineering experiences and makes this knowledge available for the monitoring strategies.

Production Solution

Improved Engine/Motor Control Module -J623- software.

Service

Update-Programming Procedure:

<u>Critical Warning</u>: The Midtronics battery charger <u>must</u> be connected to the vehicle battery for the duration of the programming, to ensure the battery state of charge remains above 12.5 volts during the update process. If the battery drops below 12.5 volts, the programming could fail which may result in damage to the control module. Control modules damaged by inadequate voltage will not be covered under the warranty policy. The technician should verify the vehicle voltage prior to starting the update process, and should monitor the voltage for the duration of the update.



WARNING:

Radiator Fan(s) may cycle ON high speed during the Update Process! There is a risk that personal injury may result if contact is made with spinning fan blades.

Keep hands and all objects away from Radiator Fan(s) during Update Process!



Note:

Prior to launching the ODIS Service diagnostic applications and starting control module update process, confirm tester screen saver and power settings in accordance with Diagnostic Device Hardware & Windows® - VHW-20-02 Change Power Options After Windows®10 Upgrade. Failure to do so may result in the tester entering power save mode during data transfer, and subsequent control module failure. When using a VAS 6150/X or 6160/X tester in conjunction with a VAS 6154 wireless transmitter head for a flash procedure, connect a USB cable between the transmitter head and the tester. Failure to do so may lead to errors during the flash procedure.

VAS tools must only be used with their power adapters plugged in. Under no circumstances should they be used on battery power alone during the programming procedure.

Technical Service Bulletin

Transaction No: 2062519/1



01-21-06 - Update Programming Engine/Motor Control Module -J623-, Release date: 3/3/2021 Various Fault Codes Stored



To Update-Programming using Software Version Management (SVM), **review and follow** instructions in **Technical Bulletin Instance 2014603** "Software Version Management".

The SVM process must be completed in its entirety so the database receives the update confirmation response. A warranty claim may not be reimbursed if there is no confirmation response to support the claim or action is carried out that is not explicitly stated in the Technical Bulletin.

• Update the Engine/Motor Control Module -J623- using the SVM Unit code as listed in the table below:

| Model | Engine | Old Software Part No. | Old Software Version | New Software Part No. | New Software Version (or higher) | SVM Unit Code |
|-------|--------------------------------|--------------------------|------------------------------|--------------------------|---|------------------|
| Jetta | Jetta 1.4T (DGXA / DJXA) | 04E 906 024 AR | Z843 7257 9509 9911 | 04E 906 024 AR | 9970 | 45CF |
| | | 04E 906 024 AS | Z843 7258 9510 9912 | 04E 906 024 AS | | |
| | | 04E 906 024 AT | Z843 7259 9511 9913 | 04E 906 024 AT | | |

The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software.



The procedure can be found in GFF under Functions/ Component Selection, Software Version Management, Adapting Software.

Ensure attached ECM/TCM Tuning Form has been completed and signed by customer as required in SVM Technical Bulletin Instance 2014603.



01-21-06 - Update Programming Engine/Motor Control Module -J623-, Release date: Various Fault Codes Stored

3/3/2021

Warranty

| Model(s) | Yea | ar(s) | Eng. Code(s) | Trans. Code(s) | VIN Range From | | VIN Range To | |
|--|-------------|----------------|--------------------------------------|------------------------|--|-------------------|--------------|--|
| Jetta | 2020 | | 1.4T | All | All | | All | |
| | | | (DGXA / DJXA) | Coding | | | | |
| Claim Type: | Us | se applica | able Claim Type | | | | | |
| Service Number: | | Damage Code | нѕт | | Damage Location (Depends on Service No.) | | | |
| 2470 | | | 0039 | - | Use applicable whe indicated in Elsa (L/l | | • | |
| Parts Manufacturer | | er | Je | etta | | 3ME ²⁾ | | |
| Labor Operation 3): Charge Battery | | | ry | 27068950 = 10 TU | J | | | |
| Labor Operation 3): Update Programming Control Module | | | amming ECM | 24705599 = 50 TU | J | | | |
| Causal Part: | | | | 27068950 | | | | |
| | | | Diagnos | tic Time ⁴⁾ | | | | |
| GFF Time expenditure | | | 01500000 = Actual GFF print out | | | NO | | |
| Road Test | | | 01210002 = 00 TU 01210004 = 10 TU | | | YES | | |
| | | | 01320000 = 00 T | - 00 TU max. | | | NO | |
| Claim Comment | t: Input "A | As per Te | chnical Bulletin 2 | 062519" in commer | nt section | of Warr | anty Claim. | |

Technical Service Bulletin

Transaction No:

2062519/1



01-21-06 - Update Programming Engine/Motor Control Module -J623-, Release date: 3/3/2021 Various Fault Codes Stored

3) Labor Time Units (TUs) are subject to change with ELSA updates.

Required Parts and Tools

| Tool Description | Tool No: | |
|-----------------------------------|--|--|
| Midtronics Battery Tester/Charger | GRX3000VAS | |
| | or | |
| | MTRMSP0702 battery maintainer/charger | |
| VAS Diagnostic Tool | VAS 6150/X & VAS 6160/X and | |
| | ODIS Service with current online updates | |

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.

⁴⁾ Documentation required per Warranty Policies and Procedures Manual.



OWNER INFORMATION ABOUT CONTROL MODULE TUNING* ACKNOWLEDGEMENT AND AUTHORIZATION FOR REPROGRAMMING (REFLASHING) OF CONTROL MODULE(S)

| *) "TUNING" is described as the addition of or modification of any convolkswagen vehicle to perform outside the normal parameters and specific Volkswagen Group of America / Volkswagen Group Canada. | • |
|---|---------------------------|
| voikswageri Group of America / voikswageri Group Canada. | |
| Date: | |
| Dealer Number: | |
| Vehicle Identification Number: | |
| Repair Order Number: | |
| | Dealer stamp |
| I, owner or driver of the above identified | Volkswagen, confirm: |
| Tuning" as described above (especially power increasing modificement on my vehicle. | cations) has NOT been |
| "Tuning" as described above has been performed on my vehicle and twere modified or installed: | the following components |
| TUNING was performed by (Please provide Company name and telephor to contact them): | ne number, if you wish us |
| I understand that if my Control Module is determined to have been tuned the tuning of the Control Module (including adverse emissions consequently VWGoA / VGC warranties. | |
| I am permitting an authorized Volkswagen Dealer to reflash (update) my doing so, I understand that this process will automatically overwrite (delete any tuning program that was previously installed on the Control M vehicle. | estroy) and permanently |
| By signing below, I fully acknowledge and understand that the tuning propand VWGoA / VGC, will not be liable in any way for the loss of tuning date | • |
| Signature | of Customer |