



26-19-01 - AdBlue® Warning and or MIL ON - Ad Blue® Leakage at **Reductant Injector** 

Release date:

3/18/2021

# **Condition**

Applicable Vehicles					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta	2015	2.0L TDI (CVCA)	All	AJ_FM200001	AJ_FM296633
Jetta	2015	2.0L TDI (CVCA)	All	AJ_FM350050	AJ_FM358215
Beetle	2015	2.0L TDI (CVCA)	All	AT_FM600001	AT_FM639473
Beetle Convertible	2015	2.0L TDI (CVCA)	All	AT_FM800001	AT_FM811301
Passat	2015	2.0L TDI (CVCA)	All	A3_FC000001	A3_FC064622
Golf	2015	2.0L TDI (CRUA)	All	AU_FM000001	AU_FM069384
Golf SportWagen	2015	2.0L TDI (CRUA)	All	AU_FM500001	AU_FM501189

Revision Table					
Instance Number	Published Date	Version Number	Reason For Update		
2039436/12	3/18/21	26-19-01	Update warranty table due to SAGA updates.		
2039436/11	1/11/21	26-19-01	Update part number suffix.		
2039436/1	1/21/15	V261501	Original publication.		



26-19-01 - AdBlue® Warning and or MIL ON - Ad Blue® Leakage at Reductant Injector

Release date:

3/18/2021

The following fault code may also be stored in the ECM Fault Memory:

DTC	Description
P20E8	Reductant Pressure Too Low

### **Technical Background**

Welding process issues of the reductant line connector to the supply line may cause AdBlue® leakage at the reductant injector.

#### **Production Solution**

Improved parts implemented into production.

#### **Service**

Inspect the connection of the reductant supply line connector at the reductant injector in the engine compartment. If white crystalized (dried) AdBlue® is found at the reductant injector (see Figure 1 & 2), it will be necessary to replace the reductant supply line.





Figure 1 Figure 2

- Thoroughly clean the area of the reductant supply line connection with water to remove the crystalized AdBlue®.
- · Replace the reductant supply line.
- Refill reductant agent as required per part table quantity.



It is not necessary to replace the reductant injector.



26-19-01 - AdBlue® Warning and or MIL ON - Ad Blue® Leakage at Reductant Injector

Release date:

3/18/2021

# Warranty

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual <sup>1)</sup>

and Procedures Manual 1)							
Model(s)	Yea	ır(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From		VIN Range To
Jetta	20	15	2.0L TDI (CVCA)	All	AJ_FM200001		AJ_FM296633
Jetta	20	15	2.0L TDI (CVCA)	All	AJ_F	FM350050	AJ_FM358215
Beetle	20	15	2.0L TDI (CVCA)	All	AT_FM600001		AT_FM639473
Beetle Convertible	20	15	2.0L TDI (CVCA)	All	AT_FM800001		AT_FM811301
Passat	20	15	2.0L TDI (CVCA)	All	A3_I	FC000001	A3_FC064622
Golf	20	15	2.0L TDI (CRUA)	All	AU_FM000001 AU_FM		AU_FM069384
Golf SportWagen	20	15	2.0L TDI (CRUA)	All	AU_FM500001		AU_FM501189
SAGA Coding							
Claim Type:	m Type: Use applicable Claim Type 1)						
Service Number:		Damage Code	HST		Damage Location (Depends on Service No.)		
2684		0050					
Parts Manufacturer		Passat		WWO <sup>2)</sup>			
		Golf, Golf Spor Beetle, Beetl	tWagon, Jetta, 3ME <sup>2)</sup>		)		



26-19-01 - AdBlue® Warning and or MIL ON - Ad Blue® Leakage at Reductant Injector

Release date:

**Transaction** 

No:

3/18/2021

r -					
	Passat				
Labor Operation 3): Reductan Line Remove + Install	t Agent Supply	26841905 = see Elsa for latest time units.			
<b>Labor Operation</b> 3): Clean Up Ad Blue	of crystallized	26842999 = 30 TU			
<b>Labor Operation</b> 3): Reductan + Add	t Agent Inspect	26883500 = see Elsa for latest time units.			
Jetta, G	olf, Golf SportW	/agen, Beetle, Be	eetle Convertible		
<b>Labor Operation</b> 3): Reductan	t Agent Inspect	26883500 = see Elsa for latest time units.			
Labor Operation 3): Clean Up Ad Blue	of crystallized	26842999 = 30 TU			
Labor Operation 3): Upper En	gine Cover	10831900 = see Elsa for latest time units.			
Labor Operation 3): Front Red Supply Line Remove + Install	luctant Agent	26841952 = see Elsa for latest time units.			
Causal Part: Supply Line for R	Reduction Agent	See Parts Table	Below		
Diagnostic Time 4)					
GFF Time expenditure	01500000 = Actual GFF print out		YES		
Road Test	01210002 = 00 TU 01210004 = 10 TU		YES		
Technical Diagnosis:	01320000 = 00	TU max.	NO		

Claim Comment: Input "As per Technical Bulletin 2039436" in comment section of Warranty Claim.

<sup>1)</sup> Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only

<sup>&</sup>lt;sup>2)</sup> Code per warranty vendor code policy.

<sup>&</sup>lt;sup>3)</sup> Labor Time Units (TUs) are subject to change with ELSA updates.

<sup>&</sup>lt;sup>4)</sup> Documentation required per Warranty Policies and Procedures Manual.

#### **Technical Service Bulletin**



2039436/12



26-19-01 - AdBlue® Warning and or MIL ON - Ad Blue® Leakage at Reductant Injector

Release date:

3/18/2021

# **Required Parts and Tools**

Part Number	Description	
561 131 984 *	Supply Line for Reduction Agent	
5Q0 131 984 *	Supply Line for Reduction Agent	
5C0 131 984 E	Supply Line for Reduction Agent	
G 052 910 A2	AdBlue® Max. Qty. = 2.00	
	561 131 984 * 5Q0 131 984 * 5C0 131 984 E	

Part numbers are accurate at time of publication. Always refer to ETKA for the latest part information.

Tool Description	Tool No:	
Midtronics Battery Tester/Charger	InCharge 940 (INC-940)	
	or	
	GRX3000VAS	
VAS Diagnostic Tool	VAS 6150/X & VAS 6160/X with	
	ODIS Service with: current online updates	

### **Additional Information**

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.