

This bulletin provides the procedure to update the software logic of the Engine Control Module (ECM) system on some 2022MY Stinger (CK) vehicles equipped with the 3.3L GDI engine and 8AT transmission, produced from January 15, 2021 through February 5, 2021, to improve the variable sound of the muffler in "sport mode". The exhaust sound in "sport mode" was not properly mapped exhibiting a low and poor sound, especially under "low to moderate" load. Apply the improved logic to the ECM system using the KDS ECU Upgrade function as described in this bulletin. For confirmation that the latest reflash has been applied to a vehicle you are working on, verify the ROM ID using the table on page 3 of this bulletin.



Kia Diagnostic System (KDS)

***** NOTICE

A Service Action is a repair program without customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DPSM approval.

Repair status for a VIN is provided on WebDCS (Service \rightarrow Warranty Coverage \rightarrow Warranty Coverage Inquiry \rightarrow Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs \rightarrow Not Completed Recall \rightarrow Recall VIN \rightarrow Select Report), which includes a list of affected vehicles.

This issue number is SA468.

Printed TSB copy is for reference only; information may be updated at any time. Always refer to KGIS for the latest information.

Circulate To:	🛛 General Manager	Service Manager	🛛 Parts Manager
Service Advisor	s 🛛 🖾 Technicians	🗵 Body Shop Manager	Fleet Repair

SERVICE ACTION: VARIABLE MUFFLER OPERATION LOGIC IMPROVEMENT (SA468)

ECU Upgrade Procedure:

To correct this condition, the ECU should be reprogrammed using the KDS download, as described in this bulletin.

Upgrade Event Name

542. CK PE 3.3TGDI 8AT VARIABLE MUFFLER SOUND LOGIC IMPROVEMENT

***** NOTICE

- Confirm a <u>fully charged battery</u> with 12.3 volts or higher is necessary or the use of a fully charged jump starter box connected to the battery.
- Ensure the KDS GDS is sufficiently charged at 60% or higher prior to reflash.
- All ECU upgrades must be done with the ignition key in the 'ON' position unless otherwise stated.
- Be careful not to disconnect the VCI-II connected to the vehicle during the ECU upgrade procedure.
- DO NOT start the engine during ECU upgrade.
- DO NOT turn the ignition key 'OFF' or interrupt the power supply during ECU upgrade.
- When the ECU upgrade is completed, turn the ignition 'OFF' and wait 10 seconds before starting the engine.
- ONLY use approved ECU upgrade software designated for the correct application.

IMPORTANT

It is recommended to ALWAYS check the Electronic Parts Catalog (EPC) to locate the ECU Part Number respective to Auto/Manual Mode ROM IDs. DO NOT reference the parts label affixed to the ECU.

***** NOTICE

Before attempting an ECU upgrade on any Kia model, make sure to first determine whether the applicable model is equipped with an immobilizer a security system. Failure to follow proper procedures may cause the PCM to become inoperative after the upgrade and any claims associated with this repair may be subject to chargeback.



SERVICE ACTION: VARIABLE MUFFLER OPERATION LOGIC IMPROVEMENT (SA468)

ROM ID INFORMATION TABLE:

Upgrade Event #542

Model	lel EM TM		IMMO	ECU P/No.	ROM ID		
WOUEI		I IVI		ECO F/NO.	Previous	New	
				39111 3L024	CENNDM_Q_N2A	CENNDM_Q_N2B	
				39111 3L025	CENNDM_T_N2A	CENNDM_T_N2B	
				39111 3L026	CENNDM_R_N2A	CENNDM_R_N2B	
СК		3.3L GDI 8AT Yes -	Yes	39111 3L027	CENNDM_U_N2A	CENNDM_U_N2B	
UN				39111 3L028	CENNDM_W_N2A	CENNDM_W_N2B	
			39111 3L029	CENNDM_Z_N2A	CENNDM_Z_N2B		
				39111 3L030	CENNDM_X_N2A	CENNDM_X_N2B	
			39111 3L031	CENNDM_1_N2A	CENNDM_1_N2B		

To verify the vehicle is affected, be sure to check the Calibration Identification of the vehicle's ECM ROM ID and reference the Information Table as necessary.

Prior to performin	ig the ECU upgrade, be sure to check that the KDS is fully charged.



Page 4 of 9

SUBJECT:

SERVICE ACTION: VARIABLE MUFFLER OPERATION LOGIC IMPROVEMENT (SA468)

1. Connect the VCI-II to the OBD-II connector, located under the driver's side of the instrument panel.

***** NOTICE

The ECU upgrade function on KDS operates wirelessly. It is not necessary to perform the upgrade via USB cable.


2. With the ignition ON, turn ON the KDS tablet. Select **KDS** from the home screen.


3. Confirm communication with VCI (A) and then configure the vehicle (B) using the **AUTO VIN** (C) feature.

4. Select ECU Upgrade.











SERVICE ACTION: VARIABLE MUFFLER OPERATION LOGIC IMPROVEMENT (SA468)

5. The KDS will check the server for recently uploaded Events and then automatically download **Upgrade Event #542 (CK).**



The vehicle must be identified in Vehicle Selection to download an Event for that vehicle.

6. Select Auto Mode.




Do NOT attempt to perform a Manual Mode upgrade <u>UNLESS</u> <u>Auto Mode fails</u>. Always follow the instructions given on the KDS in either Auto or Manual mode.

7. Select the **Engine** system under the System selection menu.

Touch **ID Check** (D) and confirm that the latest update is available.

Select **Upgrade Event #542,** and select **Upgrade** to continue.

Event	Status
271.QF 2.4GDI DTC P0171,P0420 LOGIC IMPROVEMENT	Downloading
273.TF 2.4GDI DTC P0171,P0420 LOGIC IMPROVEMENT	Ready
36%	
Do not touch any system buttons while performin	ng this function.



			>
ROM ID		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	
Currently in Vehicle	#####	<u>ب</u>	ID Check
Latest Update	#####		ID Offeen
Event Group			тѕв
###.XX			



Page 6 of 9

SUBJECT:

SERVICE ACTION: VARIABLE MUFFLER OPERATION LOGIC IMPROVEMENT (SA468)

8. The ECU upgrade will begin and the progress of the upgrade will appear on the bar graph. Upgrade part (1/2) (E) will download the upgrade event to the VCI-II. Upgrade part (2/2) (F) will upgrade the ECU.




Do not touch the system buttons (like 'Back', 'Home', 'etc.') while performing ECU Upgrade.

9. If a "Communication Fail" screen appears, verify that the VCI-II and KDS are communicating properly. Touch **OK** and restart the procedure from step 4.


***** NOTICE

If an error notice continues to appear or if the upgrade cannot be performed, DO NOT disconnect the KDS/VCI-II. Contact GIT America Help Desk at (888) 542-4371 or Techline.

10. When instructed on the KDS, turn the ignition **OFF** for ten (10) seconds then back on. Touch **OK** to continue.









Page 7 of 9

SUBJECT:

SERVICE ACTION: VARIABLE MUFFLER OPERATION LOGIC IMPROVEMENT (SA468)

11. Once the upgrade is complete, touch **OK** to finalize the procedure.

500% Succeed The ECU Upgrade is successfully finished.	and the second
The ECU Upgrade is successfully finished.	
ROM ID	
Currently in Vehicle #####	
Latest Update #####	
ок	

12. When prompted, select **YES** to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.

	-	V				
Notice						
Do you want to run Fault Code Searching?						
,	Yes	No				
Latest Update	58910-C6900	_1.3				

13. Start the engine to confirm proper operation of the vehicle.



SERVICE ACTION: VARIABLE MUFFLER OPERATION LOGIC IMPROVEMENT (SA468)

Manual Upgrade Procedure:

***** NOTICE

The manual upgrade should ONLY be performed if the automatic upgrade fails.

If the automatic upgrade fails, turn the ignition OFF for about 10 seconds then place it back in the ON position to reset the control unit BEFORE performing manual upgrade.

See table below for Manual Mode passwords.

Manual Mode ECU Upgrade Passwords

Menu	Password
CK PE 3.3TGDI 8AT +IMMO/SMK (NAS) : 39111-3L024	3024
CK PE 3.3TGDI 8AT +IMMO/SMK (NAS) : 39111-3L025	3025
CK PE 3.3TGDI 8AT +IMMO/SMK (NAS) : 39111-3L026	3026
CK PE 3.3TGDI 8AT +IMMO/SMK (NAS) : 39111-3L027	3027
CK PE 3.3TGDI 8AT +IMMO/SMK (NAS) : 39111-3L028	3028
CK PE 3.3TGDI 8AT +IMMO/SMK (NAS) : 39111-3L029	3029
CK PE 3.3TGDI 8AT +IMMO/SMK (NAS) : 39111-3L030	3030
CK PE 3.3TGDI 8AT +IMMO/SMK (NAS) : 39111-3L031	3031

- 1. Within the ECU Upgrade screen displayed, select Manual Mode.
- Select the Engine system under the System selection menu. Select Upgrade Event #542 (CK) and select Upgrade to continue.
- 3. Select the appropriate control unit part number with reference to the ROM ID Information Table on page 3, and select **OK**.
- 4. Enter the appropriate password from the Manual Mode password table above and select **OK**.
- 5. The upgrade will begin and the progress of the upgrade will appear on the bar graph.
- 6. When instructed on the KDS, turn the ignition **OFF** for ten (10) seconds then back on. Touch **OK** to continue.
- 7. Once the upgrade is complete, touch **OK** to finalize the procedure.
- 8. When prompted, select **YES** to check for Diagnostic Trouble Codes (DTC) and erase any DTCs stored such as EPS, ESC, and TPMS that may have been set during the upgrade.
- 9. Start the engine to confirm proper operation of the vehicle.



SERVICE ACTION: VARIABLE MUFFLER OPERATION LOGIC IMPROVEMENT (SA468)

AFFECTED VEHICLE RANGE:

Model	Production Date Range
Stinger (CK)	January 15, 2021 to February 5, 2021

WARRANTY INFORMATION:

N Code: N99 C Code: C99

Claim Type	Causal P/N	Qty.	Repair Description	Labor Op Code	Op Time	Replacement P/N	Qty.
V	39111 3L026	0	(SA468) ECM Logic Improvement	210029R0	0.3 M/H	N/A	0

***** NOTICE

VIN inquiry data for this repair is provided for tracking purposes only. Kia retailers should reference <u>SA468</u> when accessing the WebDCS system.

