# Technical Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



Subject:

FLOCK FINISHING ON DOOR SASH MOLDING PEELS OFF WHEN OPENING FROZEN DOOR

Bulletin No.: 09-008/21

Last Issued: 03/09/2021

#### **BULLETIN NOTES**

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted in Red text.

Previous TSBs:	Date(s) Issued:	
09-040/18	11/09/18	

#### APPLICABLE MODEL(S)/VINS

2017-2019 CX-5 2018-2019 CX-5 (Mexico spec.)

#### **DESCRIPTION**

Some customers may notice the flock finishing on the door sash molding is peeled off (as shown below) when opening the frozen door. This concern may be caused by insufficient durability due to an improper production process of the door sash moldings. To eliminate this concern, the production process of the door sash moldings has been changed.

Page **1** of **5** 



#### REPAIR PROCEDURE

- 1. Verify the customer concern.
- 2. Replace the affected door sash molding(s) with modified part(s) according to the instructions on MGSS online:
  - FRONT SASH MOLDING REMOVAL
  - FRONT SASH MOLDING INSTALLATION
  - REAR SASH MOLDING REMOVAL
  - REAR SASH MOLDING INSTALLATION
- 3. Verify the repair.

#### PARTS INFORMATION

FRONT SASH MOLDING (RIGHT):

Page 2 of 5

Bulletin No.: 09-008/21	Last Issued: 03/09/2021

Part Number	Description		Remark
KB7W-50-981K	MOULD (R), FRONT, SASH'A'	1	
KB7W-50-640C	MOULD (R), FRONT, BELT	1	[R]
KB7W-50-M10B GARNISH (R), FRONT DOOR		1	[R] B-PILLARGARNISH
KB7 W-30-IVITUB	GARNISH (R), FRONT DOOR	1	BLACK
KB8A-50-M10D GARNISH (R), FRONT DOOR		1	[R] B-PILLARGARNISH
		1	PIANO BLACK

## FRONT SASH MOLDING (LEFT):

Part Number	Description		Remark
KB7W-50-985K	MOULD (L), FRONT, SASH'A'	1	
KB7W-50-650C	MOULD (L), FRONT, BELT	1	[R]
KB7W-50-M20B	GARNISH (L), FRONT DOOR	1	[R] B-PILLAR GARNISH BLACK
KB8A-50-M20D	GARNISH (L), FRONT DOOR	1	[R] B-PILLAR GARNISH PIANO BLACK

#### **REAR SASH MOLDING (RIGHT):**

Part Number	Description		Remark
KB7W-50-991K	MOULD (R), REAR, SASH'A'	1	
KB7W-50-660C	MOULD (R), REAR, BELT	1	[R]
KB7W-50-M30B	GARNISH (R), REAR DOOR	1	[R] B-PILLAR GARNISH BLACK
KB8A-50-M30C	GARNISH (R), REAR DOOR	1	[R] B-PILLAR GARNISH PIANO BLACK
KB7W-50-M50A	GARNISH (R), REAR DOOR	1	[R] C-PILLAR GARNISH BLACK
KB8A-50-M50C	GARNISH (R), REAR DOOR	1	[R] C-PILLAR GARNISH PIANO BLACK

## **REAR SASH MOLDING (LEFT):**

Page 3 of 5

Bulletin No.: 09-008/21	Last Issued: 03/09/2021

Part Number	Description		Remark
KB7W-50-995K	MOULD (L), REAR, SASH'A'	1	
KB7W-50-670C	MOULD (L), REAR, BELT	1	[R]
KB7W-50-M40B GARNISH (L), REAR DOOR		1	[R] B-PILLAR GARNISH
			BLACK
KB8V-20-V440C	CADMICH (I ) DEAD DOOD	1	[R] B-PILLAR GARNISH
KB8A-50-M40C GARNISH (L), REAR DOOR		Т	PIANO BLACK
KB7W-50-M60A GARNISH (L), REAR DOOR		1	[R] C-PILLAR GARNISH
KB7 W-30-WOOA	GARNISH (L), REAR DOOR		BLACK
KB8V-20-M60C	CADNICH (I) DEAD DOOD		[R] C-PILLAR GARNISH
KB8A-50-M60C GARNISH (L), REAR DOOR		1	PIANO BLACK

## WARRANTY INFORMATION

#### NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
  - This repair will be covered under Mazda's New Vehicle Limited Warranty term.
  - Additional diagnostic time cannot be claimed for this repair.

Symptom Code	92
Damage Code	92
	****-50-981*
	or
	****-50-985 *
	or
	****-50-991*
Part Number Main Cause	or
	****-50-995*
	(Select the part number of the affected sash molding applicable to the subject vehicle from "Parts Information" table.)
Quantity	1
Operation No. and Labor Hours	Refer to the table below

## Page 4 of 5

Bulletin No.: 09-008/21	Last Issued: 03/09/2021

NOTE: Claim other necessary parts for repair, Qty. = 1 as related part.

## Sash Moldings Replaced: ONE

Operation No.	Labor Hrs.	Replacement
XXP9NARX	0.5	Front Door Sash Molding - One Side
XXP9NBRX	0.6	Rear Door Sash Molding - One Side

## Sash Moldings Replaced: TWO

Operation No.	Labor Hrs.	Replacement
XXP9NCRX	0.8	Front Door Sash Molding - Both Side
XXP9NDRX	1.0	Rear Door Sash Molding - Both Side
XXP9NERX	0.9	One Front and One Rear Door Sash Molding

#### Sash Moldings Replaced: THREE

Operation No.	Labor Hrs.	Replacement
XXP9NFRX	1.1	Both Front Door Sash Molding and One Rear
XXP9NGRX	1.3	Both Rear Door Sash Molding and One Front

## Sash Moldings Replaced: FOUR

Operation No.	Labor Hrs.	Replacement
XXP9NHRX	1.5	Both Front and Rear Door Sash Moldings

Page **5** of **5**