



# SERVICE BULLETIN

Classification: AT16-003B	Reference: NTB16-045B	Date: March 2, 2021
------------------------------	--------------------------	------------------------

## 2016-2019 TITAN AND TITAN XD; 7 SPEED A/T DTCs STORED

This bulletin has been amended. See AMENDMENT HISTORY on the last page.  
Please discard previous versions of this bulletin.

- APPLIED VEHICLES:** 2016-2019 Titan and Titan XD (A61)  
**APPLIED TRANSMISSION:** RE7R01B (7 A/T – 7 speed)  
**APPLIED ENGINE:** VK56VD (V8 Gasoline)

### SERVICE INFORMATION

**IMPORTANT:** If you confirm one or more of the following transmission DTCs are stored:

- P0729: 6GR Incorrect Ratio
- P0730: Incorrect Gear Ratio
- P0731: 1GR Incorrect Ratio
- P0732: 2GR Incorrect Ratio
- P0733: 3GR Incorrect Ratio
- P0734: 4GR Incorrect Ratio
- P0735: 5GR Incorrect Ratio
- P1734: 7GR Incorrect Ratio

### **Before performing any transmission repairs:**

1. Check **all** of the engine intake air ducting and make sure:
  - It is connected securely and correctly at the throttle body and all other connections. See Figures 1 and 2 on the next page.
  - All clamps and connectors are secure and tight.
  - There are no air leaks.
2. Perform DTC confirmation procedure to confirm the incident.
  - Refer to the Electronic Service Manual (ESM) for DTC confirmation procedures.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.




Figure 1



Figure 2

## AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
April 21, 2016	NTB16-045	Original bulletin published
November 11, 2016	NTB16-045A	APPLIED VEHICLES revised
March 2, 2021	NTB16-045B	APPLIED VEHICLES revised

