Technical Service Bulletin

Transaction No:

2062929/1



69-21-01 – Friction Related Click or Pop Noise from Steering Column

Release date:

4/7/2021

Condition

Applicable Veh	nicles				
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Tiguan	2020-2021	All	All	AX_LM000001	AX_MM077885

Revision Table			
Instance Number	Published Date	Version Number	Reason For Update
2062929/1	4/7/21	69-20-01	Original publication.

Friction, popping, clicking noises from steering column when turning / maneuvering steering wheel.

Technical Background

The repair will consist of a component inspection and adding a lubricant to specific areas between the steering wheel and airbag.

Production Solution

Modified lubrication process during assembly beginning with VIN: AX_MM077886.

Service



Be sure to observe all airbag handling cautions, warnings, notes and tips before beginning repairs. See repair manual group 69 in Elsa.



69-21-01 – Friction Related Click or Pop Noise from Steering Column

Release date:

4/7/2021




Figure 1: Upper steering column cover (2)

Remove the airbag. See repair manual group 69 in Elsa.

Remove the upper steering column cover using trim wedge tool -3409-. See repair manual group 68 in Elsa.




Figure 2:

Inspect the installation of the Steering Column Electronics Control Module -J527- (steering column combination switch) at the steering column upper housing.



69-21-01 – Friction Related Click or Pop Noise from Steering Column

Release date:

Transaction

No:

4/7/2021



Figure 3: Switch retaining tabs on column

The -J527- must be engaged in the column slots, NOT resting on top of the slots.

If the Steering Column Electronics Control Module -J527- is improperly seated, reinstall the -J527-. See repair manual group 94 in Elsa.

Install upper steering column cover.



Figure 4: Lubricate spring packs

Apply lubricant G 052 172 M2 to the 6 spring packs on the steering wheel (steering wheel removed for clarity).



Care must be taken not to get the lubricant on the 3 actuating arms of the horn contacts.

Install airbag. See repair manual group 69 in Elsa.

Technical Service Bulletin



69-21-01 – Friction Related Click or Pop Noise from Steering Column

Release date:

No:

4/7/2021

Warranty

To determine if this procedure is covered under Warranty, always refer to the Warranty Policies and Procedures Manual ¹⁾							
Model(s)	Yea	r(s)	Eng. Code(s)	Trans. Code(s)	VIN Range From		VIN Range To
Tiguan	2020-2021		All	All	AX_LM000001		AX_MM077885
SAGA			Coding				
Claim Type:	Use applica	ıble Clain	n Type ¹⁾				
Service Number:		Damage Code	HST		Damage Location (Depends on Service No.)		
6958	3		0020		Use applicable wher indicated in Elsa (L/R		
Parts N	lanufacture	r	Tig	uan	WWO ²⁾		O ²⁾
Labor Operation 3): Remove and install airbag			69 58 19 00 = see Elsa for latest time units.				
Labor Operation 3): Remove and install upper steering column cover			70 11 19 00 = see Elsa for latest time units.				
Labor Operation ³⁾ : Inspect Steering Column Electronics Control Module installation (no further action required)			94 50 01 99 = 10TU				
Labor Operation 3): Remove and reinstall Steering Column Electronics Control Module (as required)			94 49 19 50 = see Elsa for latest time units.				
Labor Operation 3): Lubricate steering wheel spring packs			48 10 41 99 = 10TU				
Causal Part: Select Labor Operation			48 10 41 99				
Outside Material: Lubricant Part No: G 052 1		72 M2	\$4.00 (1 can repairs 10 vehicles		irs 10 vehicles)		
Diagnostic Time ⁴⁾							
GFF Time expe	enditure		01500000 = Actua	I GFF print out	YES		ES
Road Test			01210004 = 10 TU		YES		

Technical Service Bulletin

Transaction No: 2062929/1



69-21-01 - Friction Related Click or Pop Noise from Steering Column

Release date:

4/7/2021

Technical Diagnosis	01320000 = 00 TU max.	NO
---------------------	-----------------------	----

Claim Comment: Input "As per Technical Bulletin 2062929" in comment section of Warranty Claim.

- 1) Vehicle may be outside any Warranty in which case this Technical Bulletin is informational only.
- ²⁾ Code per warranty vendor code policy.
- 3) Labor Time Units (TUs) are subject to change with ELSA updates.
- ⁴⁾ Documentation required per Warranty Policies and Procedures Manual.

Required Parts and Tools

Part No:	Part Description	Quantity
G 052 172 M2	Lubricant	1 (repairs 10 vehicles)

Part numbers are accurate at time of publication. Always refer to ETKA for the latest part information.

Tool Description	Tool No:
Trim Wedge Tool	3409
5mm-6mm pin punch	Obtained locally

Additional Information

All part and service references provided in this Technical Bulletin are subject to change and/or removal. Always check with your Parts Dept. and Repair Manuals for the latest information.