



Preliminary Information

PIC4996C Tips for Servicing Fuel Level Sensors/ Fuel Gauge Inoperative or Inaccurate

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Allure (Canada)	2005 - 2016	All	All	All	All
Buick	LaCrosse	2006 - 2019	All	All	All	All
Chevrolet	Impala	2006 - 2020	All	All	All	All
Chevrolet	Monte Carlo	2006 - 2007	All	All	All	All
Pontiac	Grand Prix	2004 - 2008	All	All	All	All

Supersession Statement

This PI was superseded to Update Model Years . Please discard PIC4996B.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

Several part returns of fuel level sensors are received NTF or damaged to the point where engineering cannot root cause product issue.

Recommendations / Instructions

If the SI diagnostic leads to a potential level sensor failure at the component, test the circuit from the connector at the top of the fuel module



When testing the sweep of the fuel level sensor, slowly sweep the float arm from the empty position to the full position watching the ohm meter looking for a momentary O.L. or open reading. You should see the sweep range from approximately 40 ohms to 250 ohms, + or - 5 ohms.



Note: Do not remove the fuel level sensor from the fuel module unless you get a faulty reading during the testing of the sensor. This may cause damage to the fuel level sensor unnecessarily.

If during testing you identify a faulty sensor, remove the sensor from the unit by lightly prying the lock tab on the fuel level sensor body inside the fuel level module.



Once sensor is removed from assembly carefully depress lock tabs on both sides of the sensor to remove the terminals from the fuel level sensor assembly. Install terminals into a new fuel level sensor. Carefully, install new fuel level sensor into module. Perform the sweep test again with your meter leads on the connector at the top of the fuel level module.



Upon a successful sweep test, reinstall module into the fuel tank, reassemble the components and verify successful repair.

If the sweep test fails with the new fuel level sensor installed replace the complete fuel module.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



© 2021 General Motors. All Rights Reserved.