

Technical Service Bulletin

47 Rattling noises coming from front axle, brake retaining pins are incorrectly positioned

47 21 09 2063040/1 April 20, 2021.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q5, SQ5	2018 - 2022	All	Disc brakes in front

Condition

Customer states:

• Rattling noises are coming from front axle.

Workshop findings:

• The retaining pins are not in the correct position in the brake caliper.

Technical Background

The retaining pins may become loose and move out of their position in the brake caliper as a result of vibrations at the front of the vehicle.

The measure described below must be performed to ensure the retaining pin remains seated in the brake caliper permanently.

Production Solution

A production change is under development.

Service

When replacing brake pads, ensure the retaining pin remains seated permanently, apply a drop of locking fluid to the barrel spring of the retaining pin (Figure 1).

© 2021 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin



Figure 1. Locking fluid application area in the retaining pins.

Warranty

mananty			
Claim Type:	 110 up to 48 Months/50,000 Miles. G10 for CPO Covered Vehicles – Verify Owner. If the vehicle is outside any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	4739		
Damage Code:	0010		
Labor Operations:	Retaining Pins installation + Glue application	4739 9999	20 TU
	Pads for front disc ; Remove + Reinstall NOTE: This I O care only he included if node are	4636 2050	See SRT with associated operations
	This LO can only be included if pads are being replaced.		
	Wheel removed + reinstalled	4405 2000	See SRT with associated operations
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	0121 0004	10 TU
Claim Comment:	As per TSB #2063040/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual.* Claims are subject to review or audit by Audi Warranty.

© 2021 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.					
Part Number	Part Description	Quantity			
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA			
See ETKA	Set of Braking Pads (if necessary)	01			
See ETKA	Retaining Pins (if necessary)	As needed			
D 154100A1	Locking Fluid	0.1			

Additional Information

All parts and service references provided in this TSB (2063040) are subject to change and/or removal.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.

© 2021 Audi of America, Inc.

Page 3 of 3

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.