## PORSCHE

# Advanced Technical Information

Bulletin #: 2107 Part ID: 2706 2

## 9YA When Replacing 12V Li-ion Battery, PHEV Models Have No Crash Shield

#### **Vehicles Affected**

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Cayenne	As of 2019 up to 2021	9YA	N/A	N/A

### **Revision History**

Revision	Release Date	Changes
0	April 30, 2021	Original document

### Condition

When replacing the 12V Li-ion battery, PHEV models no longer need or support an additional crash shield (often called a crash plate or reinforcement).

#### **Technical Background**

Previously, all Cayenne replacement 12V Li-ion batteries were supplied by LG Chem. These batteries require an additional crash shield that the workshop ordered along with the battery. Porsche recently adopted an A123 battery for PHEV Cayenne only. This new battery is reinforced internally and does not need an additional crash shield. However, the gasoline powertrain models still require the external shield as of the release of this bulletin.



**AfterSales** 

# Advanced Technical Information

**Bulletin #: 2107** Part ID: 2706

#### **Service Information**

The replacement 12V battery part numbers listed in PET are correct as of April 2021 for both PHEV and traditional gasoline powertrain Cayenne models. Please stay up to date with PET and order and install the parts specified therein.

Porsche will update the workshop manual shortly to reflect this information.

#### Search Items

E3, Cayenne, Li-ion, 12V, LiFePO4, parts, crash bar, shield, plate

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

