

Technical Information

Service

40/21 ENU 4381

4

Complaint – Warning Message "Lift System Fault – Service Necessary" Appears in Instrument Cluster: Observe Specified Procedure (40/21)

Model Line: 911 Carrera (992)

Model Year: As of 2020

Equipment: Front-axle lift function (M-no. 2UH)

Concerns: Front-axle lift function

Information: The white warning message 'Lift system fault – Service necessary' appears in the instrument cluster and

the entry '000302 – Measuring vehicle height fault' can be stored in the fault memory of the front-axle lift system control unit. This fault type can occur if the vehicle was parked with the body front section raised.



Information

Always park the vehicle at the lowered position, as the upper holding position cannot be guaranteed over a long period of time with the engine stopped depending on the system. Further information on the front-axle lift system can be found in the relevant section of the Owner's Manual.

Action required: If both error messages are displayed, perform ride height measurement and check.

Required tools

Tools:

 Battery charger with a current rating of at least 90 A and, if required, also with a current and voltage-controlled charge map for lithium starter batteries, e.g. VAS 5908 battery charger, 90A



Information

The 911 (992) may be equipped with a lithium-ion 12V battery (I-no. J2A).

Lithium starter batteries must only be charged using a **suitable battery charger** that has a current and voltage-controlled charge map.

For further information about the battery chargers to be used, see \Rightarrow Workshop Manual '270689 Charging battery/vehicle electrical system'.

4381 ENU 40/21

Technical Information

Ride height measurement and check

Work Procedure: 1 Perform ride height measurement.

- 1.1 Raise the body front section.
 - 1.1.1 Start the engine.
 - 1.1.2 Press the button for the lift system in the center console.
 - 1.1.3 Wait until the indicator light on the button lights up continuously red.A message briefly appears in the instrument cluster indicating that the body front section is raised.
 - 1.1.4 Stop the engine.



Information

The measurement is described and shown for one side as an example. The measurement on the other side is almost identical.


- 1.2 Determine the ride height at the front left \Rightarrow *Ride height measurement, front left-Z-*.
 - 1.2.1 Apply adhesive strips (e.g. adhesive tape) \Rightarrow *Ride height measurement, front left* -1- to the wing.
 - 1.2.2 Align the measurement tool \Rightarrow *Ride height measurement, front left* **-2** vertically and mark the measuring point \Rightarrow *Ride height measurement, front left* **-3**-.
 - 1.2.3 Carefully measure the ride height and write it down.
 - 1.2.4 Repeat the procedure for the right side.
- 1.3 Observe an idle period of three hours.
- 1.4 Repeat the measurements, write them down and compare values:

	Assessment	Action required
(√)	The ride height at the left or right has dropped by less than 10 mm (0.4 inch).	Please inform the customer that the vehicle must only be parked with the front body section lowered. Further information can be found in the 'Front-axle lift system' section of the Owner's Manual. There is not necessarily a technical fault if the fault type occurs again. The error message can be corrected by repeated raising and lowering of the lift system.
(X)	The ride height at the left or right has dropped by more than 10 mm (0.4 inch).	Replace compressor for front-axle lift system, see \Rightarrow Workshop Manual '431519 Removing and installing compressor (front-axle lift system)'.

Service

L

40/21 ENU 4381



Ride height measurement, front left

Required parts and materials as required

Parts Info:	Part No.	Designation – Use	Qty.
	9P1412257G	⇒ Pump unit including pressure line– Front-axle lift system	1 ea.
	WHT008676	⇒ Hexagon-head bolt,M12 x 1.5 x 45– Right diagonal brace	2 ea.

Additional parts required (M-no. 1X1):

Part No.	Designation	Qty.
	- Use	
PAF107190	\Rightarrow Collared cheese head bolt	12 ea.
	with hexagon socket head	
	 Front drive shaft 	
PAF008660	⇒ Hexagon nut, M10	2 ea.
	 Front transmission support 	

Service

4381 ENU 40/21

Technical Information

N 10629602	⇒ Hexagon flange bolt,	4 ea.
	M10 x 35	
	 Rear final drive bracket 	

992521225 \Rightarrow Boot 1 ea.

Cardan shaft

PAF909910 \Rightarrow Cheese head bolt with 3 ea.

multiple-tooth head, M10 x 23

(M-no. G1L) – Cardan shaft

or

PAF909910 \Rightarrow Cheese head bolt with 4 ea.

multiple-tooth head, M8 x 16 $\,$

(M-no. G1G) – Cardan shaft

Materials: Required materials (usually already available at the Porsche dealer):

Part No. Designation Qty.

– Use

PAF052735 \Rightarrow Lubricating grease 20-gram tube ¹⁾

Front cardan shaft

Invoicing

Invoicing:

For documentation and warranty invoicing, enter the labor operations, PQIS coding and, if required, relevant part numbers specified below in the warranty claim:

APOS	Labor operation	I No.
43010149	Checking levelling system	
43151950	Removing and installing compressor for levelling system	

PQIS coding:

Location (FES5)	43810	Air-lift pump control unit
Damage type (SA4)	9833	Cannot establish cause, re-coded

References: ⇒ Workshop Manual '431519 Removing and installing compressor (front-axle lift system)'

¹⁾ approx. 2 grams required per vehicle

			
Technical Information	Service	Service	
	40/21 ENU 4381	4	

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know how to do the job properly and safety. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed. © 2021 Porsche Cars North America, Inc.

Page 5 of 5