



SERVICE BULLETIN

Classification:

BT21-004

Reference:

NTB21-014

Date:

March 1, 2021

2012-2015 TITAN; HIGH-MOUNTED STOP LAMP SERVICE PART

APPLIED VEHICLES: 2012-2015 Titan (A60)

SERVICE INFORMATION

The mounting stud diameter for the high-mounted stop lamp service part has changed from 5 mm to 6 mm.

If, for any reason, the high-mounted stop lamp needs to be replaced, the mounting hole will need to be enlarged to 6.5 mm ($\frac{1}{4}$ inch) as follows:

1. Remove the high-mounted stop lamp.
 - For high-mounted stop lamp removal, refer to the Electronic Service Manual: Section **DRIVER CONTROLS > EXL – Exterior Lighting System > HIGH-MOUNTED STOP LAMP > Removal and Installation > HIGH-MOUNTED STOP LAMP**.
2. Enlarge the high-mounted stop lamp's mounting holes (see Figure 1 on page 2) using a 6.5 mm ($\frac{1}{4}$ inch) drill bit.

NOTICE To avoid damage to the vehicle, apply light pressure to the drill while drilling. Excessive force may cause the drill bit to penetrate too far and damage the headliner.
3. Apply touch-up paint to the mounting holes to protect the bare metal.
4. Install the new high-mounted stop lamp using M6 mounting nuts. Refer to the **PARTS INFORMATION** on page 2.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

- Figure 1, below, shown with the high-mounted stop lamp removed.




Figure 1

PARTS INFORMATION

| DESCRIPTION | PART NUMBER | QUANTITY |
|----------------------------------|-------------|-----------|
| High-Mounted Stop Lamp (M6 stud) | 26590-7S20A | 1 |
| NUT-HEX (M6 nut) | 08911-2062H | 2 |
| Touch-up Paint | Shop supply | As needed |

AMENDMENT HISTORY

| PUBLISHED DATE | REFERENCE | DESCRIPTION |
|----------------|-----------|-----------------------------|
| March 1, 2021 | NTB21-014 | Original bulletin published |