



SERVICE BULLETIN

Classification: DA15-007A	Reference: NTB15-027A	Date: March 12, 2021
------------------------------	--------------------------	-------------------------

2014 – 2015 ROGUE FCW SYSTEM SUPPLEMENTAL INFORMATION

This bulletin has been amended. See **AMENDMENT HISTORY** on the last page.
Discard all previous versions of this bulletin.

APPLIED VEHICLES: 2014 – 2015 Rogue (T32) Equipped with FCW

SERVICE INFORMATION

This bulletin is provided as supplemental information to aid in assisting the customer and servicing a vehicle with customer-reported FCW (Forward Collision Warning) system questions or issues.

- **FIRST:** Before proceeding to diagnostic and repair information in the Electronic Service Manual (ESM), make sure to review all of the FCW information in the Owner's Manual with the customer to determine whether the customer-reported operation of the system is consistent with a properly functioning FCW.
- **Do not attempt to test the operation of the FCW system by driving the vehicle. Driving situations in which the FCW is designed to activate are unsafe.**
- If after reviewing the Owner's Manual, it is determined that the FCW may not be operating as designed, follow the diagnostic and repair information in the Electronic Service Manual (ESM), section DAS-Driver Assistance Systems, for any confirmed issues.

The information on pages 2 and 3 lists items that may have an effect on the operation of the FCW system.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

ITEMS THAT MAY EFFECT THE OPERATION OF THE FCW SYSTEM

Sensor/Bumper Cleaning

- Make sure the bumper is clean in the area shown in Figure 1.
- The FCW sensor is located behind the bumper fascia and below the passenger side headlamp.
- Dirt on the bumper may have an effect on the FCW operation.




Figure 1

Collision Damage

- Check for any collision damage to the front of the vehicle.
- Previous collision damage may not be easily visible. Make sure the FCW sensor and supporting body panels are not damaged.
- Repair as needed. Collision damage is not covered under the Nissan Warranty.

DTCs (Diagnostic Trouble Codes)

- Use CONSULT-III plus (C-III plus) to check for any FCW DTCs.
- Follow the diagnostic and repair information in the Electronic Service Manual (ESM), section DAS-Driver Assistance Systems, for any DTCs that are stored.

FCW Warning Chime

- Use C-III plus to check the operation of the FCW warning chime.
- Follow the diagnostic and repair information in the Electronic Service Manual (ESM), section DAS-Driver Assistance Systems, if the warning chime does not operate correctly.

NOTE: The FCW warning chime Active Test is listed as “ICC Buzzer” on the C-III plus screen.




Figure 2

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
April 6, 2015	NTB15-027	Original bulletin published
March 12, 2021	NTB15-027A	Classification Number updated