

Bulletin No.: PIP5796A Published date: 04/7/2021

# Preliminary Information

## PIP5796A Engine Compartment Tick or Rattle Noise From Purge Solenoid Resonance Through PCV Tube

<u>Models</u>

Brand:	Model:		Model Years:	VIN:		Engine	Transmissions:
Di di lu.				from	to	Engine:	mansmissions.
Buick	Enclave		2020 - 2021	All	All	3.6 LFY	All
Chevrolet	Traverse		2020 - 2021	All	All	3.6 LFY	All
Involved Region or Country		North America Some customers may comment that they notice a loud ticking or rattle noise coming from the engine compartment area. Upon inspection technician may notice the noise coming from the purge solenoid tube.					
		This condition may be caused by pressure pulsations in the purge tube when the					

These pulsations create an audible rattle/tick noise which can be heard inside or

purge solenoid is commanded on.

outside the vehicle.

#### Correction:

Cause

To correct this condition, verify the noise is coming from the purge tube by commanding the purge solenoid on and off.


If noise can be duplicated, then it will be necessary to install insulator/dampers on the tube at the locations noted below.

1. Make 2 Insulators/Dampers using 2 pieces of 3/8 inch rubber fuel hose 3 inches long and 2 pieces of 1/2 inch rubber fuel or vacuum/heater hose 3 inches long on the outside of the 3/8 hose.

It will be necessary to split these hoses lengthwise.

2. Install 1 rubber damper at each location noted below using 2 tie straps on each one.

Orientate insulator with seam facing down.



1= Purge Line 2= Dampers

NOTE: This is a temporary repair for customer satisfaction. When the actual damper becomes available it will further dampen the noise.

NOTE: This PI will become a bulletin when the special part damper is available.

#### Warranty Information

For vehicles repaired under the Powertrain coverage. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time		
4087838	Install Insulators/ Dampers	0.5 Hrs.		
*This is a unique Labor Operation for Bulletin use only.				

### <u>Version History</u>

Version	2
Modified	03/30/2021 - Created on.
	04/07/2021- Updated to add Labor Operation.



© 2021 General Motors. All Rights Reserved.