



Bulletin No.: PIT5834A

Published date: N/A

Preliminary Information

PIT5834A A/C Blows Warm Intermittently Or Takes A Long Time To Start Cooling



Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Blazer, 11th VIN Digit=S	2021	MS500042 (8/6/20)	MS504602 (9/10/20)	All	All
Chevrolet	Equinox, 11th VIN Digit=S	2020	LS720529 (8/25/20)	LS720792 (9/10/20)	All	All

Involved Region or Country:	North America
Condition:	A/C is slow to cool, takes longer to blow cool air when compared to like vehicle.
Cause:	Possible A/C refrigerant contamination.

If you duplicate this condition and there is a noticeable performance difference when compared to another Blazer or Equinox and the vehicle was built during the above time period, recover the refrigerant using the GE-50957 Contaminated Refrigerant Recovery Machine. Remove the line from the condenser and the TXV and look for contamination like illustrated in the pictures below. If you have this contamination, take pictures of the fittings, open a TAC case and attach them to the case. Your case will be reviewed and you will be contacted directly. If you do not see visible contamination like below reinstall the lines and diagnose using the performance chart and diagnostics in Service Information.





Version History

Version	2.0
Modified	04/14/2021 - Created on. 04/20/2021 - Edit to add VIN breaks and dates



GENERAL MOTORS

© 2021 General Motors. All Rights Reserved.