



Preliminary Information


PIT5834B A/C Blows Warm Intermittently Or Takes A Long Time To Start Cooling



Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Blazer, 11th VIN Digit=S	2021	MS500041	MS505210	All	All
Chevrolet	Equinox, 11th VIN Digit=S	2020	LS716628	LS737551	All	All
Chevrolet	Equinox, 11th VIN Digit=5	2021	MS100011	MS100017	All	All

Involved Region or Country:	North America
Condition:	A/C is slow to cool, takes longer to blow cool air when compared to like vehicle or if the vehicles refrigerant needs to be evacuated for another repair.
Cause:	Possible A/C refrigerant contamination.

If you duplicate this condition and the vehicle was built during the above time period, recover the refrigerant using the GE-50957 Contaminated Refrigerant Recovery Machine. Remove the line from the condenser and the TXV and look for contamination like illustrated in the pictures below. If you have this contamination, take pictures of the fittings, open a TAC case and attach them to the case. Your case will be reviewed and you will be contacted directly. If you do not see visible contamination like below reinstall the lines and diagnose using the performance chart and diagnostics in Service Information.





Version History

Version	3
Modified	04/14/2021 - Created on. 04/20/2021 - Edit to add VIN breaks and dates 04/29/2021 - Edit to add VIN's and text.



GENERAL MOTORS

© 2021 General Motors. All Rights Reserved.