

48 Electric steering column adjustment is not working, DTC B14BF01 is stored in the BCM 1

48 21 01 2062288/3 May 14, 2021. Supersedes Technical Service Bulletin Group 48 number 21-95 dated March 8, 2021 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7, A8, S8, Q5, and SQ5	2018 - 2021	All	Electric steering column
Q7, SQ7	2017 - 2021	All	Electric steering column
S6, RS 6, S7, and RS 7	2018, 2020 - 2021	All	Electric steering column
Q8, Audi e- tron quattro	2019 - 2021	All	Electric steering column
A6 allroad, A8 PHEV, SQ8, RSQ8, and Audi e- tron Sportback	2020 - 2021	All	Electric steering column
A6 Avant, A7 PHEV, Q5 Sportback, and SQ5 Sportback	2021	All	Electric steering column

Condition

REVISION HISTORY			
Revision	Date	Purpose	
3	-	Revised Condition (Added Workshop findings statement)	
2	03/08/2021	Revised Service (Added Note)	
1	02/25/2021	Initial publication	

Customer states:

The electric steering column adjustment is not working in the vertical direction.

Workshop findings:

The customer statement can be reproduced.



There is no DTC stored.

Or

The following DTC is stored in the electronic central control module (BCM 1), J519 (address word 0009):

DTC B14BF01 (Steering column vertical adjustment motor electrical error) with symptom code 66145.

Technical Background

The software needs to be updated and the unit cleared.

Production Solution

Starting from production date 10/06/2020.

Service

SVM Update Instructions

- 1. Follow all instructions in TSB 2011732: 00 Software Version Management (SVM), operating instructions.
- 2. Update the steering column control module, J866 using the SVM action code as listed in the table below, if necessary:

Model	Old Software Part Number	Old Software Version	New Software Part Number (or higher)	New Software Version (or higher)	SVM Code Input
Audi e-tron quattro, Audi e-tron Sportback	80A907705A 80A907705	0200 0100	80A907705A	0210	
A8	80A907705A 80A907705	0200 0100 0080	80A907705A	0210	649S001
A6, A7	80A907705A 80A907705	0200 0100	80A907705A	0210	
Q7, Q8	80A907705A	0200	80A907705A	0210	



	80A907705	0100 0080 0070		
Q5	80A907705A 80A907705	0200 0100 0080	80A907705A	0210

- 3. The function of the electric steering column adjustment must be restored. Proceed as follows:
 - Get into the vehicle and use your knees to push the steering wheel upward (a force of approx. 40 kg or 88 lbs is required), at the same time press the steering column adjustment switch upwards in the vertical adjustment direction (Figure 1).
 - This will restore the function of the electric steering column adjustment.



Figure 1. 40 kg force pushing steering wheel upward.

4. The electric steering column adjustment must be cleared with the help of up to 50 adjustment cycles in the vertical direction. To do so, you will need the tool kit T10230 (the toolset weighs approximately 9 kg or 20 lbs).



If the tool kit T10230 is not available in the workshop, look for a similar weight toolbox.

5. Move the steering wheel as far as possible toward the dashboard and then move the driver's seat as far back as it will go.



6. Attach the tool kit to the steering wheel using a small securing strap (Figure 2). Take care not to damage the steering wheel.

We recommend placing a cleaning cloth underneath, as shown in Figure 2.



Figure 2. Weight necessary for steering adjustment.

7. Apply plastic foil to make sure the tool kit cannot scrape against the seat (Figure 3).



Figure 3. Plastic foil protection for the seat.

8. If needed, operate the steering column adjustment and move the steering column all the way up and down again up to 50 times. The weight of the tool kit will create a current in the adjustment motor and this will clear the adjustment unit.





Note:

The Test Plan should perform the 50 adjustments automatically. <u>If</u> the Test Plan does not perform the 50 adjustments automatically, then perform it manually as described in this step.

<u>Test Plan location</u>: 0009 Electronic Central Electrics, function >> 09 Remedy Process, electrically adjustable steering column.

Warranty

Trairianty			
Claim Type:	• 110 up to 48 Months/50,000 Miles.		
	G10 for CPO Covered Vehicles – Verify Owner.		
	If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	4823		
Damage Code:	0040		
Labor Operations:	Software Update (Includes checking for DTCs)	0151 0000	Time stated on the diagnostic protocol
	Check and adjust steering column	4823 0599	50 TU
Diagnostic Time:	GFF	No allowance	0 TU
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2062288/3		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Tool Number	Tool Description
T 10230	Assembly tool – Only necessary to simulate the weight



Additional Information

The following Technical Service Bulletin(s) will be necessary to complete this procedure:

TSB 2011732, 00 Software Version Management (SVM), operating instructions.

All part and service references provided in this TSB (2062288) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.