



**NUMBER:** 08-065-21

**GROUP:** 08 - Electrical

**DATE:** April 24, 2021

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**SUBJECT:**

Flash: Radio Frequency Hub Module (RFHM) Enhancements

**OVERVIEW:**

This bulletin involves reprogramming the RFHM with the latest available software.

**MODELS:**

2019 - 2021 (BV) Jeep Renegade

**NOTE:** This bulletin applies to vehicles within the following markets/countries: North America and EMEA.

**NOTE:** This bulletin applies to vehicles built on or before March 30, 2021 (MDH 0330XX) equipped with Passive Entry Remote Start Package (Sales Code AJW) or Passive Entry / Keyless Go (Sales Code GX4).

**SYMPTOM/CONDITION:**

Customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the technician may find that the following Diagnostic Trouble Code (DTC) has been set:

- B1053-64 RFHM (Keyless Ignition Node (KIN) Communication) - Signal Plausibility Failure.

In addition, the customer may notice the following condition(s):

- Service Passive Entry Light" on cluster and MIL code B1053-64.
- Vehicle will not shut off with DTC B1053-64.
- Vehicle may not start with DTC B1053-64.

**DIAGNOSIS:**

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed above or if the technician finds the DTC, perform the Repair Procedure.

**REPAIR PROCEDURE:**

**NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.**

**NOTE: If this flash process is interrupted/aborted, the flash should be restarted.**

1. Reprogram the RFHM with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

**POLICY:**

Reimbursable within the provisions of the warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Skill Category	Amount
18-19-12-9U	Module, Radio Frequency Hub (RFHM) - Reprogram (0 - Introduction)	6 - Electrical and Body System	0.2 Hrs.

**NOTE: The expected completion time for the flash download portion of this procedure is approximately 3 minutes. Actual flash download times may be affected by vehicle connection and network capabilities.**

**FAILURE CODE:**

**The dealer must use failure code CC with this Service Bulletin.**

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- When utilizing this failure code the 3C's (customer's concern, cause and correction) must be provided for processing Service Bulletin flash/reprogramming conditions.

CC	Customer Concern
----	------------------