



Subject: CONNECTED VEHICLE SYMPTOM TROUBLESHOOTING	Service Alert No.: SA-013/21
	Last Issued : 05/11/2021

BULLETIN NOTES

This service alert supersedes the previously issued service alert listed below. The changes are noted in Red text.

Previous Service Alert	Date(s) Issued:
SA-013/21	04/27/21, 03/15/21, 02/22/21, 02/08/21 and 02/02/2021
SA-031/20	12/09/20, 11/30/20, 11/06/20, 10/28/20, 06/16/20, 06/05/20, 06/01/20, 05/18/20, 04/14/2020, 04/02/20, 03/11/20 and 02/27/20

APPLICABLE MODEL(S)/VINS

- 2019-2021 Mazda3
- 2020-2021 CX-30
- 2021 CX-5
- 2021 CX-9

DESCRIPTION

Some customers may complain about any of the following:

- Infotainment Center Display does not provide the Authorization Code during the MyMazda App Connected Vehicle enrollment.
- Remote function(s) inoperative.
 - Engine Start / Stop
 - Door Lock / Unlock
 - Lights ON / OFF
- MAZDA CONNECT connected vehicle reception strength icon shows "X" or "\".

Confirm the customer's phone and vehicle have good to strong reception during the concern as shown in the table below.

- If the reception is weak, move the vehicle to a location where the reception is good to strong as shown in the table, then try to get the Authorization Code and/or operate the remote functions before proceeding to the Repair Procedure if there is still an issue.
- If the reception is good to strong, proceed to the Repair Procedure.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.



Indication	Explanation
	Radio waves are not being received. Move to a location with good reception.
	Weak reception.
	Good Reception
	Strong reception.
	Currently conducting an operation check of the communication unit. If this condition continues, consult an Authorized Mazda Dealer.
	Currently conducting an operation check of the onboard communication unit. NOTE: Communication is not possible during this display.
<p>CX-5, CX-9</p>	<p>The communication function is temporarily disabled due to infotainment system setting.</p>
<p>Mazda3, CX-30</p>	<ul style="list-style-type: none"> • Connected Service contract has ended (Subscription expired) • Customer deactivated Connected Services (Opt-Out) <ul style="list-style-type: none"> ◦ eMDCS Warranty Vehicle Inquiry will show Campaign CSP04 Status Closed
<p>CX-5, CX-9</p>	<ul style="list-style-type: none"> • TCU has not been initialized, go to SA-004/21

Remote Engine Start Will Not Function under the following conditions

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Item	Condition
1	Vehicle battery voltage low
2	Automatic Transmission shift position except "P"
3	Vehicles equipped with manual transmission
4	Vehicle speed above 3 mi/h (5 km/h)
5	Brake pedal switch malfunction
6	Engine has been running by remote engine start function
7	Engine started by remote engine start more than 2 consecutive times while the vehicle is not driven. The vehicle must be driven 1-mile or 24-hours must pass from the last successful Remote Engine Start for the use count to reset.
8	2021 Mazda3 and CX-30: Vehicle's electrical control area network (CAN) is in "Sleep Mode"
9	A registered key is detected in the vehicle
10	Brake pedal switch detects brake application
11	Low fuel warning message
12	Engine starts, then turns OFF due to abnormal high engine rpm detected. (Engine rotation over 3000 rpm continued for more than 0.2[s])
13	No engine rpm detected after sending engine start request. (Engine rotation 0 rpm continued for more than 0.2[s])
14	When the CAN data signal for engine shut off is present (e.g.: door ajar signal)
15	After 10 second maximum cranking time
16	Burglar alarm status is "Alarm" and "Alarm stand by" (CAUTION - DO NOT enable, see Theft-Deterrent System section in SA-012/20)
17	Room fuse blown/missing
18	Connected Vehicle Maintenance Mode enabled (Restricted Transmitting Mode in MDARS)
19	Vehicle is parked (stored) for approximately 1 week or longer or in deep sleep mode. Drive the vehicle for a few miles to recover.
20	DTC Stored
21	Aftermarket Remote Engine Start accessory installed.
22	Mazda Remote Engine Start (BCKA-V7-620) accessory installed (No MyMazda app remote engine start function). Mazda Remote Engine Start (RES) Removal a. Remove the Mazda Remote Engine Start (RES) accessory module. b. Deactivate and activate Advanced Key(s). Refer to MGSS IMMOBILIZER SYSTEM-RELATED PARTS PROGRAMMING [(US)]
23	First remote control attempt fails, second attempt works fine. Go to TSB 16-002/20 .

Remote Engine Start Function Will turn engine OFF under the following conditions




Item	Condition
1	Vehicle door(s) opened

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

2	Vehicle trunk opened
3	Vehicle hood opened
4	Ignition switch push button "ON" detected
5	Remote engine STOP request
6	Brake pedal switch detects brake application
7	DTC Stored
8	Engine will stop running automatically after 15 minutes for safety, security and emissions.


REPAIR PROCEDURE

NOTE: Vehicles stored for long periods may lose GPS clock synchronization. If the vehicle is stored for a long period, test drive the vehicle to give the GPS clock time to synchronize before enrolling or testing connected vehicle functions.

Customer Complaint	Action
<p>Remote function(s) inoperative.</p> <ul style="list-style-type: none"> • Engine Start / Stop • Door Lock / Unlock • Lights ON / OFF 	<p>1. Go to the MyMazda App INBOX -> ACTIVITY HISTORY -> to view reason for remote function failure.</p> <p>2. If necessary, use MDARS to ID the vehicle and check for DTC's stored.</p> <p>Are DTC(s) stored?</p> <ul style="list-style-type: none"> • Yes: Go to MGSS for normal DTC diagnosis.. • No: Contact Hotline for technical support if needed. <p>NOTE: The customer can view the reason for remote function failure.</p> <p>Example 1 (Push notification)</p> <div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  <p>OS Lock Screen Tap the push notification</p> </div> <div style="text-align: center;">  <p>Home Tap the alert card</p> </div> <div style="text-align: center;">  <p>Inbox Detail Tap "check vehicle status"</p> </div> </div>

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

Example 2 (Activity History)



Vehicle Center Display does not provide the Authorization Code during the MyMazda App Connected Vehicle enrollment.

1. Use MDARS to ID the vehicle and check for DTC's stored.
Are DTC(s) stored?
 - **Yes:** Go to step 2.
 - **No:** Perform [ODR Data Collection Procedure](#), then go to step 2.
2. Retrieve MAZDA CONNECT CMU log data. Go to MGSS [MAZDA CONNECT CMU Data Retrieval](#)
3. Perform "[Activating Remote Control by Smart Phone](#)" ([links TCU to BCM](#))
4. Clear DTC(s).
NOTE: If DTC 2050:55 is stored, go to [SA-003/20](#) to clear DTC.
5. Perform KAM reset.
NOTE: Test drive vehicle after a KAM reset to allow the GPS clock to synchronize before retrying Authorization Code.
6. Contact Hotline for additional technical support if needed.

MAZDA CONNECT connected vehicle reception strength icon shows "X" or "\".
Mazda3, CX-30



1. **Did the customer deactivate Connected Services (Opt-Out)?**
NOTE: If deactivated, eMDCS Warranty Vehicle Inquiry will show Campaign [CSP04](#) Status Closed.
 - **Yes:** No repair needed.
 - **No:** Go to next step.
2. Check for DTCs.
Are there any DTC's stored?

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

CX-5, CX-9



- **Yes:** Go to MGSS for normal DTC diagnosis.
- **No:** Go to next step.

3. Disconnect battery terminal for 30 seconds, then move the vehicle. **Is the reception strength signal normal?**

- **Yes:** Repair complete.
- **No:** Go to next step.



4. Perform TCU activation. Go to [SA-004/21](#). **Is the reception strength signal normal?**

- **Yes:** Repair complete.
- **No:** Go to next step.

5. Compare Tel antenna No. 1 signal strength with good known vehicle near by.

Go to DIAGNOSTIC ASSIST FUNCTION [CONNECTIVITY MASTER UNIT (US)]
Functional Inspection / Adjustment -> Navigation System Inspection

Example:



- **Good:** Contact Hotline for technical support.
- **No Good:** Swap Tel antenna No. 1 with known good vehicle.


Except CX-5 and CX-9:

- MAZDA CONNECT and/or MyMazda APP

Go to [SA-002/21](#).

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

displays incorrect tire pressures after battery disconnect and/or infotainment CMU software update.



2019 Mazda3 only:


- The customer is not able to activate Connected Services via the MyMazda app after CSP06 completion.
- MAZDA CONNECT connected vehicle reception strength icon is missing or shows unsubscribed after CSP06 completion.



Go to [CSP07 Repair instructions](#).



2020 Mazda3 only:

- Infotainment center display does not provide Authorization Code during the MyMazda App Connected Vehicle enrollment and infotainment Software Update Error message.



Go to [SSPC1](#).

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

<p>2021 Mazda3 and CX-30 functions inoperative:</p> <ul style="list-style-type: none"> • Vehicle Status Alert • Remote Engine Start / Stop • Remote Door Lock / Unlock • Remote Hazard Lights ON / OFF • Vehicle Finder (vehicle location mapping function is available) 	<p>Vehicle's electrical control area network (CAN) is in "Sleep Mode".</p>  <p>No dealer visit is required. Sleep Mode can be reset by starting the engine and idling or driving for 5 minutes or longer.</p> <p>See SA-005/21.</p>
<p>First remote control attempt fails, second attempt works fine.</p> <ul style="list-style-type: none"> • Engine Start / Stop • Door Lock / Unlock • Lights ON / OFF 	<p>Go to TSB 16-002/20.</p>
<p>Remote Engine Start inoperative due to:</p> <ol style="list-style-type: none"> 1. Aftermarket Remote Engine Start accessory installed. 2. Mazda Remote Engine Start (BCKA-V7-620) accessory installed. 	<ol style="list-style-type: none"> 1. Remove the aftermarket accessory. 2. The customer can use either the Mazda Remote Engine Start accessory or the MyMazda app function. Cannot use both. <p>Mazda Remote Engine Start (RES) Removal</p> <ol style="list-style-type: none"> a. Remove the Mazda Remote Engine Start (RES) accessory module. b. Deactivate and activate Advanced Key(s). Refer to MGSS IMMOBILIZER SYSTEM-RELATED PARTS PROGRAMMING [(US)].

ODR Data Collection Procedure


<p>1. ID the vehicle using MDARS</p>	<p>---</p>
--------------------------------------	------------

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

2. Select "Toolbox"




3. Select Vehicle Icon




CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

4. Select "Collect Diagnostic Information"




5. Select Collect Diagnostic Information "Run"



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

6. Turn Ignition ON, then select "Next"



Activating Remote Control by Smart Phone (links TCU to BCM)

NOTE: This procedure cannot be performed if the key transmitter power saving function is enabled. See [SA-040/20](#).

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

1. Connect MDARS.




2. Use MDARS to verify if the Telematics Control Unit (TCU) is at the latest software level (Toolbox > Software Update > Run > TCU).

Is the TCU at the latest software level?

- **Yes:** Go to step 3.
- **No:** Update TCU software, then go to step 3.

3. Select the following:
 a. Toolbox
 b. Repair icon
 c. MAZDA CONNECT
 d. Activating Remote Control by Smart Phone
 e. RUN.




4. Follow the on-screen instructions and wait for process to complete.

NOTE: If the Activating Remote Control by Smart Phone shows "Incomplete", the possible causes are:

- a. The advanced key is not in the vehicle.
- b. The connected Vehicle Maintenance Mode is enabled.
- c. The Key transmitter power saving function is enabled.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

d. The pacemaker radio wave interference prevention function is enabled.



5. Select Quick Check (A), then start the engine and select the DTC Clear icon (B).

CAUTION: If the engine is not started, DTC P2610 is stored and cannot be erased.



CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.