



# HYUNDAI

## Technical Service Bulletin

GROUP <b>Body</b>	NUMBER <b>21-BD-005H</b>
DATE  <b>May, 2021</b>	MODEL(S) <b>Accent (RB), Accent (HC) Elantra (MD/UD), Azera (HG), Sonata (LF/LFa), Sonata Hybrid (LF HEV)</b>

**SUBJECT:** TRUNK LATCH BASE REPLACEMENT

**This TSB supersedes 20-BD-010H-2 by updating the parts information section to specify that the part number 81231-C1000FFF is also applicable to Sonata (LF/LFa).**

**Description:** The trunk latch base can be ordered separately from the trunk latch assembly. This bulletin describes the procedure to replace the trunk latch base.

**Applicable Vehicles:** Certain 2014 – 2017MY Accent (RB), 2018MY and newer Accent (HC), 2013 – 2016MY Elantra (MD/UD), 2015 – 2017MY Azera (HG), 2015 – 2018MY Sonata (LF/LFa), and 2015 – 2018MY Sonata Hybrid (LF HEV) vehicles.

### Parts Information:

Applicable Model(s)	Part Number	Part Name	Comments	
Accent (RB) Accent (HC)	81231-1R020FFF	Trunk lid latch base	N/A	
Elantra (MD/UD) - Power	81231-3X010FFF			
Elantra (MD/UD) - Manual	81231-3X000FFF			
Azera (HG) Sonata (LF/LFa)	81231-C1000FFF			Without valet locking switch
Sonata (LF/LFa) Sonata Hybrid (LF HEV)	81231-C1010FFF			With valet locking switch

### Warranty Information:


MODEL	OP CODE	OPERATION	OP TIME	CAUSAL PART	NATURE CODE	CAUSE CODE
Accent (RB) Accent (HC) Elantra (MD/UD) Sonata (LF/LFa) Sonata Hybrid (LF HEV)	81231F01	Trunk Latch Partial Repair	0.3 M/H	Refer to the table above for the applicable P/N	I11	ZZ3
Azera (HG)	81231F02		0.4 M/H			

**NOTE:** Normal warranty applies.

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair

**Service Procedure:**

1. Remove the trunk latch assembly according to the applicable vehicle shop manual.



2. Remove the four trunk latch assembly screws.



3. Replace the trunk lid latch base and reuse the actuator.



When reusing the actuator, do not contaminate the motor area.



Latch Base



Actuator

4. Reinstall the removed parts in reverse order of removal.
5. After reassembly, verify that the trunk operates normally.
6. The service procedure is now complete.