Technical Bulletin



SERVICE BULLETIN

Classification:	Reference:	Date:
AN21-004	NTB21-038	May 7, 2021

DIAGNOSING SOFTWARE VS. HARDWARE AV ISSUES

APPLIED VEHICLES: All Nissan **APPLIED SYSTEM:** Infotainment

SERVICE INFORMATION

When diagnosing audio visual infotainment issues, confirming whether the issue is software or hardware based can be difficult to determine. To help the diagnostic process, a comparison of hardware vs. software issues and recommended resolutions has been provided in **TABLE 1** on page 2. In most cases replacing an AV unit that has a software concern with the same level part will not correct the issue. First, check ASIST for the latest related bulletins, and use the correct software package or Over The Air (OTA) updates, if available.

- As of the publication date of this bulletin, global shortages of raw materials have resulted in a very limited supply of AV units. Do not replace an AV unit unless it is absolutely necessary.
- Refer to the 2021 February-March Tech Talk article "Hardware vs. Software" for additional information.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

Software vs. Hardware Issues

TABLE 1

	Software Issues	Hardware Issues
Examples	 Intermittently freezes/reboots Issues that are triggered when a specific sequence of events occurs 	Constant blank screenContinuous rebootingButtons inoperative
Duplication	 Usually difficult to duplicate Typically no DTCs Note any steps for duplication 	Typically easy to duplicateSometimes DTCs present
Known Good Vehicle Comparison	Happens in all vehicles	Only happens in incident vehicle
What to check?	 Check configuration is correct Check for applicable TSBs Confirm software version is latest (refer to TSBs) Frequency that issue occurs Conditions when issue occurs Cold start After driving XX hours 	 Check configuration Check connections Check power and ground
Recommendation	Software update required Parts replacement not recommended	Replace Parts

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
May 7, 2021	NTB21-038	Original bulletin published

2/2 NTB21-038