



Technical Service Bulletin

93 High-voltage battery charger control module reports under wrong diagnostic address after being replaced

93 21 52 2063427/1 June 3, 2021.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Audi e-tron quattro, Audi e-tron Sportback	2020 - 2021	All	Not applicable

Condition

Customer states:

- The high-voltage battery charger control module, J1050 (address word 00C6) has been replaced due to a fault.

Workshop findings:

- After the vehicle's high-voltage battery charger control module, J1050 is replaced, the new unit no longer reports in the diagnostic scan tool under address word 00C6 but instead reports under address word 8113.

Technical Background

The replacement part needs to have the diagnostic address/address word changed.

Production Solution

Not applicable.

Service

If the concern occurs after the component is replaced, proceed as following using the diagnostic scan tool. Using Guided Functions select:

- High-Voltage Battery Charger Control Module 2, J1239 (Diagnostic address 8113).
- 8113 - High-Voltage Battery Charger Control Module 2, functions.
- 8113 - Change diagnostic address from 8113 to 00C6.
- Run the test plan and the scan tool will correct the diagnostic address.



Technical Service Bulletin

5. Check that the high-voltage battery charger control module, J1050 is now reporting in the scan tool under address word 00C6 and high-voltage battery charger control module 2, J1239 is no longer reporting under address word 8113.
6. Finish the replacement test plan for replacement of the high-voltage battery charger control module, J1050.

Warranty

This TSB simply provides extended repair instructions; it should not be used for separate billing. The extra time needed should be included in the GFF time for the repair you were currently working on.

Additional Information

All part and service references provided in this TSB (2063427) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.