

CUSTOMER SATISFACTION CAMPAIGN

GSX-R1000RA/RZA INERTIAL SENSOR



P.O. Box 1100, Brea CA 92822-1100

Vin# JS1DM11H2HXXXXXX



* J S 1 D M 1 1 H 2 H

Campaign EZ-R5

First Class Mail
U.S. Postage

PAID

Torrance, CA
Permit No. 1



CUSTOMER SATISFACTION CAMPAIGN

FIFTH REMINDER - ACTION REQUIRED

1 WHY HAVE YOU RECEIVED THIS NOTICE?

In September 2018, owners of select 2017-2018 GSX-R1000RA/RZA models were notified that Suzuki was conducting a customer satisfaction campaign to replace the inertial sensor (also known as the inertial measurement unit) on affected motorcycles. Parts are available to complete this campaign.

2 WHAT SHOULD YOU DO?

Please make an appointment to have your vehicle repaired **free of charge** at any Suzuki Dealer. **To locate your nearest Suzuki Dealer, go to www.suzukicycles.com and click on Find a Dealer at the top of the web page.** Provide the Vehicle Identification Number (VIN) from the front of this card to your Suzuki Dealer.

Operating your GSX-R1000RA/RZA without the repair being done may cause the ABS warning lamp to illuminate while disabling the ABS.

We ask that you immediately make arrangements to have this **FREE** repair performed by your Suzuki dealer.

Thank you for being a Suzuki Customer.

Suzuki Motor USA, LLC



To find your nearest Suzuki Dealer, go to www.suzukicycles.com and click on **Find a Dealer** at the top of the web page.

If you're having trouble having this repair completed, contact Customer Support at **1.714.572.1490** Monday through Friday **7:30am to 4:30pm, PDT**