



NUMBER: 09-005-21

GROUP: 09 - Engine

DATE: May 27, 2021

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This Technical Service Bulletin has also been released as a Rapid Response Transmittal (RRT) 21-067, date of issue May 27, 2021. All applicable Sold and Un-Sold RRT VINs have been loaded. To verify this RRT service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RRT will expire 18 months after the date of issue.

SUBJECT:

6.2L Engine Oil Temperature Sensor Leak

OVERVIEW:

This bulletin involves re-torquing the oil temperature sensor to the provided specification.

MODELS:

2021

(DT)

RAM 1500 Pickup

NOTE: This bulletin applies to vehicles within the following markets/countries: North America, LATAM, EMEA and APAC.

NOTE: This bulletin applies to vehicles built on or after July 13, 2020 (MDH 0713XX) on or before April 14, 2021 (MDH 0414XX) equipped with 6.2L Supercharged Hemi V8 SRT Engine (Sales Code ESD).

SYMPTOM/CONDITION:

Customers may notice a slight oil leak from under the vehicle near the oil temperature sensor location (Fig. 1) .




Fig. 1
Oil Leaking/Dripping Location

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair. If any vehicle not on the VIN list exhibits the symptom/condition, perform the repair.

REPAIR PROCEDURE:

1. Disconnect and isolate the negative battery cable(s). Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info> 08 - Electrical / 8F - Engine Systems / Battery System / Standard Procedure.
2. Disconnect engine wire harness clips to gain access to the sensor wire harness.
3. Disconnect the oil temperature sensor wire harness connector.
4. Torque the oil temperature sensor to 50 N·m (38 ft.lbs). **Do not remove the sensor only torque to the specification provided in this step.**
5. Reconnect the oil temperature sensor wire harness connector.
6. Reconnect engine wire harness clips in place, that were removed to gain access to the sensor wire harness.
7. Reconnect the negative battery cable(s). Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info> 08 - Electrical / 8F - Engine Systems / Battery System / Standard Procedure.
8. Check oil level and top off oil if necessary.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
08-46-20-90	Oil Temperature Sensor - Torque (1 - Semi-Skilled)	9 - Engine	0.3 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------