

**Countries:**

Availability: ISIS, Bus ISIS, FleetISIS, Body Builder, NotSIR

Major System: COOLING

Current Language: English

Other Languages: NONE

Viewed: 240

Document ID:

IK0900141

Revision: 1

Created: 3/19/2021

Last Modified: 6/16/2021

Author: Allan Hertko

[Less Info](#)
[Hide Details](#)
Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 0	Not Helpful 0
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	-------------------------	-----------------------------

Title: MV Air Compressor Inlet Hose Rubbing

Applies To: MV's with Cummins B6.7 built 11/20/2019 - 11/06/2020

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

06/14/2021- Updated article reflecting steps for diagnostic trouble codes and procedures.
03/21/2021- Initial Article Release

DESCRIPTION

Navistar has identified that in some rare circumstances the Air Compressor Inlet Hose from the Charge Air Cooler, may chafe due to insufficient route and clip. The description and images below offer instruction on sufficient route and clip.

SYMPTOM(s)

Diagnostic Trouble Code(s) & Dashboard Indicator Light(s):

DTC/Light	Description
SPN: 411 FMI: 2 (Cummins 1866)	EGR Differential Pressure - Data Erratic, Intermittent, or Incorrect
SPN: 102 FMI: 10 (Cummins 3361)	Intake Manifold Pressure - Abnormal rate of change
SPN: 3058 FMI: 18 (Cummins 3382)	EGR System - Data valid but below normal operating range
SPN: 3058 FMI: 10 (Cummins 3389)	EGR System - Abnormal rate of change

Customer Observations or Concerns:

- Air compressor inlet hose chaffed
- Turbo boost air leak at the air compressor inlet hose
- Check engine light

SPECIAL TOOL(s) / SOFTWARE

Tool Description	Tool Number	Comments	Instructions
N/A			

SERVICE PARTS INFORMATION

Kit Description	Part Number	Quantity	Notes
HOSE, AIR COMPRESSOR, 1 IN ID	6132813C2	1	Only required if chafed or leaking

DIAGNOSTIC STEP(s)

NOTE:

If an engine has experienced a failed air compressor hose and check engine light with active or inactive fault codes: 1866, 3361, 3382 and or 3389. Please refer to Cummins [Inspection & Cleaning Procedure Air Intake Connection](#) and [Service Bulletin 5579934](#) for further information. Proceed with hose replacement after cleaning and inspection has been completed.

NOTE:

If a hose is found to be chafed or leaking with no fault codes present proceed with hose replacement and routing steps listed below.

1. Inspect air compressor inlet hose for chafing or leaks
2. If chafing or leaks are found, replace hose
3. Route and clip hose per instructions below

REPAIR STEP(s)

Route and Clip Requirements:

1. Air Compressor Intake Hose clipping point on the CAC pipe shall be centered horizontally and securely fastened with a saddle & tie strap (Figure 1)
2. Air Compressor Intake Hose clipping point to the saddle tie strapped on the CAC pipe shall be centered vertically on the CAC pipe and securely fastened with a tie strap (Figure 2)
3. Air Compressor inlet hose routing shall be routed above and parallel to the fuel line, positioned in the highest clipping point in the stanchion bracket, and securely fastened with a tie strap (Figure 3)
4. Tie straps located near the driver side motor mount shall have the sharp trimmed edges of tie straps rotated away from the Air Compressor Inlet Hose so sharp edges face the motor mount (Figure 4)






Figure 1: Top View- CAC pipe saddle & tie strap centered


Air Compressor Intake Hose clipping point on the CAC pipe shall be centered horizontally and securely fastened with a saddle & tie strap

**Figure 2: Side View- CAC pipe saddle & tie strap centered**

Air Compressor Intake Hose clipping point to the saddle tie strapped on the CAC pipe shall be centered vertically on the CAC pipe and securely fastened with a tie strap

**Figure 3: Air Compressor Inlet hose routed above fuel line**

Air Compressor inlet hose routing shall be routed above and parallel to the fuel line, positioned in the highest clipping point in the stanchion bracket, and securely fastened with a tie strap

**Figure 4: Rearward projection- Sharp Edge rotated to away**

Tie straps located near the driver side motor mount shall have the sharp trimmed edges of tie straps rotated away from the Air Compressor Inlet Hose so sharp edges face the motor mount

WARRANTY INFORMATION

Warranty Claim Coding:

Refer to the [Warranty Coding Manual](#) for Group and Noun Codes.

Standard Repair Time(s):

Refer to the [SRT Manual](#) for Repair Times

NOTE:

Reference Cummins Inspection & Cleaning of Air Intake Connection

OTHER RESOURCES

[Master Service Information Site](#)

 Hide Details

Feedback Information

Viewed: 239

Helpful: 0

Not Helpful: 0

Staff ID	Client ID	Comments	Created Date
	DY00184	You received the following feedback From: DY00184 - Shane Hoyer Email Address: shoyer@hillintltrucks.com Job Classification: SE003, Service Manager Dealer: HILL INTL TRUCKS NA LLC Feedback: CAN WE ADD THE NOUN FOR THIS HOSE TO THE LETTER PLEASE	6/29/2021 8:53:01 AM