Bulletin #: 2114 Part ID: 9064

Engine Will Not Start: Updating PVTS CU Software via Dealer Web Portal

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
918 Spyder	As of 2010 up to 2021	918	N/A	 VTS preparation and Porsche Car Connect
Cayenne		92A		(I-no. 7G9)
Macan		95B		• VTS security package and keypad (I-no. 7IO)
Panamera		970/971		 VTS security package (I-no. 712)
Boxster/Cayman		982		
911 Carrera		991		

Revision History

Revision	Release Date	Changes
0	May 1, 2020	Initial release
1	June 18, 2020	Revision 1
2	June 23, 2021	Revision 2, converted from global TI to PCNA ATI

This bulletin replaces TI Group 9, 41/20, dated June 18, 2020.

Condition

The customer reports the engine will not start, and the instrument cluster may not turn on. An immobilizer error may be displayed in the instrument cluster. The condition can be intermittent. Diagnosis in the workshop confirms the immobilizer is activated and blocking vehicle/engine startup.

Technical Background

Certain Porsche Vehicle Tracking System (PVTS) control unit (CU) software is susceptible to false theft detection triggered by vibration.

Bulletin #: 2114 Part ID: 9064

Service Information

The PVTS CU hardware and software versions must first be checked using the PIWIS Tester.

The PVTS CU hardware version 2145 (or H10, or E50, depending upon PIWIS Tester software interpretation) is designed to handle software updates Over the Air (OTA). If the hardware version is 2145 and the software version is less than 0930, the control unit may be updated via the Dealer Web Portal (also known as the Porsche Car Connect Online Support Portal). If the software update via Dealer Web Portal is not functioning as described below then control unit replacement may be necessary.

If the hardware version is 2148 (or H11 or higher), then an OTA software update is not possible and control unit replacement is necessary.

 PPN Apps
 PPN Portal
 PPN Admin

 Navigation
 | PPN Portal
 > Porsche Cars

 Online Systems
 >
 >

 > Porsche Academy (PALMS 2.... *
 *

 > Porsche Car Connect - Onlin... *
 *

 > Porsche Connect Store - Co... *
 *



If the PVTS Control Unit requires replacement, then the correct replacement part should be determined via PET; do not use the part numbers listed in the Workshop Manual or Technical Information. If the Dealer Web Portal indicates the vehicle has an Active Contract, then use the Device Replacement Function in the portal. If there is not an Active Contract, it is not necessary to use the Device Replacement Function in the portal.

Note: Customers and Dealership employees can contact the Porsche Car Connect support center by calling 1-866-253-1742. This may be necessary due to security controls limiting vehicle tracking service information and control unit status information.

Performing a software update via the Dealer Web Portal

- 1. Read out the control unit software version using the PIWIS Tester
 - a. Select the "Porsche Vehicle Tracking System (PVTS)" control unit
 - b. Select the "Extended identifications" tab
 - c. Check the software version; it must be less than "0930"
- 2. Perform a software update
 - a. Ensure the PTVS CU has sufficient mobile (GSM) and satellite (GPS) reception
 - i. Note: the PVTS CU contains an embedded SIM card and Vodafone manages data connection for service to this CU. No plug-in SIM is required to perform this update.
 - ii. To perform the update on a vehicle that does not have a customer contract set up, activate the vehicle using the dealership demo account. Perform the update as directed below, then remove the vehicle from the demo account. Activating the vehicle via the demo account allows this update without starting the customer's free trial period of Porsche Car Connect





Bulletin #: 2114 Part ID: 9064

- b. Access the Porsche Partner Network (PPN) --> Online Systems --> Porsche Car Connect (Online Support)
- c. Select "Device repair" (Figure 2, -1-)
- d. Enter the VIN (Figure 2, -2-) and click "Search" (Figure 2, -3-). Vehicle information and settings are displayed.

Note: If the error message, "This device is not eligible to the repair process" is displayed, please verify the VIN entered is correct and retry the Search function several times. Also, try refreshing/reloading the webpage. If the same error message is received after several retries, then it may be necessary to replace the control unit.

e. After Vehicle information and settings are displayed, click the **Repair** button (Figure 2, **-4-**). Once the update is completed successfully, the message "Your vehicle configuration has been updated" will appear briefly.

Note: If the update is not successful after the third attempt, please contact the Porsche Car Connect support center to verify vehicle information and settings as well as PVTS status by VIN.

PORSCHE	Device Repair Request This section allows you to initiate the procedure for repairing a device.			
Porsche Car Connect - Online Support	-			
Velcome	Vehicle Identification I	Number (VIN) WP0ZZZ97LHU040163 Search		
Seneral information				
105	Vehicle model	склым 3		
	Contract status	ACTIVATED		
ontract information	Country of senirce	Germany		
	Remote	Subscribed 2018-05-22 - 2023-05-22		
echnical information and logs	Safety	Not subscribed -		
evice Replacement	VTS	Notsubscribed -		
levice Repair	Driver cards (Nb, IDs)	2 6735030 6735050		
Privacy Costina Palcy	Radio Keys (No, IDs)	7 6736031 6736032 6739033 6739034 6739035 6739035 6739035		
	Transport mode	OFF		
	Garage Mode	OFF		
	Disarmed mode	OFF		
	Geofence	OFF		
	Speed limit	91 KM/H		
	Crank Inhibition	UNLOCKED		
	Timer 1	0 2000-01-01T00:00:00		
	Timer 2	0 2000-01-01T00:00:00		
	Timer 3	0 2000-01-01T00:00:00		
	Timer 4	0 2000-01-01T00:00:00		
4	Timer 5	0 -		
4	Timer 6	0 -		

Figure 2

AfterSales



Bulletin #: 2114 Part ID: 9064 9

f. Check whether all information and settings are the same after the repair function is completed (Figure 3, -1-), then click the "**Generate Report**" button (Figure 3, -2-).

Porsche Car Connect - Online Support	This section allow	This section allows you to initiate the procedure for repairing a device.				
Velcome	Vehicle Identificat	tion Number (VIN)	WP0ZZZ97LHU040163	Search		
Seneral information			-			
AQs		Befor repair	~1~	After repair		
ontract information	Vehicle model	CAYMAN	Vehicle model	CAYMAN		
	Contract status	ACTIVATED	Contract status	ACTIVATED		
actinical information and logs	Country of service	Germany	Country of service	Germany		
Device Replacement	Remote	Subscribed 2018-05-22 2023-05-22	2+ Remote	Subscribed 2018-05-22 - 2023-05-22		
Device Repair	Safety	Not subscribed -	Safety	Not subscribed -		
	VTB	Not subscribed +	VTS.	Not subscribed -		
Privaty Cooties Policy	Driver cerds (Nh, IDs)	2 6735030 6735050	Driver cards (Nb. IDs)	2 6735030 6735050		
	Radie Keys (Nb. Ds)	7 6735031 6735032 6735033 6735034 6735035 6735036 6735036 6735037	Rado Keys (lib, IDs)	7 6736031 6736032 6736033 6736034 6736035 6736035 6736036 6735037		
	Transport node	OFF	Transport node	OFF		
	Gatage Node	OFF	Garage Node	OFF		
	Disarmed mode	OFF	Disarmed mode	OFF		
	Geolence	OFF	Geofence	OFF		
	Speed limit	56.0 K34/H	Speed limit	56.0 K341H		
	Crank Inhibition	UNLOCKED	Crank Inhibition	UNLOCKED		
	Timer 1	0 -	Tindr 1	0 -		
	Timer 2	0 -	Timer 2	0 -		
	Timer 3	0 -	Timer 3	0 -		
	Timer 4	0 -	Timer 4	0 -		
			Timer 5	0 -		
2	Timer 5	u -				
2	Timer 5 Timer 6	0 -	Timer 6	0 -		



Bulletin #: 2114 Part ID: 9064 9

g. Verify the Immobilizer is deactivated. The "**Crank inhibition**" value should show "**Unlocked**" after repair (Figure 4, **-1**-).

	In partnership with Vodafone Automotive	T U	elem pgra	atics Do de Rep	evice ort
VIN Number	WP0ZZZ	7LHU040163	Contract	Number 0100	089649
Report status	FAIL				
	before repair			after repai	r
Vehicle model	CAYMAN			CAYMAN	
Contract status	Activated			Activated	
Country of service:	Germany			Germany	
Remote Service	Subscribed	2018-05-22 - 20	23-05-22	Subscribed	2018-05-22 - 2023-05-22
Safety Service	Not Subscribed			Not Subscribed	
Security Service	Not Subscribed	-		Not Subscribed	-
Number of Driver cards	2, 6735030, 6	735050		0	
Number of Remote keys	7, 6735031, 6	735032, 6735033	6735034,	0	
Garage mode	6735035, 673 Off	5036, 6735037			
Transport mode	Off				
Disarmed mode	Off				
Geofence	Off			Off	
Speed limit	56.0 KM/H			Off	
Timer 1	0 -				
Timer 2	0-				
Timer 3	0 -				
Timer 4	0-				
Timer 5	0 -				
Timer 6	0-				
Crank inhibition	Locked			Unlocked	-
					-1
		Figure 4	1		

- 3. Read out the control unit software version using the PIWIS Tester
 - a. Select the "Porsche Vehicle Tracking System (PVTS)" control unit
 - b. Select the "Extended identifications" tab
 - c. Check the software version; it must be **"0930**".

Bulletin #: 2114 Part ID: 9064

Invoicing

Invoicing:

For documentation and warranty invoicing, enter the labor operation and PQIS coding specified below in the warranty claim:

APOS	Labor operation	I No.
90642510	Programming the control unit for the auxiliary alarm system	

PQIS coding:

Location (FES5)	90640	Control unit for the auxiliary alarm
Damage type (SA4)	1619	System does not start

Search Items

PVTS, Porsche Vehicle Tracking System, Dealer Web Portal, Porsche Car Connect, PCC, Vodafone, Connect, Immobilizer

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

