

Downstream Oxygen Sensor Error(s) – “Slow Response – Rich to Lean”

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Cayenne	2020	9YABB1, 9YBBB1	N/A	N/A

Revision History

Revision	Release Date	Changes
0	June 4, 2020	Original document
1	August 18, 2020	Update of Technical Background, Service Information and Warranty
2	June 30, 2021	Update of Technical Background, Service Information and Warranty

Condition

Downstream oxygen sensor errors P013B00 (005C35, Bank 1) and P013D00 (005C3B, Bank 2) - ‘Slow Response – Rich to Lean’ of the 2.9 liter bi-turbo V6 engine for the Cayenne S and Cayenne S Coupé occurring under the following operating conditions:

- Low engine speed (1200 – 1500 rpm)
- Calculated engine load at approximately one-third (25 – 35%)
- Engine temperature approaching or at operating temperature (50 – 100°C)
- Low vehicle mileage (0 – 500 miles)

Technical Background

An altered diagnostic sensitivity occurring under specific engine operating conditions, as described above, can cause the aforementioned faults to set the engine's malfunction indicator lamp (MIL).

Service Information

Please record an initial Vehicle Analysis Log (Before VAL), and delete this fault(s) from the DME. Perform Automatic Programming and Coding to the DME control with a tester that is at least of a software version **40.300.020** (or higher) to achieve the following DME target software configuration:

Porsche Part Number: 9Y0.907.551.K

Version: 0002

Warranty

As always, please document the case completely in PQIS.

For this repair, please code the "cause" as follows:

Cause location: 24700 "DME control unit"

Cause symptom: 4028 "Reacts to faults"

Use the following troubleshooting labor operation:

03350000 On board diagnostic (Main work) Fault memory read out

03350053 On board diagnostic (Composite) VAL

24702550 DME control unit program

Search Items

E3, oxygen (lambda) sensor, P013B00 (005C35, Bank 1), and P013D00 (005C3B, Bank 2) - 'Slow Response – Rich to Lean,' 2.9 liter bi-turbo V6, Cayenne S, Cayenne S Coupé

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.
