



SERVICE BULLETIN

Classification: FA19-002B	Reference: NTB19-105B	Date: June 30, 2021
------------------------------	--------------------------	------------------------

CLICKING/POPPING NOISE FROM FRONT AXLE AREA DURING TAKE OFF/ACCELERATION AND/OR DECELERATION

This bulletin has been amended. See AMENDMENT HISTORY on the last page.
Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2018-2021 LEAF (ZE1)

IF YOU CONFIRM

A clicking or popping noise is coming from the front axle area during take off/acceleration and/or deceleration.

ACTION

Before performing diagnostic procedures, torque the lug nuts for all four (4) wheels to 113 N•m (12kg-m, **83 ft-lbs**), in a diagonal pattern.

- If the clicking/popping noise is still present after torquing the lug nuts, refer to the ESM for further diagnostic information.




Figure 1

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Check Torque on Wheel Nuts (All)	(1)	PX92AA	ZE	32	0.2

- (1) Reference the electronic parts catalog and use the Wheel Road Nut (40224-*****) as the Primary Failed Part (PFP).

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 22, 2019	NTB19-105	Original bulletin published
October 15, 2020	NTB19-105A	APPLIED VEHICLES revised
June 30, 2021	NTB19-105B	APPLIED VEHICLES revised

