

Subject:**WASHER MOTOR LEAKS****Bulletin No.: 09-022/21****Last Issued : 07/12/2021****APPLICABLE MODEL(S)/VINS**


2016-2021 Mazda2 (Mexico spec) with VINS lower than JMZDJ*****304700 (produced before August 4, 2020)

2016-2021 CX-3 with VINS lower than JM1DK*****501594 (produced before August 19, 2020)


2019-2021 Mazda3 (Japan built) with vins lower than JM1BP*****307417 (produced before September 2, 2020)

DESCRIPTION

Some customers may complain that the frequency of replenishing the window washer liquid is higher than expected, or they may complain of leakage at around the washer motor (1).



Mazda2 and CX-3



Mazda3

This is caused by a crack that may occur at the joint section of the washer motor housing due to an inappropriate assembly process. To eliminate this concern, the design of the washer motor has been modified to not have a joint section.

Customers having this concern should have their vehicle repaired using the following repair procedure.

REPAIR PROCEDURE

1. Verify customer concern.
2. Replace the washer motor with a modified one according to the instructions on MGSS.

- Mazda2 (WASHER MOTOR REMOVAL/INSTALLATION)
- CX-3 (WASHER MOTOR REMOVAL/INSTALLATION)
- Mazda3 (WASHER MOTOR REMOVAL/INSTALLATION)

3. Verify repair.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical--including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.

PARTS INFORMATION

Parts Number	Description	Qty.	Notes
BDTT-67-482	Pump, Washer	1	Mazda3 4-door SD
DGH9-67-482	Pump, Washer	1	Mazda2, Mazda3 5-door HB, CX-3
BJT6-67-491	Grommet, Washer Tank	1	[R] Mazda2

[R]: Replacement part

WARRANTY INFORMATION**NOTE:**

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	A
Symptom Code	77
Damage Code	9E
Part Number Main Cause	BDTT-67-482 or DGH9-67-482
Quantity	1
Operation Number / Labor Hours:	XXT20DRX / 0.2 Hrs (Mazda3) XXT20FRX / 0.5 Hrs (Mazda2) XXT20ARX / 0.6 Hrs. (CX-3)

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/ equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.