

## Technical Information

88/21 ENU 2796

Service

2

## Complaint – Vehicle Plug does not Lock and the Charging Process Cannot be Started: Observe Specified Procedure (88/21)

Model Line: Taycan (Y1A/Y1B) Model Year: As of 2020 Concerns: Locking mechanism for vehicle charge port Information: The vehicle plug does not interlock in the vehicle charge port. The release button on the vehicle lights up red and the charging process cannot be started. The reason for this is charge connector that is not correctly positioned. As a result, the charging plug cannot be locked and the charging process cannot be started. The use of heavy charging cables/charging plugs can cause this problem. One of the following entries is stored in the fault memory of the high-voltage charger (OBC) control unit: **P33E800** – AC charging socket, charging plug lock, mechanical fault (200302) **P33E900** – Charging socket combo, charging plug lock, mechanical fault (200312) Action required: The vehicle plug must be inserted fully and straight into the vehicle charge connection so that the locking mechanism can engage. If necessary, the procedure must be repeated and the vehicle plug may have to be held in position by hand. If the charging plug tilts down even slightly, this can be enough to prevent the actuator from locking the charging plug  $\Rightarrow$  *Incorrect position of vehicle plug.* 



Correct position of vehicle plug



Incorrect position of vehicle plug

| Technical Information | Service        | $\mathbf{O}$ |
|-----------------------|----------------|--------------|
|                       | 88/21 ENU 2796 | <u> </u>     |

Further information can be found in section 'Plugging in vehicle plug on the vehicle charge connection and starting charging process' in the Driver's Manual.  $\Rightarrow$  Betriebsanleitung



Replacing the vehicle plug, wiring train or vehicle charging socket will not correct the problem.

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know how to do the job properly and safely. Part numbers listed in these builtetins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2021 Porsche Cars North America, Inc.

**AfterSales**