

Technical Information

77/21 ENU

Service

2870

Complaints Immediately or Shortly After Changing or Removing and Installing Spark Plugs: **Observe Specified Procedure (77/21)**

Vehicle Type: 911 Carrera (991)/911 Carrera S (991)/911 Carrera GTS (991) 911 Carrera (992)/911 Carrera S (992) 718 Boxster (982)/718 Boxster T (982)/718 Cayman (982)/718 Cayman T (982)

- Model Year: As of 2017
- Equipment: 3.0-liter petrol engines (911) 2.0-liter petrol engines (718)
- Concerns: Spark plugs

Information: The customer complains about one or more of the following issues immediately or shortly after removing and installing or changing spark plugs:

- Check Engine warning light comes on •
- Vehicle jerking
- Rough-running engine

This may be caused by incorrect installing of the spark plugs using an incorrect or worn tool. As a result, the ceramic body will be damaged by excessive transverse forces when tightening it in the slightly angled spark-plug recess.

The electrodes can also touch and bend when inserting them.



Damage to spark plugs

- 1 Electrode bent
- 2 Insulator tip broken
- 3 Insulator broken
- 4 Housing/connection damaged

NOTICE

Damaged, worn or incorrect tool

- Risk of damage to spark plugs
- ⇒ Only use the prescribed tool and install spark plugs according to instructions in the relevant Workshop Manual.

Action required: Use the prescribed tool when removing and installing spark plugs:

- Double hexagon socket for spark plugs, a/f 14
- Extension, 3/8"

Install spark plugs according to instructions in the relevant Workshop Manual. \Rightarrow Workshop Manual '287020 Removing and installing spark plugs'

AfterSales

	Technical Information	Service		\mathbf{O}
		77/21 ENU 2	2870	2

i Information

Damaged spark plugs as a result of incorrect installing must not be invoiced using the new vehicle warranty or Porsche Approved Warranty (PAW) and can be re-debited as required after checking.

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

 $\ensuremath{^\odot}$ 2021 Porsche Cars North America, Inc.

AfterSales