

Service Bulletin

TECHNICAL

Subject: Rough Idle with Misfire Counts on Random Cylinders, Malfunction Indicator Lamp (MIL) Illuminated

This bulletin cancels PIP5715B. Please discard PIP5715B.

Brand:	Model:	Model Year:		VIN:		Engine	Transmission:
		from	to	from	to	Engine:	fransinission.
Chevrolet	Corvette	2020	2021	—	—	6.2L (LT2)	—

Involved Region or Country	North America, Uzbekistan, Middle East, Paraguay, Japan, GM Korea Company, China
Condition	Some customers may comment on a rough idle condition and/or the MIL may be illuminated. – This is typically noticed on vehicles at low mileage (like PDI) or vehicles that may have
	been started then shut off multiple times such as marshaling. Upon inspection, the technician may also notice random misfires on multiple cylinders.
	This condition may be caused by marshalling the vehicle around and/or short runtime soot, fouling the spark plugs.
	- The LT2 engine in the Corvette is a very capable and powerful powerplant, the jewel within the all-new mid-engine design. Producing 495 horsepower at 6450 rpm and 470 lb-ft. of torque at 5150 rpm with performance exhaust, this engine produces more naturally aspirated HP per liter of displacement than any Corvette engine in history.
Cause	– To fully enable this extreme level of engine performance, the LT2 was designed to be driven. Like many performance car engines, the LT2 is sensitive to short run-time starts where the spark plug does not have time to heat up. In these cases, carbon from the combustion process can accumulate on the spark plug and result in rough idle or misfire. The best way to keep your spark plugs clean is to safely exercise your Corvette on your favorite roads or track. Both running your engine and spirited driving can clean plugs that may be partially impacted.
	 Whenever possible, try to run the engine until it has reached a coolant temperature greater than 51°C (125°F), and/or at least 3 minutes of engine run time, instead of frequent, short duration start/stop cycles.
	If you encounter a vehicle that is in for this condition and meets the criteria above, follow the Correction steps.
	If you encounter this condition, utilizing the GDS2, command the engine speed up to 2000 rpm for 10 minutes and re-evaluate the concern.
	 If the misfires stop counting, return the vehicle to the customer.
Correction	 If the concern is not completely gone, the vehicle may need to be driven to finish cleaning the spark plugs.
	 If the above steps do not resolve the concern, it will be necessary to replace all 8 spark plugs.

Parts Information

Causal Part	Description	Part Number	Qty
Х	SPARK PLUG, GAS ENG IGN	12622442	8

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time	
4020870	Gas Engine Ignition Spark Plug Replacement - Left Side		
4020871	Gas Engine Ignition Spark Plug Replacement - Left Side - Multiple	Use Published	
4020880	Gas Engine Ignition Spark Plug Replacement - Right Side	Labor Operation Time	
4020881	Gas Engine Ignition Spark Plug Replacement - Right Side - Multiple		

Version	1
Modified	Released June 29, 2021

GM bulletins are intended for use by professional technicians, NOT a "<u>do-it-yourselfer</u>". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION