

Service Bulletin

Bulletin No.: 21-NA-134

Date: June, 2021

TECHNICAL

Subject: Squeak Noise from Exhaust System


Brand:	Model:	Model Year:		VIN:		Engino	Transmission:
		from	to	from	to	Engine:	mansinission.
Chevrolet	Camaro	2016	2021	_	_	3.6L (LGX)	_

Involved Region or Country	North America, Europe, Russia, Middle East, Israel, Argentina, Brazil, Bolivia, Chile, Colombia, Ecuador, Paraguay, Peru, Uruguay, Japan, GM Korea Company, China, Taiwan, Philippines		
Additional Options (RPOs)	EXHAUST SYSTEM-DUAL (RPO N10)		
Condition	Some customers may comment that a squeak noise can be heard from the exhaust system while driving over bumps.		
Cause	This condition may be caused by a mis-aligned intermediate exhaust pipe flange rubbing the cup on the flex joint.		
Correction	Inspect the exhaust system and re-align the flange. ⇒ If you encounter a vehicle with the above concern, refer to the Service Procedure below.		

Service Procedure



585/883





5854885

- 2. Wedge a suitable tool between the flex coupling cup and the flange to gain clearance between the flange and the flex coupler cup at approximately 1/8 inch.
 - ⇒ Attempt to re-position the flange. The graphic is an example of the proper clearance.
- Re-assemble the intermediate pipe to the exhaust system and test drive the vehicle to ensure the noise is no longer present.

Parts Information

No parts are required for this repair.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
4050272	Exhaust System Alignment	Use Published Labor Operation Time

Version	1
Modified	Released June 10, 2021